KOLAR Document ID: 1775415

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

Kansas Corporation Commission Oil & Gas Conservation Division

WELL PLUGGING RECORD K.A.R. 82-3-117

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

OPERATOR: License #:				API No. 15			
Name:				Spot Description:			
Address 1:				Sec Twp S. R East West			
Address 2:				Feet from North / South Line of Section Feet from East / West Line of Section			
City:							
Contact Person:				Footages Calculated from Nearest Outside Section Corner:			
Phone: ()				☐ NE ☐ NW ☐ SE ☐ SW			
Type of Well: (Check one) Oil Well Gas Well OG D&A Cathodic Water Supply Well Other: SWD Permit #:				County: Well #:			
ENHR Permit #: Gas Storage Permit #:				Date Well Completed:			
Is ACO-1 filed? Yes No If not, is well log attached? Yes No				The plugging proposal was approved on: (Date)			
Producing Formation(s): List All (If needed attach another sheet)				by:(KCC District Agent's Name) Plugging Commenced:			
Depth to Top: Bottom: T.D							
Depth to Top: Bottom: T.D				Plugging Completed:			
Depth to Top: Bottom: T.D					Completed.		
Show depth and thickness of a	all water, oil and gas forma	ations.					
Oil, Gas or Water Records			Casing Reco	sing Record (Surface, Conductor & Production)			
Formation	Content	Casing	Size		Setting Depth	Pulled Out	
cement or other plugs were us		-				ds used in introducing it into the hole. If	
Plugging Contractor License #: Nan							
Address 1: Address							
City:			Sta	ate:		Zip:+	
Phone: ()							
Name of Party Responsible for Plugging Fees:							
State of	County, _		, s	SS.			
		Г	_	nployee of Operator or	Operator on above-described well,		
(Print Name)				=[]	inproyee or Operator or	Operator on above-described well,	

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

Gilbert HJ 2 15-189-20345 Well Plugging Record

4/17/2024: Move in rig. RU tried to unseat the pump. Pump is stuck. Tried to back off rods broken at 8 rods. LD rods. Try to pull tbp. Tbp was stuck. Change equipment over to rods. Clean up thread on rods to try to get deeper break but @ 9 rods. Screw rods back together and work rods. same break at 9 rods. Shut in well. The crew drove home.

4/18/2024: Held TGSM. Open up. Ran rods back in hole. Work pump didn't make no movement. Try to back off. Back off was 9 rods. Parted rods. Lad 41 rods - total 1025. Kansas wants to get 1750 out of hole. Shut in well. The crew drove home. Get dies for fishing tools in morning.

4/19/2024: Held TGSM. Open up well. Pick up baby red and 42-3/4 rods latch on rods. Work rods. Parted rods came out hole w/ 6ft with back in hole. Work rods. Parted rods came out of hole with 21 rods total 63 1575 Kansas wants to get 1750' out of hole. Shut in well. Crew drove home.

4/21/2024: Adrian Hernandez drove to Kansas from Odessa

4/22/2024: Held TGSM. Open well. RIH w/ 43 3/4 rods. Pick up 20 rods. Latch on to rods. Work rods. Stund back rods. LD 5 ft rods. Try to run back in hole but high winds. Had to shut down. Shut in well. Crew drove home.

4/23/2024: Held TGSM. Open up well. RIH w/ 13 triple rods. Had to shut down to change out compressor on rig. Finish RIH. Latch on fish. Work rods came out of hole. Only had 6 ft went back in hole 2 more times. got enough rods out to cutt tbp @ 1750'. LD rods. shut in well. crew drove home.

4/24/2024: Held TGSM. Open up well. LD 71-3/4" rods. RU wireline. RIH w/ 2-3/8" junk basket to 1755'. Change out tools. RIH w/ free point. tbp was free @ 1755'. Change out tools. RIH w/ wireline. Cut tbp @ 1755'. Stund back tbp. LD 10 ft piece of tbp. RIH w/tbp. spot 75 sks @ 1755'. stund back 15 stands. Shut in well. crew drove home

4/25/2024: Held TGSM. Open up well. RU wireline. RIH w/ BP tag plug @ 1282'. Set bp @ 660'. Pick up jts. Test BP and csg to 500 psi. RU wireline. Perforated at 640'. RIH w/ tbp to 600'. circulate well through perf squeeze. 300 sks to surfaces. LD tbp .watch cement top of 5.5 w/ 10sks. cement wash up. Wash up cement equipment and rig down. crew drove home