Form CP-4

STATE OF KANSAS
STATE CORPORATION COMMISSION
Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission
212 No. Market

WEL	L PI	JUGGING	RECO	ORD
77 444	Jan J. A.			JIU

212 No. Market Wichita, Kansas	<u> </u>	··············					
NORTH	Location as "N	E/CNW%SW%"	or footage fro	om lines	SW NE NE		
	Lease Owner_	kan darpusar mendirah mendirikan sembilik dimentelah dimentelah sembilik (dimension sebesah sembilik dimension	1 .	U. Miller			 1
	Lease Name		Wic.	hita Vano	3.0	Well No	164
	8						
	1	Vell (completed pleted	=				_19
	1	plugging filed_					
		plugging appro-					_19
	3	nenced	1/17	~~ ~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~			_19
		leted		<u>/67</u>			_19
	Reason for abar	ndonment of we	l or producin	g formation	deplete	d.	
	TC 1	11 . 1 . 1	7 7	-			
		well is abandon					_19
Locate well correctly on above Section Plat		n obtained from			or its agents be	efore plugging	was co
ne of Conservation Agent who su	pervised plugging of thi	is well	· · · · · · · · · · · · · · · · · · ·	Massey	editerritette et en et en		
ducing formation	I	Depth to top	Botton	n	Total Depth o	of Well 3775	5 t F
w depth and thickness of all wate							
DIL. GAS OR WATER RECOR						@16716 DE	
OIL, GAS OR WATER RECOR	was					CASING RE	CORD
FORMATION	CONTENT	FROM	то	SIZE	PUT IN	PULLED	OUT
				8 5/8	233	none	
		ļ	ļ	5 1/2	3768	28181	
		ļ	 	<u> </u>			
							
			 				
			<u> </u>				
Moved string of in unit, raised Rigged up on 5½ 40 gallons of d. 1545, had Globe 3745, dumped 5	tubing, tried mast, checked had 9" ténsion iesel fuel, wor e pump 172 barr sacks of cemen	to move put bottom, gon. Tried ked BS witels of salt with 3"	mping un ot down to push h bailer t water, dump bai	it, was fr to 1124', BS out w/ . Checked checked b ler. Shot	ozen down. cleaned or bailer. I hole, got ottom. Ra pipe at 2	. Moved ut cellar. Dumped t down to an sand to 2917;	fee
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints	tubing, tried mast, checked ", had 9" ténsiciesel fuel, wor e pump 172 barr sacks of cemen lled collar off " again. Worke pulled 60 joint s of 5½", pipe	to move put bottom, gon. Tried ked BS wit els of salt with 3" landing id pipe to s of 5½", was breaki	mping un ot down to push h bailer t water, dump bai oint. H 30" tans had troung hard.	it, was fr to 1124*, BS out w/ Checked checked b ler. Shot ad welder ion. Shot ble with s Busted c	ozen down cleaned or bailer. I hole, got ottom. Rapipe at 2 strap on opipe at 2 lips. Piphain tong	. Moved ut cellar. Dumped to down to an sand to 2917', collar. 2813', wor pe was much. Loaded	fee
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile	tubing, tried mast, checked ", had 9" ténsiciesel fuel, wor e pump 172 barr sacks of cemen lled collar off " again. Worke pulled 60 joint s of 5½", pipe ed hole to 248	to move put bottom, gon. Tried ked BS witels of salt with 3" landing id pipe to s of 5½", was breakin, set 10'	mping un ot down to push h bailer t water, dump bai oint. H 30" tans had troung hard.	it, was fr to 1124*, BS out w/ Checked checked b ler. Shot ad welder ion. Shot ble with s Busted c	ozen down cleaned or bailer. I hole, got ottom. Ra pipe at 2 strap on opipe at 2 lips. Piphain tong	. Moved ut cellar. Dumped to down to an sand to 2917', collar. 2813', wor pe was much. Loaded	fee
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints	tubing, tried mast, checked ", had 9" ténsiciesel fuel, wor e pump 172 barr sacks of cemen lled collar off " again. Worke pulled 60 joint s of 5½", pipe ed hole to 248	to move put bottom, gon. Tried ked BS witels of salt with 3" landing id pipe to s of 5½", was breakin, set 10'	mping un ot down to push h bailer t water, dump bai oint. H 30" tans had troung hard.	it, was fr to 1124*, BS out w/ Checked checked b ler. Shot ad welder ion. Shot ble with s Busted c	ozen down cleaned or bailer. I hole, got ottom. Ra pipe at 2 strap on opipe at 2 lips. Piphain tong	. Moved ut cellar. Dumped to down to an sand to 2917', collar. 2813', wor pe was much. Loaded	fee
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile	tubing, tried mast, checked ", had 9" ténsiciesel fuel, wor e pump 172 barr sacks of cemen lled collar off " again. Worke pulled 60 joint s of 5½", pipe ed hole to 248	to move put bottom, gon. Tried ked BS witels of salt with 3" landing id pipe to s of 5½", was breakin, set 10'	mping un ot down to push h bailer t water, dump bai oint. H 30" tans had troung hard.	it, was fr to 1124*, BS out w/ Checked checked b ler. Shot ad welder ion. Shot ble with s Busted c	ozen down cleaned or bailer. I hole, got ottom. Ra pipe at 2 strap on opipe at 2 lips. Piphain tong	. Moved ut cellar. Dumped to down to an sand to 2917', collar. 2813', wor pe was much. Loaded	fee
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile	tubing, tried mast, checked ", had 9" ténsiciesel fuel, wor e pump 172 barr sacks of cemen lled collar off " again. Worke pulled 60 joint s of 5½", pipe ed hole to 248	to move put bottom, gon. Tried ked BS witels of salt with 3" landing id pipe to s of 5½", was breakin, set 10'	mping un ot down to push h bailer t water, dump bai oint. H 30" tans had troung hard.	it, was fr to 1124*, BS out w/ Checked checked b ler. Shot ad welder ion. Shot ble with s Busted c	ozen down cleaned or bailer. I hole, got ottom. Ra pipe at 2 strap on opipe at 2 lips. Piphain tong	. Moved ut cellar. Dumped to down to an sand to 2917', collar. 2813', wor pe was much. Loaded	fee
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile	tubing, tried mast, checked had 9" ténsiciesel fuel, wore pump 172 barr sacks of cemen lled collar off again. Worke pulled 60 joints of 5½", pipe ed hole to 248!	to move put bottom, gon. Tried ked BS witels of salt with 3" landing id pipe to s of 5½", was breakin, set 10'	mping un ot down to push h bailer t water, dump bai oint. H 30" tans had troung hard.	it, was fr to 1124*, BS out w/ Checked checked b ler. Shot ad welder ion. Shot ble with s Busted c	ozen down cleaned or bailer. I hole, got ottom. Ra pipe at 2 strap on opipe at 2 lips. Piphain tong	. Moved ut cellar. Dumped to down to an sand to 2917', collar. 2813', wor pe was much. Loaded	fee
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile ready mix. Rack	tubing, tried mast, checked had 9" ténsiciesel fuel, wore pump 172 barr sacks of cemen lled collar off again. Worke pulled 60 joints of 5½", pipe ed hole to 248!	to move put bottom, gon. Tried ked BS witels of salt with 3" landing id pipe to s of 5½", was breakin, set 10'	mping un ot down to push h bailer t water, dump bai oint. H 30" tans had troung hard.	it, was fr to 1124*, BS out w/ Checked checked b ler. Shot ad welder ion. Shot ble with s Busted c	ozen down cleaned or bailer. I hole, got ottom. Ra pipe at 2 strap on opipe at 2 lips. Piphain tong	. Moved ut cellar. Dumped to down to an sand to 2917', collar. 2813', wor pe was much. Loaded	fee
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile ready mix. Rack	tubing, tried mast, checked had 9" ténsiciesel fuel, wore pump 172 barr sacks of cemen lled collar off again. Worke pulled 60 joints of 5½", pipe ed hole to 248!	to move put bottom, gon. Tried ked BS witels of salt with 3" landing id pipe to s of 5½", was breakin, set 10'	mping un ot down to push h bailer t water, dump bai oint. H 30" tans had troung hard.	it, was fr to 1124*, BS out w/ Checked checked b ler. Shot ad welder ion. Shot ble with s Busted c	ozen down cleaned or bailer. I hole, got ottom. Ra pipe at 2 strap on opipe at 2 lips. Piphain tong	Moved ut cellar. Dumped t down to an sand to 2917', collar. 2813', wor pe was muc. Loaded ards of	rked ddy.
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile ready mix. Rack	tubing, tried mast, checked had 9" ténsiciesel fuel, wore pump 172 barr sacks of cemen lled collar off again. Worke pulled 60 joint s of 5½", pipe ed hole to 248 ked unit, tall	to move put bottom, gon. Tried ked BS witels of salt with 3" landing id pipe to s of 5½", was breaki, set 10' ied pipe.	mping un ot down to push h bailer t water, dump bai oint. H 30" tans had trou ng hard. rock bri	it, was fr to 1124*, BS out w/ Checked b ler. Shot ad welder ion. Shot ble with s Busted c dge and du	ozen down cleaned or bailer. I hole, got ottom. Ra pipe at 2 strap on opipe at 2 lips. Piphain tong	. Moved ut cellar. Dumped to down to an sand to 2917', collar. 2813', wor pe was much. Loaded	rked ddy.
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile ready mix. Rack	tubing, tried mast, checked had 9" ténsiciesel fuel, wore pump 172 barr sacks of cemen lled collar off again. Worke pulled 60 joint s of 5½", pipe ed hole to 248 ked unit, tall	to move put bottom, gon. Tried ked BS witels of salt with 3" landing id pipe to s of 5½", was breaki, set 10' ied pipe.	mping un ot down to push h bailer t water, dump bai oint. H 30" tâns had trou ng hard. rock bri	it, was fr to 1124*, BS out w/ Checked b ler. Shot ad welder ion. Shot ble with s Busted c dge and du	ozen down cleaned or bailer. I hole, got ottom. Rapipe at 2 strap on opipe at 2 lips. Piphain tong mped 4½ ya	Moved ut cellar. Dumped t down to an sand to 2917', collar. 2813', wor pe was muc. Loaded ards of	rked ddy.
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile ready mix. Rack	tubing, tried mast, checked had 9" ténsiciesel fuel, wore pump 172 barr sacks of cemen lled collar off again. Worke pulled 60 joint s of 5½", pipe ed hole to 248 ked unit, tall	to move put bottom, gon. Tried ked BS witels of salt with 3" landing id pipe to s of 5½", was breaki, set 10' ied pipe.	mping un ot down to push h bailer t water, dump bai oint. H 30" t&ns had trou ng hard. rock bri	it, was fr to 1124*, BS out w/ Checked b ler. Shot ad welder ion. Shot ble with s Busted c dge and du	ozen down cleaned or bailer. I hole, got ottom. Rapipe at 2 strap on opipe at 2 lips. Piphain tong mped 4½ ya	Moved ut cellar. Dumped t down to an sand to 2917', collar. 2813', wor pe was muc. Loaded ards of	rked ddy.
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile ready mix. Rack	tubing, tried mast, checked had 9" ténsiciesel fuel, wore pump 172 barr sacks of cemen lled collar off again. Worke pulled 60 joint s of 5½", pipe ed hole to 248 ked unit, tall	to move put bottom, gon. Tried ked BS witels of salt with 3" landing id pipe to s of 5½", was breaki, set 10' ied pipe.	mping un ot down to push h bailer t water, dump bai oint. H 30" t&ns had trou ng hard. rock bri	it, was fr to 1124*, BS out w/ Checked b ler. Shot ad welder ion. Shot ble with s Busted c dge and du	ozen down cleaned or bailer. I hole, got ottom. Rapipe at 2 strap on opipe at 2 lips. Piphain tong mped 4½ ya	Moved ut cellar. Dumped t down to an sand to 2917', collar. 2813', wor pe was muc. Loaded ards of	rked ddy.
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile ready mix. Rack	tubing, tried mast, checked had 9" ténsiciesel fuel, wor e pump 172 barr sacks of cemen lled collar off again. Worke pulled 60 joints of 5½", pipe ed hole to 248 ked unit, tall	to move put bottom, gon. Tried ked BS witels of salt with 3" landing id pipe to s of 5½", was breaki, set 10° ied pipe. description is necessification.	mping un ot down to push h bailer t water, dump bai oint. H 30" t&ns had trou ng hard. rock bri	it, was fr to 1124*, BS out w/ Checked b ler. Shot ad welder ion. Shot ble with s Busted c dge and du	ozen down cleaned or bailer. I hole, got ottom. Rapipe at 2 strap on opipe at 2 lips. Piphain tong mped 4½ ya	Moved ut cellar. Dumped t down to an sand to 2917', collar. 2813', wor pe was muc. Loaded ards of	rked ddy.
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile ready mix. Rack	tubing, tried mast, checked ", had 9" ténsiciesel fuel, wor e pump 172 barr sacks of cemen lled collar off " again. Worke pulled 60 joint s of 5½", pipe ed hole to 248' ked unit, tall (If additional KNIC	to move put bottom, gon. Tried ked BS with els of salt with 3" landing id pipe to sof 5½", was breakid, set 10° ied pipe. description is neces GHT CASING HASE, KANS	mping un ot down to push h bailer t water, dump bai oint. H 30" tâns had trou ng hard. rock bri	it, was fr to 1124*, BS out w/ Checked b ler. Shot ad welder ion. Shot ble with s Busted c dge and du	ozen down cleaned or bailer. I hole, got ottom. Rapipe at 2 strap on opipe at 2 lips. Piphain tong. mped 42 yard.	Moved ut cellar. Dumped to down to an sand to 2917', collar. 2813', wor pe was much Loaded ards of	rked ddy.
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile ready mix. Rack	tubing, tried mast, checked hast, checked had 9" ténsiciesel fuel, wore pump 172 barr sacks of cemen lled collar off again. Worke pulled 60 joints of 5½", pipe ed hole to 248 ked unit, tall	to move put bottom, gon. Tried ked BS witels of salt with 3" landing id pipe to s of 5½", was breaki, set 10' ied pipe. description is necessification.	mping un ot down to push h bailer t water, dump bai oint. H 30" tâns had trou ng hard. rock bri	it, was fr to 1124*, BS out w/ Checked bler. Shot ad welder ion. Shot ble with s Busted c dge and du	ozen down cleaned or bailer. I hole, got ottom. Rapipe at 2 strap on opipe at 2 lips. Pil hain tong, mped 42 ya	Moved ut cellar. Dumped t down to an sand to 2917', collar. 2813', wor pe was much Loaded ards of	ked ddy.
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile ready mix. Rack	tubing, tried mast, checked is, had 9" ténsiciesel fuel, wor e pump 172 barr sacks of cemen 11ed collar off again. Worke pulled 60 joints of 5½", pipe ed hole to 248 ked unit, tall	to move put bottom, gon. Tried ked BS witels of salt with 3" landing id pipe to sof 5½", was breaki, set 10' ied pipe. description is necessified to the control of the co	mping un ot down to push h bailer t water, dump bai oint. H 30" tâns had trou ng hard. rock bri ssary, use BACK PULLING AS RIGE	it, was fr to 1124*, BS out w/ Checked bler. Shot ad welder ion. Shot ble with s Busted c dge and du company company	ozen down cleaned or bailer. I hole, got ottom. Rapipe at 2 strap on opipe at 2 lips. Pil hain tong, mped 42 ya	Moved ut cellar. Dumped t down to an sand to 2917', collar. 2813', wor pe was much Loaded ards of	ked ddy.
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile ready mix. Rack	tubing, tried mast, checked ", had 9" ténsiciesel fuel, wore pump 172 barr sacks of cemen 1led collar off again. Worke pulled 60 joints of 5½", pipe ed hole to 248 ked unit, tall	to move put bottom, gon. Tried ked BS wit els of salt with 3" landing id pipe to sof 5½", was breaki, set 10' ied pipe. description is neces GHT CASING HASE, KANS	mping un ot down to push h bailer t water, dump bai oint. H 30" tâns had trou ng hard. rock bri ssary, use BACK PULLING AS RIGE	it, was fr to 1124*, BS out w/ Checked bler. Shot ad welder ion. Shot ble with s Busted c dge and du company company	ozen down cleaned or bailer. I hole, got ottom. Rapipe at 2 strap on opipe at 2 lips. Pil hain tong, mped 42 ya	Moved ut cellar. Dumped t down to an sand to 2917', collar. 2813', wor pe was much Loaded ards of	ked ddy.
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile ready mix. Rack	tubing, tried mast, checked ", had 9" ténsiciesel fuel, wore pump 172 barr sacks of cemen 1led collar off again. Worke pulled 60 joints of 5½", pipe ed hole to 248 ked unit, tall	to move put bottom, gon. Tried ked BS witels of salt with 3" landing id pipe to sof 5½", was breaki, set 10' ied pipe. description is necessified to the control of the co	mping un ot down to push h bailer t water, dump bai oint. H 30" tâns had trou ng hard. rock bri ssary, use BACK PULLING AS RIGE	it, was fr to 1124*, BS out w/ Checked bler. Shot ad welder ion. Shot ble with s Busted c dge and du company company	ozen down cleaned or bailer. I hole, got ottom. Rapipe at 2 strap on opipe at 2 lips. Pil hain tong, mped 42 ya	Moved ut cellar. Dumped t down to an sand to 2917', collar. 2813', wor pe was much Loaded ards of	ked ddy.
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile ready mix. Rack	tubing, tried mast, checked ", had 9" ténsiciesel fuel, wore pump 172 barr sacks of cemen 1led collar off again. Worke pulled 60 joints of 5½", pipe ed hole to 248 ked unit, tall	to move put bottom, gon. Tried ked BS wit els of salt with 3" landing id pipe to sof 5½", was breaki, set 10' ied pipe. description is neces GHT CASING HASE, KANS	mping un ot down to push h bailer t water, dump bai oint. H 30" t&ns had trou ng hard. rock bri ssary, use BACK PULLING AS RIGE employee of facts, stateme	it, was fr to 1124*, BS out w/ Checked bler. Shot ad welder ion. Shot ble with s Busted c dge and du company company	ozen down cleaned or bailer. I hole, got ottom. Rapipe at 2 strap on opipe at 2 lips. Pil hain tong, mped 42 ya	Moved ut cellar. Dumped t down to an sand to 2917', collar. 2813', wor pe was much Loaded ards of	ked ddy.
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pull Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile ready mix. Rack PLUGGING COMPLET TE OF KANSAS NO: , being first duly sworn on oath, re-described well as filed and the	tubing, tried mast, checked hast, checked hast, checked has had 9" tension iesel fuel, wor e pump 172 barr sacks of cemen lled collar off again. Worke pulled 60 joint s of 5½", pipe ed hole to 248' ked unit, tall	to move put bottom, gon. Tried ked BS witels of salt with 3" landing id pipe to sof 5½", was breaki, set 10' ied pipe. "description is necessified by the set 10' ied pipe." "description is necessified by the set 10' ied pipe."	mping un ot down to push h bailer t water, dump bai oint. H 30" t&ns had trou ng hard. rock bri ssary, use BACK PULLING AS RIGE employee of facts, stateme	it, was fr to 1124*, BS out w/ Checked bler. Shot ad welder ion. Shot ble with s Busted c dge and du control of this sheet) COMPANY Dwner) or (ownents, and matter	ozen down cleaned or bailer. I hole, got ottom. Rapipe at 2 strap on opipe at 2 lips. Pil hain tong, mped 42 ya	Moved ut cellar. Dumped t down to an sand to 2917', collar. 2813', wor pe was much Loaded ards of	ked ddy.
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pul Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile ready mix. Rack	tubing, tried mast, checked hast, checked hast, checked has had 9" tension iesel fuel, wor e pump 172 barr sacks of cemen lled collar off again. Worke pulled 60 joint s of 5½", pipe ed hole to 248' ked unit, tall	to move put bottom, gon. Tried ked BS wit els of salt with 3" landing id pipe to sof 5½", was breaki, set 10' ied pipe. description is neces GHT CASING HASE, KANS	mping un ot down to push h bailer t water, dump bai oint. H 30" t&ns had trou ng hard. rock bri ssary, use BACK PULLING AS RIGE employee of facts, stateme	it, was fr to 1124*, BS out w/ Checked bler. Shot ad welder ion. Shot ble with s Busted c dge and du control of this sheet) COMPANY Dwner) or (ownents, and matter	ozen down cleaned or bailer. I hole, got ottom. Rapipe at 2 strap on opipe at 2 lips. Pil hain tong, mped 42 years. Ss. her or operator) as herein contains.	Moved ut cellar. Dumped t down to an sand to 2917', collar. 2813', wor pe was much Loaded ards of	ked ddy.
Moved string of in unit, raised Rigged up on 5½ 40 gallons of di 1545, had Globe 3745, dumped 5 worked pipe, pull Rigged up on 5½ pipe loose and pulled 28 joints junk rack, baile ready mix. Rack PLUGGING COMPLET	tubing, tried mast, checked hast, checked hast, checked has had 9" tension iesel fuel, wor e pump 172 barr sacks of cemen lled collar off again. Worke pulled 60 joint s of 5½", pipe ed hole to 248' ked unit, tall	to move put bottom, gon. Tried ked BS witels of salt with 3" landing id pipe to sof 5½", was breaki, set 10' ied pipe. "description is necessified by the set 10' ied pipe." "description is necessified by the set 10' ied pipe."	mping un ot down to push h bailer t water, dump bai oint. H 30" t&ns had trou ng hard. rock bri ssary, use BACK PULLING AS RIGE employee of facts, stateme	it, was fr to 1124*, BS out w/ Checked bler. Shot ad welder ion. Shot ble with s Busted c dge and du control of this sheet) COMPANY Dwner) or (ownents, and matter	ozen down cleaned or bailer. I hole, got ottom. Rapipe at 2 strap on opipe at 2 lips. Pil hain tong, mped 42 years. Ss. her or operator) as herein contains.	Moved ut cellar. Dumped t down to an sand to 2917', collar. 2813', wor pe was much Loaded ards of	ked ddy.

OPERATOR I. O. Miller Allphin # :	工
-----------------------------------	---

				A	DDI	RESS	619		ow)	9145.	-115	.eh11	a, i	en			
	4	i de l	 Jer es															
	polecino) Second	i paranja	-	-	000	NTY		Box	يار	g sec.3	2	TW	r_98		., 1	IGE	194
				\bot							I.							
162				168	Ш	Off	ICE AD	DRE	S S	6	19_B	COL	Bla	لها	d.c	100	Lta,	-Kns.
					Ц	Den	LING S	TAR	TED.	1	1/9 11	6	DRILLIN	IG FINI	SHE	QL)	L/21	, 1991
		1		-	-	DAT	E OF F	IRST	PRO	200	CTION .		***	_COM	LETT	ED		
	_		4			WEI	LLOCA	TEO		1	VIII		CY	_ Y4	-1000000	٦,	North a	f South
	_	_	\sqcup	_ _	Н		and			-				West Li	ne c	f C	warter	Section
160	_	L	\sqcup	184	-						ea level)							
	_			-							(Oil, ga							
La	e a le	m.c	ii ees	rectig		CH/			-		-							
	ACTRICATE OF	N TOP ONLY					OIL O	R G	AS S	AN	DS OR Z	CONE	<u> </u>			-		
			Non	30			From	1	•				Nome			+	from	Te
1								<u> </u>			4					+		
2				-				<u> </u>			<u> </u>					+		
3	and the same			Cluster water				_	NO NAMED IN	-			-	of Reco				
		Î	erfo	reting	Res	cord If	-,							From		0	Cina	of Shot
F	CITT	ctic	a	F	POOR.	To	No. o	4 535	cris.	•		raction	3 A	HOM	 	-	3.25	
				_			┦								-	-		
						├	-	-		•					┢	-	 	
			-		-				4 5184	<u> </u>	RECORD	·				-		-
	_								V2114	<u>.</u>	ECOND		Amous	nt Pulled		Po	cker R	scord
						Amoun	f Sef		In.	-	ft.	la.	Size	Leng				Make
Size			/1.	The	-	Make	+			╁				 	+			
_5	-	1		-	b	·	1376		_	+				1	7	_		
	4				+		+	_	-	+				1	十			
		1000000	or an Awaren	<u>!</u>								-			 _ Eat	A		
Liner	Reco	ordi	Ame	ount			K	Ind.	TING	A	ND MUD	Top DING			_ 604	1000		
	T.	-	ent S	-1 6	ocks	1	Chemica		1		thod of			Mue	iding	,	Re	evite
Size	-	Ft.	T Is		oca-	-		koki	-	Ce	menting	^	mount	Ma	ehod		(See	Note)
<u> </u>	寸	3.5	,	1	~	1	$\neg \vdash$		1								L	
0-7/	7	-4	7	74														
Notes	wl Wl	hat	math	eod w	*****************	used to	protect	10	nds	if c	outer stri	ngs v	vene pu	lled †				
-																-	aninad	
NOTE	. W	ere	both	om ho	le p	lugs us	ed?	-greque		ACC COMMO	state ki	nd, d	apin sat	ONO TO	EUITE	C	00011000	
											USED						_	
Reter	y Te	ols	wort	used	fro	m	feet	to		my-ando	Cable to	sola w	ere use	d frem	-		fest h	
-			foet,	end	from		fi	s at	to		fe	et, or	ed from			foc	if 10	
							·					· HORNESS STATE						
and water	~	164	LointaRtti	A CHARLES	grass name	STORES AND ASSOCIATION OF		IITI	AL PE	100	UCTION	TEST						•
Descr	tbe	ps:	nd to	tali W	heih	er by	how the	ഗമി	h tub	ing	or coai	ng or	by pun	ping				
				Anglister - 1	-	-						-						
Amos	\$ 65g	ui (ni P	ಕರ್ಷ ಚ	. OA.	-		Siz	re of	ch	oke, if e	27 J.		Longth	of h	88 1		Water
8				ŀ	.le	Gravit	v of oil	L			Type of	Pump	if pun	repo is w	te đ ,	des	ecribe_	

FORMATION RECORD

Give detailed description and thickness of all formation drilled through, contents of sand, whother dry,

Formalies	Тер	Bottom	' Fermation	Tep	Bettern
Surface	0	183			
Sale	185	1485			-
and & Shale	1485	1636	•		
Anhydrite	1636	1673			
Shale & Shells	1673	2160			
Lime & Shale	2160	2360			
Shale & Line	2360	2575	-		
Line & Shale	2575	2750			
Shale & Line	2750	2855	•-		-
Line & Shale	2855			1.	
Broken Lime	2930		•	ľ	
Shale & Line	3095	3205		1	
Line & Stale	3205	3470	. •	00	
Lim	3470	3915		NE	
Lim & Sale	3515	3565		* V	
Line	3565	3610		7. P	İ
Line & Shale	3610	3680		10.	
Line & Shale	3680	3735	(7)		
Line, Shale & C			Cont.	102	V 2
•	3735	3760	Caron Caron		J. 6
Arbuck lo	3760	3775		92 16	
T. D.	3775	'	. E 24	\$ 3	*
		1	*	12/1/2	
	5			. .	
•				į	
-	1				I
			•		1
					1
					1
			•		1
·,					1
	1			I	-
				1	
	į				
*					1
		1			1

i, the undersigned, being first duly sworn upon sorth, state that this small record is true, correct and complete occording to the records of this office and to the best of my knowledge and belief.

John O. Farmer

Russel, (ansas.

Name and little of repress

Securibed and severa to before me this.



I. O. MILLER

C Frank Ray and make a particular formation of the state
619 Brown Building Wichita, Kansas. January 27,1967.

JAN 30 1967

Well Plug Department Mr. S. S. Greider State Corporation Commission 212 North Market St. Wichita, Kansas. 67202.

PERCENTAGE ON DISPLEMENT OF THE PROPERTY OF TH

Dear Mr. Greider:

Re: Allphin #1
SW NE NE Section 32-98-19W
Rooks County, Kansas.

I enclose drillers log from Mr.Farmer for this well.

Knight Casing Pulling Co., will no doubt send in plugging report. However if for any reason they do not, I list the information below;

From T.D., to 3745 sand
From 3745 to 3697 cement **Bfom** 3697 to 248 mud
From 248 to 238 Rock
From 238 to 00 Ready mix mix cement
Completed January 21,1967.

Yours very truly, I. O. Miller

P. C. Broadway