Give All Information Completely  Make Required Affidavit	12 /3	FORM	MATION	OR  PLUGGING	RECORD	Strike out upper lin when reporting plus
Anii or Deliver Report to:	1931					ging off formations.
Inlie Required Affidavit  Inlie or Deliver Report to:  Conservation Division  State Corporation Commission  800 Bitting Building  Wichita, Kansas	OR CONT. Bax	ah am		S 4 - 8 - 94	m 74 00	n. la ad a
NORTH OF C	Clocation as "NE	'NM%SM%'	or footage fro	om lines Center	SET of NE	nge. 1.5(p)(W
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Legge OwnerW.	Tambour.	lern,inc.	<b>a</b>		
\$777E	Lease Name G	H. Davis	i			Well No. 3
ijø						21, 193 ′
	Application for pl	ugging filed			October	8,
	Application for plant	ugging approve	ed		October	11,193
	Plugging Commen	ed ed			October	8, 193 <i>.</i> 21 193 <i>.</i>
						P
1 1	·					**************************************
						ging was commenced?
Locate well correctly on above Section Plat	Was permission of	,				ging was commenced
me of Conservation Agent who sup		m	here IA	ari		
me of Conservation Agent who sup oducing formation	Dept	h to top	Bot	tom	Total Depth	of Well 560 Fee
w depth and thickness of all water	-	S.	•			*****
L, GAS OR WATER RECORDS					CA	SING RECORD
Formation	Content	From	То	Size	Put In	Pulled Out
Marmaton	Gas - Show			8/5/832	<del>//</del> 4560	3550·
Mississippi Lime	5 gal. 230 o					d
Viola lime	2 hrs.			• •		none
	hr. 390 no w				1	
Silicious Lime	H.F. salt W.		5600			
feet for each pl	ent or other plugs were ug set.	used, state the	character of	same and depth pl	aced, from	feet
roducing it into the hole. If ceme	ent or other plugs were ug set.	used, state the	character of	same and depth pl	aced, from	feet
roducing it into the hole. If ceme feet for each plants and the second s	ent or other plugs were ug set. tro-glycerine	used, state the	character of Ls - 5360 4835	same and depth pl 1-53.751 9, 1-48601 10,	aced, from	feet
roducing it into the hole. If ceme feet for each pl Shot = 70 Qts. lig. ni """ "" "" " " " " " " " " " " " " " "	ent or other plugs were ug set. tro-glycerine	used, state the	character of 1s - 5360 4835	same and depth pl	aced, from	increase
roducing it into the hole. If ceme feet for each pl Shot = 70 Qts. lig. ni " " " " Plugged back Chat 4 5!X24 Containers	ent or other plugs were ug set.  tro-glycerine  """  steel cutting	used, state the	character of  Ls - 5360  4835  ontainer	same and depth pl 1-53.75! 9, 1-4860! 10, (100#) Lead	20/37 No /15/37 "	1ncrease 1 11 182-5600
roducing it into the hole. If ceme feet for each plushed to the state of the state	ent or other plugs were ug set. tro-glycerine  "" steel cuttings	used, state the	character of  Ls - 5360  4835  ontainer	same and depth pl 1-53.75! 9, 1-4860! 10, (100#) Lead (400#) "	aced, from	feet  increase
roducing it into the hole. If ceme feet for each plotshot - 70 Qts. lig. ni " " " "  Plugged back Chat 4 5 X24 Containers 6 " "	ent or other plugs were ug set.  tro-glycerine  """  steel cutting	used, state the	character of  Ls - 5360  4835  ontainer	same and depth pl !-53.75! 9, !-4860! 10, (100#) Lead (400#) "	aced, from	feet  increase
roducing it into the hole. If ceme feet for each place of the state of	steel cutting	used, state the	character of  1s - 5360 4835  ontainer	same and depth pl !-53.75! 9, !-4860! 10, (100#) Lead (400#) "	aced, from	feet  increase
roducing it into the hole. If ceme feet for each place of the state of	steel cutting	used, state the	character of  1s - 5360 4835  ontainer	same and depth pl !-53.75! 9, !-4860! 10, (100#) Lead (400#) "	20/37 No /15/37 " 55 wool 55 " 51	feet  increase
reducing it into the hole. If ceme feet for each plots of the state of	steel cutting  Chat  steel cutting  coakum	used, state the	character of  Ls - 5360  4835  ontainer	same and depth pl 1-53.75 9, 1-4860 10, (100#) Lead (400#) "	aced, from	feet  increase
reducing it into the hole. If ceme feet for each plots	steel cutting  """  Chat steel cutting  chat	used, state the	character of  Ls - 5360 4835  ontainer	same and depth pl 1-53.75! 9, 1-4860! 10, (100#) lead (400#) "	aced, from	feet (1) 1ncreese 182-5600 175-5582 18-5140 18-5126 15-5118
roducing it into the hole. If ceme feet for each place of the state of	steel cutting  Chat steel cutting  chat leadwool and	used, state the	character of  Ls - 5360  4835  Ontainer  FILE  DOO#BOOK	same and depth pl 1-53.75' 9, 1-4860' 10, (100#) Lead (400#) " SEC 247 34 PAGE #ZLIN	aced, from	feet (1) 1ncrease 182-5600 175-5582 18-5126 15-5118 130-5040 17-5030 Hole 6
roducing it into the hole. If ceme feet for each plushed	steel cutting  Chat steel cutting chat leadwool and ment tainer steel cu	s and 1 co	character of  1s - 5360 4835  ontainer  FILE  000#BOOK	same and depth pl 1-53.75! 9/ 1-4860! 10/ (100#) Lead (400#) " SEC 247 21 PAGE #21N	20/37 No   15/37   11   15/37   11   51   51   51   51   51   51   51	1ncrease 182-5600 175-5582 26-5140 18-5126 15-5118 130-5040 17-5030 Hole &
roducing it into the hole. If ceme feet for each place of the state of	steel cutting  tro-glycerine  steel cutting  tro-glycerine  tro-gl	s and 1 co	character of  Ls - 5360 4835  ontainer  FILE  DOO#BOOK	same and depth pl 1-5375! 9/ 1-4860! 10/ (100#) Lead (400#) " SEC 247 24 PAGE #2114	20/37 No   15/37   11   15/37   11   51   51   51   51   51   51   51	1ncrease 182-5600 375-5582 26-5140 18-5126 15-5118 130-5040 17-5030 Hole 6 10-5017
roducing it into the hole. If ceme feet for each place of the second of	steel cutting  tro-glycerine  steel cutting  tro-glycerine  tro-gl	s and 1 co	character of  Ls - 5360 4835  ontainer  FILE  DOO#BOOK	same and depth pl 1-5375! 9/ 1-4860! 10/ (100#) Lead (400#) " SEC 247 24 PAGE #2114	20/37 No   15/37   11   15/37   11   51   51   51   51   51   51   51	feet (1) 110crease 110crea
roducing it into the hole. If ceme feet for each place of the second of	steel cutting  "" "  steel cutting  " "  Chat steel cutting  chat leadwool and ment tainer steel cu	used, state the	character of  1s - 5360 4835  ontainer  FILE  000#BOOK  ad 1 container	same and depth pl 1-53.75! 9, 1-4860! 10, (100#) lead (400#) " SEC 247.34 PAGE // ZLIN piner lead v	Aced, from	feet  increase
roducing it into the hole. If ceme feet for each place of the short of the hole. If ceme feet for each place of the short	steel cutting  steel cutting  """"  Chat steel cutting  chat leadwool and ment tainer steel cu	used, state the	character of  Ls - 5360  A835  Ontainer  FILE  DOO#BOOK  ad 1 container  Sary, use BACK	same and depth pl 1-53.75' 9, 1-4860' 10, (100#) lead (400#) " SEC 247 34 PAGE // ZLIN PAGE // ZLIN of this sheet) (6~	20/37 No   15/37 No   15/37 No   15/37 No   55   51   51   51   51   50   60   60   60   60   60   60   60   6	1ncrease 182-5600 175-5582 26-5140 18-5126 15-5118 17-5030 Hole & 10-5017 175-5010 160-4866 00-4860 Bldg, Tulsa, (
reducing it into the hole. If ceme feet for each place of the state of	steel cutting  steel cutting  """"  Chat steel cutting  chat leadwool and ment tainer steel cu	used, state the	character of  Ls - 5360  A835  Ontainer  FILE  DOO#BOOK  ad 1 container  Sary, use BACK	same and depth pl 1-53.75' 9, 1-4860' 10, (100#) lead (400#) " SEC 247 34 PAGE // ZLIN PAGE // ZLIN of this sheet) (6~	20/37 No   15/37 No   15/37 No   15/37 No   55   51   51   51   51   50   60   60   60   60   60   60   60   6	feet  increase
roducing it into the hole. If ceme feet for each place of the same	steel cutting  steel cutting  chat steel cutting  chat leadwool and ment tainer steel cu	used, state the	character of  Ls - 5360  4835  ontainer  FILE  DOO#BOOK  ad 1 conti	same and depth pl 1-53.75! 9, 1-4860! 10, (100#) Lead (400#) " SEC 247_3: PAGE_#21.16 PAGE_#21.16	20/37 No   15/37 No   15/37 No   15/37 No   55   50   51   51   51   51   50   50   50   50   50   50   50   50	1ncrease 182-5600 175-5582 26-5140 18-5126 15-5118 17-5030 Hole (10-5017) 175-5010 160-4866 00-4860 Bldg, Tulsa, (10-5018)
roducing it into the hole. If ceme feet for each place of the second of	steel cutting  steel cutting  tro-glycerine  steel cutting  tro  Chat  steel cutting  chat  leadwool and ment tainer steel cutting  alled 8 5/8 fro  (If additional de	used, state the	character of  Ls - 5360  4835  ontainer  FILE  DOO#BOOK  ad 1 container  Sary, use BACK  OUTHERN,	same and depth pl 1-53.75! 9/ 1-4860! 10/ (100#) Lead (400#) " SEC 247 24 PAGE #211N PAGE #211N einer lead v	aced, from	1ncrease 182-5600 375-5582 26-5140 18-5126 15-5118 130-5040 17-5030 Hole 6 10-5017 175-5010 160-4866 00-4866 00-4860 Bldg. Tulsa, 0
troducing it into the hole. If ceme feet for each place of the second of	steel cutting  steel cutting  tro-glycerine  steel cutting  tro-glycerine  tro-gl	used, state the	FILE DOOFBOOK  and 1 continuer  Sary, use BACK  OUTHERN,	same and depth plants are and depth plants are seed of this sheet)  of this sheet)	20/37 No   15/37 No	10-5017 17-5010 17-5010 160-4866 10-5012 17-5030 Hole 6 10-5017
rateducing it into the hole. If ceme feet for each place for each	steel cutting  steel cutting  """  Chat steel cutting  chat leadwool and ment tainer steel cu  alled 8 5/8 fro  (If additional de	used, state the  5!! shel;  1	FILE DOOFBOOK  and 1 continuer  Sary, use BACK  OUTHERN,	same and depth plants are and depth plants are seed of this sheet)  of this sheet)	20/37 No   15/37 No	10-5017 17-5010 17-5010 160-4866 10-5012 17-5030 Hole 6 10-5017
chroducing it into the hole. If ceme feet for each place for each	steel cutting  steel cutting  """  Chat steel cutting  chat leadwool and ment tainer steel cu  alled 8 5/8 fro  (If additional de	s and 1 comes and	FILE DOO#BOOK  and 1 continuer  which is a strictly and the strictly are strictly as a strictly and the strictly are strictly as a stri	same and depth plants are and depth plants are seed of this sheet)  of this sheet)	20/37 No   15/37 No	10-5017 17-5010 17-5010 160-4866 10-5012 17-5030 Hole 6 10-5017
troducing it into the hole. If ceme feet for each place for each p	steel cutting  steel cutting  """  Chat steel cutting  chat leadwool and ment tainer steel cu  alled 8 5/8 fro  (If additional de	used, state the  5!! shel;  1	FILE DOO#BOOK  and 1 continuer  which is a strictly and the strictly are strictly as a strictly and the strictly are strictly as a stri	same and depth plants are and depth plants are	20/37 No   15/37 No   15/37 No   15/37 No   15/37 No   51   51   51   51   51   50   50   7001 48   48   36   70 Philtower   36   36   36   36   36   36   36   36	10-5017 17-5010 17-5010 160-4866 10-5012 17-5030 Hole 6 10-5017
roducing it into the hole. If ceme feet for each place of the second of	steel cutting  steel cutting  """  Chat steel cutting  chat leadwool and ment tainer steel cu  alled 8 5/8 fro  (If additional de	s and 1 comes and	FILE DOO#BOOK  and 1 continuer  which is a strictly and the strictly are strictly as a strictly and the strictly are strictly as a stri	same and depth plants are and depth plants are	20/37 No   15/37 No	10-5017 17-5010 17-5010 160-4866 10-5012 17-5030 Hole 6 10-5017
roducing it into the hole. If ceme feet for each place of the same are true  feet for each place of the same are true feet feet for each place of the same are true feet feet for each place of the same are true feet feet feet feet feet feet feet fee	steel cuttings  steel cuttings  """""""""""""""""""""""""""""""""""	s and 1 co	character of  1s - 5360 4835  ontainer  FILE  DOO#BOOK  ad 1 continuation  sary, use BACK  OUTHERN,  mplayee of owterfeits, and z	same and depth plants are and depth plants are	20/37 No. (15/37 No. (	10-5017 17-5010 17-5010 160-4866 10-4860 10-5017
roducing it into the hole. If ceme feet for each place of the state of	steel cuttings  steel cuttings  """""""""""""""""""""""""""""""""""	s and 1 co	FILE DOO#BOOK  and 1 continuer  which is a strictly and its continuer  container  iiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiii	same and depth plants are and depth plants are and depth plants are	20/37 No. 15/37	10. increase 10. i
chroducing it into the hole. If ceme feet for each place for each	steel cutting  steel cutting  tro-glycerine  steel cutting  tro-glycerine  tro-gl	s and 1 comes and	FILE DOO#BOOK  and 1 continuer  which is a strictly and its continuer  container  iiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiii	same and depth plants are and depth plants are and depth plants are	20/37 No. (15/37 No. (	10. increase 10. i

H. F. mud and 5 d
Wood plug © 500° in 12½°, steel cuttings, oakum, 50 buckets
sand and H.F.M.

25 sacks coment in cellar

## RECORD OF FORMATIONS

Formation	Тор	Bottom	Remarks
Eurepag and aslier	^	10	
Surface and cellar	0	10	
Clay and red bed	10	270	
Red bed and shale shells Shale shells	270 615	615	
Shale	730	730 1210	
Shale and shells	1210	1685	
Shale and lime	1685	2035	
sime	2035	2080	
ime and shale	2080	2135	
ime	2135	2170	
ime and shale	2170	2280	
ime	2280	2350	
ime and shale	2350	2400	1
ime	2400	2435	
ime and shale	2435	2590	
ime	2590	2705	
ime and shale	2705	3080	
ime	3080	3115	
ime and shale	3115	3150	
Shale	3150	3180	
Shale and lime	3180	3240	
ime	3240	<i>395</i> 0	
ime, gray shale and trace black	4000	10.10	
late	4000	4040	
ime and gray shale	4040	4095	The state of the s
dittle lime, sand, and trace gray shale	4095	4130	PLUGGING
race red bed, gray shale	4079 4130	41 <i>75</i>	
ray shale	4175	4218	FILE SEC 24 T 34 R 150
ray lime and decreasing amount	4218	4245	Top Kansas Cify Line NE 3/_
ray shale	46.20	7677	Tob warmen to a partition
ray lime	4245	4310	
ray lime, little gray shale and		.,	
race black shale	4310	4340	Slope test @ 4250 = 10
ray lime and little gray shale	4340	4445	S.L.M. @ 4300 OK Reamed tight hole 4100-4135 and 4250-4280
ray lime	4445	. 4535	WW. 1270 -1200
ray shale and lime	4535	4570	
•	4570	4572	S.L.M.
	, ·-	-21-	Drilling time -
	. ,		4500 - 4505 = 66 min.
			4505 - 4510 = 70 "
•	• •	•	4510 - 4515 = 120 min.
•		•	4515 - 4520 = 130 "
		<b>y</b> ,	4520 - 4525 = 140 "
		, ,	4525 - 4530 = 180 "
			4530 - 4535 = 65 mine
		•	4535 - 4540 = 55 "
			4540 - 4545 = 50 "
			4545 - 4550 = 50 "
·			4545 - 4550 = 50 " 4550 - 4555 = 50 "
			4545 - 4550 = 50 " 4550 - 4555 = 50 " 4555 - 4560 = 61 "
			4545 - 4550 = 50 " 4550 - 4555 = 50 " 4555 - 4560 = 61 " 4560 - 4565 = 45 "
		· .	4545 - 4550 = 50 " 4550 - 4555 = 50 " 4555 - 4560 = 61 " 4560 - 4565 = 45 " 4565 - 4570 = 48 "
	101		4545 - 4550 = 50 " 4550 - 4555 = 50 " 4555 - 4560 = 61 " 4560 - 4565 = 45 " 4565 - 4570 = 48 " Stuck drill pipe coming out
·	\$11011		4545 - 4550 = 50 " 4550 - 4555 = 50 " 4555 - 4560 = 61 " 4560 - 4565 = 45 " 4565 - 4570 = 48 " Stuck drill pipe coming out of hole at 4477 due motor
			4545 - 4550 = 50 " 4550 - 4555 = 50 " 4555 - 4560 = 61 " 4560 - 4565 = 45 " 4565 - 4570 = 48 " Stuck drill pipe coming out of hole at 4477 due motor failure. Circulated pipe lo
			4545 - 4550 = 50 " 4550 - 4555 = 50 " 4555 - 4560 = 61 " 4560 - 4565 = 45 " 4565 - 4570 = 48 " Stuck drill pipe coming out of hole at 4477 due motor

with oil and conditioned hole

Ran 8 5/8" 32# 8 thr. SS casing and cemented @ 4560. Pumped last 150' down in 14 hrs.


Cemented with 225 sacks CK at 11 A.M. 7-28-37 with Halliburton. Moved out rotary and rigged up Standard tools.

## RECORD OF FORMATION

Formation	Тор	Bottom	Remarks
			9/29/79
Lime and shale	4560	4568	Commonced drilling 8/17/37
	4568	4570	2 bailers water hour
Gray shale and lime	4570	4575	,
Lime	4575	4 <i>5</i> 90	
Black shele and lime	4590	4625	Ran tubing and tried to squeeze job to shut off water @ 4568-70
			with 60 sacks. Found top of ce-
			ment @ 4430 and drilled out to 4565. Tested for 3 hours and found pipe dry. Drilled out to 4572 and made 2/3 of 7"X35" bailer water per hour. Drilled to 4625 and tested. Made 1 2/3 bail-
Black shale and little lime,	4625	4647	ers water per hour.  Increase in water of bailer per
Gray lime and little gray shale	4647	4678	hour from 4625-4635.
Black shale and little gray lime Gray shale and thin gray lime		4718	Small show of gas 4710-16.
PLUGO FILE SEC 24- BOOK PAGE-	<b>34</b>	NOW	Hole caving and jars on below.  S/g 4745-4750, exhausted. Cleaning cave for 5 tours @ 4750.  Cleaning out cave for 3 tours @ 4757. Ran 344.7" of 7" 22#  10 thrs.SS liner (took 208 bbls. to load hole) and cement top and bottom from with 35 sack below and 25 above, from 4444-4788.  W. O. C. 72 hours. Fulled tubing and found bottom 8 joints full cement. Tested top of liner with pressure and found top of liner took pressure at 300#. Reran tubing and spotted 55 sacks of incorcement. Tested with 1000# and found 0.K. 9/10/37 found top of
	4209	4424	cement @4205. Estimated base cement 4365. Drilling cement. Mushy below 4365. Appears pressure of recementing forced first cement job to set be-
	4424	4775	hind liner. Tools fell thru liner. Found water @ 4550' and exhausted. Restrung
•	4775	4791	derrick and lines and checked depti Cement. Tested liner after bailing dry and found OK.
	• 0	4791	S/gas - estimated @ 50,000 CE. Ex hausted in 12 hours.
Fray lime and trace of shale Black shale, little gray shale	4791	4820	
and trace lime and chat Gray lime, chat and trace gray shale	4820	4840	Top Mississippi Lime @48351. (-315
	4840	4862	Show dead oil 25° @84°, 4850-55; n further increase to 4862. No gas. Bailed 5 gallons oil per 2 hours t test.
Lime and chat and gray dolomite Gray lime	4862 4956	49 56 509 4	Stain of oil and gas. 4905-23.
Prace chat and gray lime with little gray shale Gray lime Gray shale and lime, trace red	5094 5129	5129 5150	Base Mississippi Lime
rock 5156-61 Black shale, gray lime (trace)	5150 5209	520 <del>9</del> 52 <b>6</b> 6	Kinderhook Formation Chattanooga Formation-3587

## RECORD OF FORMATION

Formation	Top	Bottom	Remarks
	5266	5375	Viola Lime Show of live oil 5366-67. Tested 30 gals/2 hrs. 39 grav. @ 76°. No water. Retested and made 14 bbls. oil
, · · · · · · · · · · · · · · · · · · ·		a k	and 3/4 bbl. Salt water in 15
•	• 1	• • •	hrs. Shot with 70 qts. liquid nitro glycerine from 5360-75 under
•	e.		gravel temp. Cleaned out and tested
		-	1/3 bbl. oil and water per 3 hrs.
	5375	5405	Trace water 5389-5393, exhausted
Green shale (Sylvan)	5405	5425.	•
Green shale	5425	5 <b>450</b>	
Green shale and sand.	545 <del>0</del>	5482	All water exhausted.
Green shale	5482	5530	Fighting bad cave all the way.
Sand and green shale	5530	5563	Base of Simpson Formation
-			l 5½"X33' bailer water per hour @5565'
Lime and little sand	5566	5580	Top of Arbuckle - Silicious
Lime and sand	5580	5592	Very hard
Sandy lime - soft H.F. salt w.	5592	5600	Water level rose to 4000° in 72 hours; to 2500° in 96 hours. Preparing to plug back and recover 8 5/8° casing.



<sup>\*</sup> From sample determination by Skelly Oil Co.