
#### STATE OF KANSAS LETATE CORPORATION COMMISSION

Give All Information Completely Make Required Affidavit Mail or Deliver Report to: Conservation Division State Corporation Commission 800 Bitting Building

## WELL PLUGGING RECORD

Wichita, Kansas	Ki.					
NORTH		NE/CNW#SW#"	or footage fro	m line NE SW	SE; 9901	FSL & 990' FWI
	Lease Owner_	177 73		um Company		SE/
	Lease Name _ Office Address	D 000		Texas		Well No
		Well (completed			Dry Hole	<del></del>
	Date well con		as on, Gas Q	Temp.		1-25 <sub>19</sub> 55
i i	1	or plugging filed				1-29 <sub>19</sub> 59
<del></del>		or plugging appro				<u>1-30 <sub>19</sub> 59</u>
+ #1		menced				L2-5 <sub>19</sub> 55
	Plugging com	pleted				<u> 19 55 19 19 55 1</u>
<b>-</b> -	Reason for ab	andonment of we	ll or producing	g formation	Dry Hole	
'   i				<del></del>	Wana	<del></del>
<u> </u>		g well is abandon	-			19
Locate well correctly on above Section Plat	menced?		the Conserv	ation Division	or its agents be	fore plugging was con
e of Conservation Agent who su	menceur nervised plugging of t	his well M. A	• Rives			
ucing formation None		Depth to top	Botton	i	Total Depth o	f Well 42351 Fee
v depth and thickness of all water					١ -	•
IL, GAS OR WATER RECOR	ens.					CASING RECORD
		<del> </del>	1		<u> </u>	<del> </del>
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	PULLED DUT
None	<del>  </del>		<del> </del>	9 5/8n 5 1/2n	236	None
		<del></del>	<del> </del>	2 1/4"	4234	3025
		<del></del>	1			<u> </u>
:						
	Rig up, check back, loaded I fill up w/sd	ed btm w/ba	iler, put l gas, cl ump 5 sx	same and dept in sd to leaned out	plug cellar; led 90	
troducing it into the hole. If ce	Rig up, check back, loaded fill up w/sd jts of 5½n cs bridge, mix & 301 of base or put in 10 sx	ed btm w/ba hole to kil to 4150', d g, mudded h dump 20 sx f cellar, s cmnt, fill	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc	in sd to leaned out cmnt, pul 25', set 10 11 hole w	plug cellar; led 90 0 rock mud to mix &	feet t
troducing it into the hole. If ce	Rig up, check back, loaded l fill up w/sd jts of 5½" cs bridge, mix & 30° of base of	ed btm w/ba hole to kil to 4150', d g, mudded h dump 20 sx f cellar, s cmnt, fill	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc	in sd to leaned out cmnt, pul 25', set 10 11 hole w	plug cellar; led 90 0 rock mud to mix &	feet t
troducing it into the hole. If ce	Rig up, check back, loaded fill up w/sd jts of 5½n cs bridge, mix & 301 of base or put in 10 sx	ed btm w/ba hole to kil to 4150', d g, mudded h dump 20 sx f cellar, s cmnt, fill	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc	in sd to leaned out cmnt, pul 25', set 10 11 hole w	plug cellar; led 90 0 rock mud to mix &	feet t
troducing it into the hole. If ce	Rig up, check back, loaded fill up w/sd jts of 5½n cs bridge, mix & 301 of base or put in 10 sx	ed btm w/ba hole to kil to 4150', d g, mudded h dump 20 sx f cellar, s cmnt, fill	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc	in sd to leaned out cmnt, pul 25', set 10 11 hole w	plug cellar; led 90 0 rock mud to mix &	feet t
troducing it into the hole. If ce	Rig up, check back, loaded fill up w/sd jts of 5½n cs bridge, mix & 301 of base or put in 10 sx	ed btm w/ba hole to kil to 4150', d g, mudded h dump 20 sx f cellar, s cmnt, fill	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc	in sd to leaned out cmnt, pul 25', set 10 11 hole w	plug cellar; led 90 0 rock mud to mix &	feet t
troducing it into the hole. If ce	Rig up, check back, loaded fill up w/sd jts of 5½n cs bridge, mix & 301 of base or put in 10 sx	ed btm w/ba hole to kil to 4150', d g, mudded h dump 20 sx f cellar, s cmnt, fill	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc	in sd to leaned out cmnt, pul 25', set 10 11 hole w	plug cellar; led 90 0 rock mud to mix &	feet t
troducing it into the hole. If ce	Rig up, check back, loaded fill up w/sd jts of 5½n cs bridge, mix & 301 of base or put in 10 sx	ed btm w/ba hole to kil to 4150', d g, mudded h dump 20 sx f cellar, s cmnt, fill	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc	in sd to leaned out cmnt, pul 25', set 10 11 hole w	plug cellar; led 90 0 rock mud to mix &	feet t
troducing it into the hole. If ce	Rig up, check back, loaded fill up w/sd jts of 5½n cs bridge, mix & 301 of base or put in 10 sx	ed btm w/ba hole to kil to 4150', d g, mudded h dump 20 sx f cellar, s cmnt, fill	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc	f same and dept in sd to leaned out cmnt, pull 5; set 10 ill hole w k bridge, of cellar,	plug cellar; led 90 0 rock mud to mix &	feet t
troducing it into the hole. If ce	Rig up, check back, loaded fill up w/sd jts of 5½n cs bridge, mix & 301 of base or put in 10 sx	ed btm w/ba hole to kil to 4150', d g, mudded h dump 20 sx f cellar, s cmnt, fill	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc	in sd to leaned out cmnt, pul 25', set 10 11 hole w	plug cellar; led 90 0 rock mud to mix &	feet (
troducing it into the hole. If ce	Rig up, check back, loaded fill up w/sd jts of 5½n cs bridge, mix & 301 of base or put in 10 sx	ed btm w/ba hole to kil to 4150', d g, mudded h dump 20 sx f cellar, s cmnt, fill	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc	f same and dept in sd to leaned out cmnt, pull 5; set 10 ill hole w k bridge, of cellar,	plug cellar; led 90 of rock mud to mix & weld stee	feet t
troducing it into the hole. If ce	Rig up, check back, loaded fill up w/sd jts of 5½n cs bridge, mix & 301 of base or put in 10 sx	ed btm w/ba hole to kil to 4150', d g, mudded h dump 20 sx f cellar, s cmnt, fill	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc	f same and dept in sd to leaned out cmnt, pul 25', set 10 ill hole w ok bridge, of cellar,	plug cellar; led 90 0 rock mud to mix & weld stee	feet t
troducing it into the hole. If ce feet for each plug	Rig up, check back, loaded lill up w/sd its of 5½n cs bridge, mix & 300 of base or put in 10 sx plate on surf	ed btm w/ba hole to kill to 4150', d g, mudded h dump 20 sx f cellar, s cmmt, fill pipe.	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc to base c	f same and dept in sd to leaned out cmnt, pull 25', set 10 ill hole was bridge, of cellar,	plug cellar; led 90 of rock mud to mix & weld stee	feet (
troducing it into the hole. If ce feet for each plug  feet for each plug  of Plugging Contractor	Rig up, check back, loaded lill up w/sd its of 5½ cs bridge, mix & 30 of base or put in 10 sx plate on surf	ed btm w/ba hole to kill to 4150', d g, mudded h dump 20 sx f cellar, s cmnt, fill pipe.	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc to base c	f same and dept in sd to leaned out cmnt, pull 25', set 10 ill hole was bridge, of cellar,	plug cellar; led 90 0 rock mud to mix & weld stee	feet t
ntroducing it into the hole. If cefeet for each plug  me of Plugging ContractorAc	Rig up, check back, loaded lill up w/sd its of 5½ cs bridge, mix & 30 of base or put in 10 sx plate on surf	ed btm w/ba hole to kill to 4150', d g, mudded h dump 20 sx f cellar, s cmnt, fill pipe.	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc to base c	f same and dept in sd to leaned out cmnt, pull 25', set 10 ill hole was bridge, of cellar,	plug cellar; led 90 0 rock mud to mix & weld stee	feet  1  DIVISION
troducing it into the hole. If cefeet for each plug feet for	Rig up, check back, loaded lill up w/sd its of 5½n cs bridge, mix & 300 of base or put in 10 sx plate on surf	ed btm w/ba hole to kill to 4150', d g, mudded h dump 20 sx f cellar, s cmnt, fill pipe.	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc to base c	f same and dept in sd to leaned out cmnt, pull 25', set 10 ill hole was bridge, of cellar,	plug cellar; led 90 0 rock mud to mix & weld stee	feet (
e of Plugging Contractor AC	Rig up, check back, loaded lefill up w/sd its of 5½n cs; bridge, mix & 30n of base or put in 10 sx plate on surf	ed btm w/ba hole to kill to 4150', d g, mudded h dump 20 sx f cellar, s cmnt, fill pipe.	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc to base c	f same and dept in sd to leaned out cmnt, pull 25, set 10 ill hole was bridge, of cellar,	plug cellar; led 90 of rock mud to mix & weld stee	feet t
e of Plugging Contractor AC	Rig up, check back, loaded lill up w/sd jts of 5½ cs bridge, mix & 30 of base or put in 10 sx plate on surf	ed btm w/ba hole to kil to 4150', d g, mudded h dump 20 sx f cellar, s cunt, fill pipe.  al description is neces g Co. Bend, Kansa	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc to base c	f same and dept in sd to leaned out cmnt, pull 5; set 10 ill hole w k bridge, of cellar,	plug cellar; led 90 of rock mud to mix & weld stee	feet t
e of Plugging Contractor Acress Bo  TE OF KANSAS  R. C. Bran. being first duly sworn on oath,	Rig up, check back, loaded latin up w/sd its of 5½ cs bridge, mix & 30 of base or put in 10 sx plate on surf  (If addition ex 30 of base or put in 10 sx plate on surf	ed btm w/ba hole to kil to 4150', d g, mudded h dump 20 sx f cellar, s cunt, fill pipe.  al description is neces g Co. Bend, Kansa	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc to base c  ssary, use BACK  B  BARTON employee of c facts, stateme	f same and dept in sd to leaned out cmnt, pull 51, set 10 ill hole w sk bridge, of cellar,	plug cellar; led 90 of rock mud to mix & weld stee	In the above-describe
e of Plugging Contractor Acress Bo  TE OF KANSAS  R. C. Bran	Rig up, check back, loaded latin up w/sd its of 5½ cs bridge, mix & 30 of base or put in 10 sx plate on surf  (If addition ex 30 of base or put in 10 sx plate on surf	ed btm w/ba hole to kil to 4150', d g, mudded h dump 20 sx f cellar, s cunt, fill pipe.  al description is neces g Co. Bend, Kansa	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc to base c  ssary, use BACK  B  BARTON employee of c facts, stateme	f same and dept in sd to leaned out cmnt, pull 51, set 10 ill hole w sk bridge, of cellar,	plug cellar; led 90 of rock mud to mix & weld stee	In the above-describe
troducing it into the hole. If ce feet for each plug  Feet for eac	Rig up, check back, loaded latin up w/sd its of 5½ cs bridge, mix & 30 of base or put in 10 sx plate on surf  (If addition ex 30 of base or put in 10 sx plate on surf	ed btm w/ba hole to kill to 4150', d g, mudded h dump 20 sx f cellar, s cmmt, fill pipe.  Bend, Kansa  UNTY OF  mowledge of the and correct. So h (Signature)	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc to base c  BARTON employee of c facts, stateme elelp me God.	f same and dept in sd to leaned out cmt, pull 25', set 10 ill hole w ok bridge, of cellar,	plug cellar; led 90 of rock mud to mix & weld stee	In the above-describe
e of Plugging Contractor Acress Bo  TE OF KANSAS  R. C. Bran	Rig up, check back, loaded latin up w/sd its of 5½ cs bridge, mix & 30 of base or put in 10 sx plate on surf  (If addition ex 30 of base or put in 10 sx plate on surf	ed btm w/ba hole to kill to 4150', d g, mudded h dump 20 sx f cellar, s cmmt, fill pipe.  Bend, Kansa  UNTY OF  mowledge of the and correct. So h (Signature)	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc to base c  BARTON employee of c facts, stateme elelp me God.	f same and dept in sd to leaned out cmnt, pull 25', set 16 ill hole w ok bridge, of cellar,	plug cellar; led 90 of rock mud to mix & weld stee  IAN 1 // (Chita, Kan chita, Kan kansas	In the above-describe
e of Plugging Contractor Acres Bo  TE OF KANSAS  R. C. Bran being first duly sworn on oath, e-described well as filed and the	Rig up, check back, loaded lill up w/sd its of 5½ cs bridge, mix & 30 of base or put in 10 sx plate on surf  (If addition as Pipe Pulling ax 30 Great I have keep the same are true as at the same are true as set.	ed btm w/ba hole to kill to 4150', d g, mudded h dump 20 sx f cellar, s cmnt, fill pipe.  Bend, Kansa  UNTY OF  nowledge of the (Signature)  Bi	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc to base c  BARTON employee of c facts, stateme elelp me God.	f same and dept in sd to leaned out cmnt, pull 25', set 16 ill hole w ok bridge, of cellar, of this sheet)	plug cellar; led 90 of rock mud to mix & weld stee	In the above-describe
e of Plugging Contractor Acres Bo  RE OF KANSAS  Re Co Bran being first duly sworn on oath, e-described well as filed and the	Rig up, check back, loaded lill up w/sd its of 5½ cs bridge, mix & 30 of base or put in 10 sx plate on surf  (If addition as Pipe Pulling ax 30 Great I have keep the same are true as at the same are true as set.	ed btm w/ba hole to kill to 4150', d g, mudded h dump 20 sx f cellar, s cmmt, fill pipe.  Bend, Kansa  UNTY OF  mowledge of the and correct. So h (Signature)  Be	iler, put l gas, cl ump 5 sx ole to 22 cmnt, fi et 5 roc to base c  ssary, use BACK  BARTON employee of c facts, stateme elep me God.	f same and dept in sd to leaned out cmnt, pull 25', set 16 ill hole w ok bridge, of cellar, of this sheet)	plug cellar; led 90 of rock mud to mix & weld stee  IAN 1 // (Chita, Kan chita, Kan kansas	feet to the showe-describe and the log of the showe-describe and the log o



15-095-01298-0000

### WELL RECORD

Yazel E. TWYMAN #1 P&A NE SW SE Sec 34-295-9W Kingman County, Kansas

Zenda Fieki

Elevation 1580 KB Rotary Depth 4235

Spudded: 10-1-55, 6:00 AM

Completed: Temp Abandoned 11-25-55

Plugged & Abandoned 12-10-55

9 5/8" csg set @ 236' w/225 sx cmnt circ 10-2-55 Casing Points:

5 1/2" csg set @ 4234" w/200 sx cont

10-13-55 - pulled 3025'

				•		
FORMATION SUMMARY	FROM	<u>TO</u>	FORMATION RECORD	DEPTH	SUB-SEA	SOURCE
Sand, Red Bed Red Bed Red Bed, Shale Shale, Lime Lime, Gypsum, Shale	0 220 343 1300 1542	220 343 1300 1542 3516	Lansing Mississippi Rotary Total Depth	3512 4168 4235	<b>-1</b> 934 <b>-</b> 2590	Sample: MAF
Lime, Shale Lime Lime, Shale Lime Lime Lime Lime, Shale Mississippi Chat	3516 3628 3727 3794 383 <b>0</b> 4168		Heebner Lansing Mississippi Total Depth	3286 3511 4167 4235	-1708 -1933 -2589	Schlum n n

#### DRILL STEM TESTS:

10-12-55 - Open hole test fr 4170' to 4190', chokes 1" surf 3/4" btm, op 1 hr gas to surf in 3 min est vol 416 MCFPD, rec 80' HG & OC drlg mud, 80' HG & SOC drlg mud, 10' wtr, FP 40#-55# SIBHP 1400# in 30 min

#### PERFORATING RECORD:

10-16-55	$\frac{1}{2}$ to $\frac{1}{2}$ $\frac{1}{2}$ bullets
10-22-55	4170 to 4176 w/24 3/8" jets
10-25-55	4180 to 4185 w/30 15/32" bullets
11-1-55	4170 to 4176 w/24 ½" bullets
11-3-55	4180 to 4185 w/28 ½" bullets
11-4-55	4176 to 4180 w/16 ½" bullets

## SQUEEZE RECORD:

10-23-55	Tool failure
10-24-55	Diesel Oil squeeze perf 4170 to 4176 w/100 sx @ 2550#, 66 sx in form
10-29-55	Diesel Oil squeeze perf 4170 to 4176 & 4180 to 4185 w/100 sx @ 2850#, 86
	sx in form
10-30-55	Squeeze perf 1170 to 1176 & 1180 to 1185 w/125 sx @ 1000#. 111 sx in form

# ACID OR FRAC JOBS:

ACID OR FRAC		REC' DIR
10-18-55	Vis-0-frac perf 1:170-76 w/5000# sd & 5000 gal lse	oil, press 5100#-2600#-1100#
10-19-55 1 <del>0-</del> 21-55	Acidize perf 4170-76 w/250 gal MCA @ 3400#-2800# Acidize perf 4170-76 w/750 gal MCA @ 2100#-1500#	INFO TO THE
10-26-55	Vis-0-frac perf 4170-76 & 4180-85 w/10,000# sd & 1 atomite @ 3000#-6000#-6000#	file file for the man
<b>11-5-5</b> 5	Vis-0-frac perf 4170-76 & 4176-80 w/5000# sd & 500 3300#	00 gal lse oil @ 3600#-3300#-

#### PLUGGING AND ABANDONMENT RECORD: 12-5-55 to 12-10-55

Rig up, checked btm w/bailer, put in sd to plug back, loaded hole to kill gas, cleaned out cellar; fill up w/sd to  $4150^\circ$ , dump 5 sx cmnt, pulled 90 jts of  $5\frac{1}{2}$ ° csg, mudded hole to  $225^\circ$ , set  $10^\circ$  rock bridge, mix & dump 20 sx cmnt, fill hole w/mud to 30' of base of cellar, set 5' rock bridge, mix & put in 10 sx cmnt, fill to base of cellar, weld steel plate on surf pipe. Plugging supervised by M. A. Rives, State Corp Comm District Plugging Supervisor

