STATE CORP CONSERVATI 200 COLORA WICHITA, K TECHNICIAN Operator L Operator: Name& Address	O40864 ORATION COMMISSION ON DIVISION PLUGGIN DO DERBY BUILDING ANSAS 67302 I'S PLUGGING REPORT 4997 Ross Hoener, Inc. Rt. 1, Box 11 Iuka, KS 67066		SE SW SW, SEC. 330 4290 Lease Name Gobin County Pratt Well Total Depth Conductor Pipe: Surface Casing:	Size Size
	l as hereinafter indi			_
Plugging	Contractor Pratt N	Tell Service,	Inc.	License Number 5893
	P.O. Box 847, Pratt, KS			
-		-	— — — —	7 Year:19 94
Plugging	proposal received fro	Ross Ho	ener	216.546.0506
Ссомрапу	name) Ross Hoener, Inc	<u> </u>		[phone]316-546-2596
Yers: 5/2'	at 4499' w/125 sx ceme	ent. Open hold	e 4499-4520'	
				aker Model AD-1 tension packer
lst plug s	spot 50 sx cement throug	;h 2 3/8" tubi:	ng inside of 5½" casi ———————————	ng at 3300',
2nd plug s	set 5½" CIBP at 923',			
3rd plug p	perforate 5½" casing at	840' and pump	down 300 sx cement	
·		Plugging Prop	osal Received by	Steve Pfeifer (TECHNICIAN)
Ptugglag	Operations attended	by Agent?: /	X Nii Part	None
7.5	ns Completed: Hour: 4	· -		7 Year:19 94
-				gel cement through 2 3/8"
		<u> </u>		Waited for cement to set.
	g back down at 12:30 p.m			
Laid tubin	ng down. 2nd plug set 5	5½" CIBP at 92:	3'. Perforated the b	ease of Anhydrite at 840'.
Pumped dow	vn 5½" casing w/300 sx c	ement (115 sx	over capacity). Had	good returns through out.
Water was	coloring up, indicating	cement near	surface between 5½" X	8 5/8" annulus.but didn't
circulate Remarks:	good cement to surface. : Used 60/40 Pozmix 6% g	<u>el by Allied.</u>	sing in. (See back) No casing recovery. s necessary, use B	ACK of this form.)
1 N V 0	1 Calman observe the	is plugging.	Signed Ale	STATE CORRESPATION COMMAN
DATE		•	- 	(TECHNICIAN VIL VA 100

PLUGGING REPORT CONTINUED: On 7/9/94, tagged top of cement and found top at 62! from surface. Cut off $5\frac{1}{2}$ " & 8 5/8" and ready-mix cement to surface.

REMARKS: 7/6 & 7/94 Pratt Well Service, Inc. found tubing (2 7/8" plastic lined) parted at 1313'. A releasing overshot and working string was run in the hole. Latched onto fish at 1313'. Tubing parted at 3352'. Laid out a total of 108 joints of 2 7/8" plastic lined tubing, totaling 3352'. Tripped back in w/overshot, extension bowl, and jars and work string. Latched onto fish at 3352'. Had the rest of the tubing and packer on. Was not able to release or go up or down w/packer. (Approx. 7 years ago, attempted to pull tubing and packer from the well for a day and one-half but were unable to retrieve. Around that time frame, the tubing/casing annulus was squeezed with Anguard to seal off casing leaks and pass a MIT.)

7/7/94 P.M. Were unable to release overshot off of fish. Called out Dia-Log and backed off working string. Recovered all of working string and bumper sub. Left in hole overshot and approx. 978' of 2 7/8" plastic lined tubing and Baker Model AD-1 tension packer. (Were not able to back off any deeper in 2 7/8" plastic lined or packer due to plastic liner in tubing collapsing and plugging and then there was not enough room to get by overshot w/back off tool and the string shoot was not heavy enough to fall through the Anguard.)

SEF 2 2 1994