STATE CORPORATION COMMISSION 130 S. Market, Room 2078 Wichite, KS 67202 TYPE OR PRINT NOTICE: Fill out completely and return to Goss Div. 2310' Pt. from 25 Section 290' P	
TIPE OF PRINT NOTICE: Fill out completely and return to complete the completely and return to completely and return to complete the completely and return to completely and retu	
LEASE OPERATOR D.R. Lauck Oil Co., Inc. ADDRESS 221 S. Broadway, Suite 400, Wichita, KS 67202 CHARGE OF SECTION OF SECT	
LEASE OPERATOR D.R. Lauck Oil Co., Inc. ADDRESS 221 S. Broadway, Suite 400, Wichita, KS 67202 COUNTY Ellsworth PHONE 620; 263-8267 OPERATORS LICENSE NO. 5427 Date Meil Completed Character of Well Oil Plugging Commenced 4/3/02 (Oil, Gas, D&A, SWD, Input, Water Supply Well) Plugging Completed 4/4/02 The plugging proposal was approved on 4/4/02 (Completed District Agent's Mark ACO-1 filed? Unknown if not, is well log attached? Producing Formation Depth to Top 3243' Bottom 3294' T.D. 3294 Show depth and thickness of all water, oil and gos formations. OIL, GAS OR WATER RECORDS CASING RECORD FORMATION OIL SUPPLIES OF TOP SIZE OF SIZE OF TOP	Line
ADDRESS 221 S. Broadway, Suite 400. Wichita, KS 67202 COUNTY Ellsworth PHONE 620; 263-8267 OPERATORS LICENSE NO. 5427 Date Weil Completed Character of Weil 0il Plugging Commenced 4/3/02 (011, Gas, 0&A, SWD, Input, Water Supply Weil) Plugging Completed 4/4/02 The plugging proposal was approved on 4/4/02 (XCC District Agent's Nois ACD-1 filed? Unknown if not, is well log attached? Producing Formation Depth to Top 3243' Bottom 3294' T.D. 3294 Show depth and thickness of all water, oil and gos formations. OIL, GAS OR WATER RECORDS Casing Record Cantent Cantent From 0 Top 10-3/4" Put in 189! Puiled out 0: Production 0 3243 5-1/2" 3243' 0: Production 0 3243 5-1/2" 3243' 0: Describe in detail the sonner in which the well was plugged, indicating where the aud file placed and the method or methods used in introducing it into the hole. If cament or oth vere used, state the character of same and depth placed, from feet to feet as Bottom plug. Dump sand to 3244'. Put 5 sx on bottom. Rig up Derforators. Perfo at 1190' 938', and 260'. Run tubing in to 1214'. Spot 35 sx and 100 # hulls. Pulled by 500'. Spot 35 sx and 100 # hulls. Pulled up to 265'. Circulate to top. Spo hulls. Pulled tubing out. Tied on to surface pipe. Put 30 sx cement. Top off we cement. Tore down and moved off. Name of Plugging Contractor D.S. & W. Welliservicing, Inc. License No. 6901	Line
PHONES 620) 263-8267 OPERATORS LICENSE NO. 5427 Date Well Coopleted Character of Well Oil Plugging Commenced 4/3/02 COII, Gas, D&A, SWD, Input, Water Supply Well) Plugging Completed 4/4/02 The plugging proposal was opproved on 4/4/02 Coy Virgi] Clothier (KCC District Agent's No. 1s ACD-1 filed? Unknown	ir 🕦
Plugging Commenced 4/3/02 Coll, Gan, D&A, SWD, Input, Water Supply Well) Plugging Completed 4/4/02 The plugging proposal was approved on 4/4/02 The plugging Commenced 4/4/02 The plugging Commence 4/4/02 The pluggin	
The plugging proposal was approved an 4/4/02 (XCC District Agent's No. 1 No.	 .
The plugging proposal was approved an 4/4/02 (KGC District Agent's No. 2004 Virgil Clothier (KGC District Agent's No. 2	
Virgi] Clothier Producing Formation Depth to Top 3243' Battom 3294' T.D. 3294 Show depth and thickness of all water, oil and gas formations. Oil, GAS OR WATER RECORDS Casing Record Formation Content Surface Production Production O 189 10-3/4" Put in 189' Production O 3243 5-1/2" 3243' O' Production O 3243 5-1/2" 3243' O' Production O 3243 5-1/2" 3243' O' Production O 3243 5-1/2" Describe in detail the sonner in which the well was plugged, indicating where the and financed and the method or methods used in introducing it into the hole, if cament or oth was used, state the character of same and depth placed, from feet to feet as Bottom plug. Dump sand to 3244'. Put 5 sx on bottom. Rig up perforators. Perfo at 190', 938', and 760'. Run tubing in to 1214'. Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pulled up to 265', circulate to top. Spot bulls. Pulled tubing out. Tied on to surface pipe. Put 30 sx cement. Top off we cement. Tore down and moved off. Again of Plugging Contractor D.S. & W. Well!Servicing, Inc. License No. 6901	
Producing Formation Depth to Top 3243' Bottom 3294' T.D. 3294 Show depth and thickness of all water, ell and gas formations. OIL, GAS OR WATER RECORDS CASING RECORD Formation Content Surface 0 189 10-3/4" 189' 0' Production 0 3243 5-1/2" 3243' 0' Describe in detail the sonner in which the well was plugged, indicating where the sud fill stated and the method or methods used is introducing it into the hole. If casent or other was described by the character of same and depth placed, from feet to feet as Bottom plug. Dump sand to 3244'. Put 5 sx on bottom. Rig up perforators. Perforating to 1990' 938' and 260'. Run tubing in to 1214'. Spot 35 sx and 100 # hulls. Pup to 966'. Spot 35 sx and 100# hulls. Pup to 966'. Sp	iste)
Depth to Top 3243' Bottom 3294' T.D. 3294 Show depth and thickness of all water, oil and gas formations. OIL. GAS OR WATER RECORDS CASING RECORD Formation Content Surface Discrete Discret	me}.
Formation Content Surface Production Production Oile, gas and the method or methods used in introducing it into the hole. If cement or oth gottom plug. Dump sand to 3244'. Put 5 sx on bottom. Rig up perforators. Perforating the span of the state of surface at 1190'. 938', and 260'. Run tubing in to 1214'. Spot 35 sx and 100 # hulls. Pulled up to 265'. circulate to top. Spot hulls. Pulled tubing out. Tied on to surface pipe. Put 30 sx cement. Top off we cement. Tore down and moved off.	
Formation Content Surface 0 189 10-3/4" 189 0	ا
Formation Content Surface 0 189 10-3/4" 189 0	
Production . 0 3243 5-1/2" 3243' . 0' Describe in detail the sonner in which the well was plugged, indicating where the sud fill stated and the method or methods used in introducing it into the hole. If coment or other used, state the character of same and depth placed, from feet to get as Bottom plug. Dump sand to 3244'. Put 5 sx on bottom. Rig up perforators. Perforating at 1190'. 938', and 260'. Run tubing in to 1214'. Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100# hulls. Pulled up to 265', circulate to top. Spot hulls. Pulled tubing out. Tied on to surface pipe. Put 30 sx cement. Top off we cement. Tore down and moved off. **Rame of Plugging Contractor D.S. & W. Welliservicing, Inc. License No. 6901	
Production . 0 3243 5-1/2" 3243' . 0' Describe in detail the manner in which the well was plugged, indicating where the mud fill saced and the method or methods used in introducing it into the hole. If coment or other used, state the character of same and depth placed, from feet to feet as Bottom plug. Dump sand to 3244'. Put 5 sx on bottom. Rig up perforators. Perforating at 1190'. 938', and 260'. Run tubing in to 1214'. Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100# hulls. Pulled up to 265', circulate to top. Spot hulls. Pulled tubing out. Tied on to surface pipe. Put 30 sx cement. Top off we cement. Tore down and moved off. Taken of Plugging Contractor D.S. & W. Welliservicing, Inc. License No. 6901	<u></u> j
Bottom pluq. Dump sand to 3244'. Put 5 sx on bottom. Rig up perforators. Perfo at 1.190'. 938'. and 260'. Run tubing in to 1214'. Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966'. The following out. Tied on to surface pipe. Put 30 sx cement. Top off we cement. Tore down and moved off. **Ideas of Plugging Contractor D.S. & W. Well!Servicing, Inc. Licease No. 6901	
Bottom pluq. Dump sand to 3244'. Put 5 sx on bottom. Rig up perforators. Perfo at 1.190'. 938'. and 260'. Run tubing in to 1214'. Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966': Spot 35 sx and 100 # hulls. Pup to 966'. The following out. Tied on to surface pipe. Put 30 sx cement. Top off we cement. Tore down and moved off. **Ideas of Plugging Contractor D.S. & W. Well!Servicing, Inc. Licease No. 6901	
	rate we lled t 300#
D.O. Boy 221 Claflin VC 67525	
Address P.O. Box 231, Claflin, KS 67525	
NAME OF PARTY RESPONSIBLE FOR PLUSSIMS FEES: D.R. Lauck Oil Col. Inc.	
STATE OF Kansas COUNTY OF Barton .ss.	
Joseph F. Strube (Employee of Operator) or (Operator) or (

OR