

Kansas Corporation Commission Oil & Gas Conservation Division

1084841

Form CP-1
March 2010
This Form must be Typed
Form must be Signed
All blanks must be Filled

WELL PLUGGING APPLICATION

Form KSONA-1, Certification of Compliance with the Kansas Surface Owner Notification Act, MUST be submitted with this form.

OPERATOR: License #:		API No. 1	5			
Name:			If pre 1967, supply original completion date: Spot Description:			
City: State:		_	Feet from	North / South	Line of Section	
Contact Person:		_	Feet from	East / West	Line of Section	
Phone: ()		Footages	Calculated from Neares		er:	
Filone. ()		0		SE SW		
			me:			
		Lease Na		vveπ π		
Check One: Oil Well Gas Well OG	D&A Cat	hodic Water	Supply Well Ot	her:		
SWD Permit #:	ENHR Permit #:		Gas Storage	Permit #:		
Conductor Casing Size:	_ Set at:	(Cemented with:		Sacks	
Surface Casing Size:	_ Set at:		Cemented with:		Sacks	
Production Casing Size:	_ Set at:		Cemented with: Sac		Sacks	
Elevation: (G.L. / K.B.) T.D.: Condition of Well: Good Poor Junk in Hole Proposed Method of Plugging (attach a separate page if adding Is Well Log attached to this application? Yes No. 1f ACO-1 not filed, explain why:	Casing Leak at:tional space is needed):			tone Corral Formation)		
Plugging of this Well will be done in accordance with K. Company Representative authorized to supervise plugging						
Address:	(Dity:	State:	Zip:	-+	
Phone: ()						
Plugging Contractor License #:	1	Name:				
Address 1:	A	ddress 2:				
City:			State:	Zip:	_+	
Phone: ()						
Proposed Date of Plugging (if known):						

Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Agent

Submitted Electronically



Kansas Corporation Commission Oil & Gas Conservation Division

1084841

Form KSONA-1
July 2010
Form Must Be Typed
Form must be Signed
All blanks must be Filled

CERTIFICATION OF COMPLIANCE WITH THE KANSAS SURFACE OWNER NOTIFICATION ACT

This form must be submitted with all Forms C-1 (Notice of Intent to Drill); CB-1 (Cathodic Protection Borehole Intent); T-1 (Request for Change of Operator Transfer of Injection or Surface Pit Permit); and CP-1 (Well Plugging Application).

Any such form submitted without an accompanying Form KSONA-1 will be returned.

Select the corresponding form being filed: C-1 (Intent) CB-1 (CB-1)	Cathodic Protection Borehole Intent)		
OPERATOR: License #	Well Location:		
Name:	SecTwpS. R		
Address 1:	County:		
Address 2:	Lease Name: Well #:		
City: State: Zip:+	If filing a Form T-1 for multiple wells on a lease, enter the legal description of		
Contact Person:	the lease below:		
Phone: () Fax: ()			
Email Address:			
Surface Owner Information:			
Name:	When filing a Form T-1 involving multiple surface owners, attach an additional		
Address 1:	sheet listing all of the information to the left for each surface owner. Surface owner information can be found in the records of the register of deeds for the		
Address 2:	county, and in the real estate property tax records of the county treasurer.		
City: State: Zip:+			
the KCC with a plat showing the predicted locations of lease roads, tank are preliminary non-binding estimates. The locations may be entered or	dic Protection Borehole Intent), you must supply the surface owners and a batteries, pipelines, and electrical lines. The locations shown on the plat in the Form C-1 plat, Form CB-1 plat, or a separate plat may be submitted.		
owner(s) of the land upon which the subject well is or will be loce CP-1 that I am filing in connection with this form; 2) if the form the form; and 3) my operator name, address, phone number, fax, and I have not provided this information to the surface owner(s). I an KCC will be required to send this information to the surface owner(s).	act (House Bill 2032), I have provided the following to the surface ocated: 1) a copy of the Form C-1, Form CB-1, Form T-1, or Form being filed is a Form C-1 or Form CB-1, the plat(s) required by this and email address. cknowledge that, because I have not provided this information, the wner(s). To mitigate the additional cost of the KCC performing this I fee, payable to the KCC, which is enclosed with this form.		
If choosing the second option, submit payment of the \$30.00 handling form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-	fee with this form. If the fee is not received with this form, the KSONA-1 will be returned.		
Submitted Electronically			

Form	CP1 - Well Plugging Application
Operator	BP America Production Company
Well Name	SHIELDS 1
Doc ID	1084841

Perforations And Bridge Plug Sets

Perforation Top	Perforation Base	Formation	Bridge Plug Depth
2355	2598	Chase	

DATE Shield Cos Unit #1 PATA Shield Cos Unit #1 PATA Procedure w) Cost 1) Millers a, unthange well a Na 442 Pullsub. work css for mechanical freepoint on 4912 Liner. Cut april 442 from freepoint. 2) Nu Bold TIH white 1850, Mix aspot 50.xs Class "C cemes 650' to cover Ponhylrite. Pull up hobe at the e 1100' a spot water 850' to cover possible Glorietta Cospeck. Pott withs 800' A WOC. 3) Load & test Csg e 300 psi. Ru wireline & run CBL from TOC inside 7" casing to verify Toc costside 7" Casing. 30) If coment is below useable water or 10" shoe; Part sq holes a squeeze with 15 sts. coment. 3b) If coment is above useable water or 10" shoe; Run those to 850' & circulate coment to surface Allydrite wit 150 sts. coment. Poth without & fill 7 annulus With 25 sts. 4) Remost is above useable water or 80" shoe; Cost 2214 Liss 28 his e 300 Whr 2350' Casing Tools, tongs & adapter speols = 1200 Backhoe, welder, water trk & 200 = 3000 219,000 00.	FOR	Jason P	he lps	JOB OR AUTH. NO	
PAA Shield Gos Unit #1 Reserve Cty, KS Sec 4 255 35W PAA Procedure wil cost 1) MIRUSU, unthough well a Nu 442 Aulisub. Work CSS for mechanical freepoint on 442 lines. Cut apull 442 from freepoint. 2) Nu BOP a TIH without 1850, mix a spot 50 sec Class C coment 50 sec Class C coment will up hole without 8 100 % spot 50 sec Class C coment will not be cattonseed hulls up to wather 850 to cover possible Glorietta Cssleck. And without 800. 3) Loud a test Csg @ 200 psi. Ru Wireline & run CBL from TOC inside 7" casing to verify TOC outside 7" Casing. 30) If coment is below useable water or 10" shoe; Pert sq holes a squeeze wi 75 sts coment. 3b) If coment is above useable water or 10" shoe; Run tog to 850 a circulate coment to surface wil 150 sts coment. Dit without 465. & fill 7 annulus wil 150 sts coment. Dit without 465. & fill 7 annulus Will 125 sts. 4) Romosu Digart/cut off 4 below ground a welch ID Abdo Cost Casing. 2214 Right 28 has @ 300 w/h Cast 4 tocks (350 sts) 2 setups = 12,300 or Cut 412 Csg, CBL & pert sq holes = 7000 Bouthous welder, welfer to the a BOP = 3000 or Cusing Tools, tongs a adester species = 1200		Linn Er	rergy	, ,	
PAA Procedure wil cost 1) MIRUS U, untlargo well a NU 442 Aullsub. Work CSS for Mechanical Freepoint on 442 hullsub. Work CSS for Mechanical Freepoint on 442 hullsub. Work CSS for Mechanical Freepoint on 442 hullsub. World CSS from Freepoint. 2) NU BOPA TIH with So 1850, mix a spot 50.545 Class C cement 650' to cover Anhydrite. Aull up hole with So e 100' x spot 50.545 Claus C cement wil 100 lbs cottonseed hulls up to water 850' to cover possible Glorietta Css leck. Auth withs 850' a WOC. 3) Loud & test Csg e 300 psi. Ru Wireline & run CBL from TOC: Inside 7" casing to verify Toc outside 7" Casing. 20) If cement is below useable water or 10" shoe; Pert So holes a squeeze with 75 sks cement. 3b) If cement is above useable water or 10" shoe; Run those to 850' a circulate cement to surface wil 150 sxs cament. Authority. A fill 7"annulus wil 11-25 sxs. 4) Ramusu Digaut/cut off 4' below ground a welch ID Plate Cost Lig 28 has e 300 Whr 2201 2211 2211 2211 2211 2212 2213 2214 2215 Cament & tracks (350 sxs) 2 setups = 12,300 av 2355' Cament & tracks (350 sxs) 2 setups = 12,300 av 24578' Cut 412 Csg, CBL k pert Sy holes = 7000 Bockhoe, welder, water trik a 800 = 3000 av Casina Tools, tongs a adopter spools = 1200	SUBJECT	A Chi	W. G. U. H. #1	DATE 6/7/(2	^^
PAA Procedure wil cost 1) MIRUS U, untlargo well a NU 442 Aullsub. Work CSS for Mechanical Freepoint on 442 hullsub. Work CSS for Mechanical Freepoint on 442 hullsub. Work CSS for Mechanical Freepoint on 442 hullsub. World CSS from Freepoint. 2) NU BOPA TIH with So 1850, mix a spot 50.545 Class C cement 650' to cover Anhydrite. Aull up hole with So e 100' x spot 50.545 Claus C cement wil 100 lbs cottonseed hulls up to water 850' to cover possible Glorietta Css leck. Auth withs 850' a WOC. 3) Loud & test Csg e 300 psi. Ru Wireline & run CBL from TOC: Inside 7" casing to verify Toc outside 7" Casing. 20) If cement is below useable water or 10" shoe; Pert So holes a squeeze with 75 sks cement. 3b) If cement is above useable water or 10" shoe; Run those to 850' a circulate cement to surface wil 150 sxs cament. Authority. A fill 7"annulus wil 11-25 sxs. 4) Ramusu Digaut/cut off 4' below ground a welch ID Plate Cost Lig 28 has e 300 Whr 2201 2211 2211 2211 2211 2212 2213 2214 2215 Cament & tracks (350 sxs) 2 setups = 12,300 av 2355' Cament & tracks (350 sxs) 2 setups = 12,300 av 24578' Cut 412 Csg, CBL k pert Sy holes = 7000 Bockhoe, welder, water trik a 800 = 3000 av Casina Tools, tongs a adopter spools = 1200		XIV SAIN	Kerry Cty, Ks Se	c 4 255 35W	
for mechanical freepoint on 4/12 Linei. Cut a pull 4/2 from freepoint. 2) Nu BOP at TIH with the 1850, mix a spot 50.5Ks. Class "C cement of to cover Anhydrite. All up hole with a fellow as pot 50.5Ks. Class "C cement of 100 lbs catterseed hulls up to 100 lbs. Catterseed hulls up to 100 lbs. Catterseed hulls up to 100 lbs. 850' to cover possible Glorietta Cssleck. Alt with this a word. 3) Loud a test Csq. a 300 psi. Ru wireline a run CBL from TOC. inside 7" casing to verify Toc catside 7" Casing. 3a) If cement is below useable water or 10" shoe; Pert sq. holes a squeeze with 155 sts coment. 3b) If cement is above useable water or 10" shoe; Run thog to 850' a Circulate cement to surface with 150 sts coment. Alt with 150. a fill 7'annulus with 1-25 sts. 4) Ramosu Diquat/cut off 4' below ground a weld ID Plato Cost Liq 28 his a 300 whr 250' Canent a trucks (350 sts) 2 setups = 12,300 av. Cut 4/2 Csq., CBL & pert sq. holes = 7000 Buckhoe, welder, water trk a BOP = 3000 av. Caincy Tools, tongs a adapter spools = 1200			Λ .		
for mechanical freepoint on 4/12 Linei. Cut a pull 4/2 from freepoint. 2) Nu BOP at TIH with the 1850, mix a spot 50.5Ks. Class "C cement of to cover Anhydrite. All up hole with a fellow as pot 50.5Ks. Class "C cement of 100 lbs catterseed hulls up to 100 lbs. Catterseed hulls up to 100 lbs. Catterseed hulls up to 100 lbs. 850' to cover possible Glorietta Cssleck. Alt with this a word. 3) Loud a test Csq. a 300 psi. Ru wireline a run CBL from TOC. inside 7" casing to verify Toc catside 7" Casing. 3a) If cement is below useable water or 10" shoe; Pert sq. holes a squeeze with 155 sts coment. 3b) If cement is above useable water or 10" shoe; Run thog to 850' a Circulate cement to surface with 150 sts coment. Alt with 150. a fill 7'annulus with 1-25 sts. 4) Ramosu Diquat/cut off 4' below ground a weld ID Plato Cost Liq 28 his a 300 whr 250' Canent a trucks (350 sts) 2 setups = 12,300 av. Cut 4/2 Csq., CBL & pert sq. holes = 7000 Buckhoe, welder, water trk a BOP = 3000 av. Caincy Tools, tongs a adapter spools = 1200			1) MIRUSU, untlan	ge well a NU 442 Pull	sub. Work as
from free point. 2) Nu bop a TIH withy a 1850, mix a spot 50.45 (Cass C come of to cover Anhydrite. All up hole with a e 100 a spot 50.50. Class C comen will no lbs cotton seed hulls up to water 850 to cover possible Glorietta Cssleck. All withs 800. A will. 3) Loud a test Csg e 200 psi. Ru wireline a run CBL from TOC inside 7" casing to verify Toc cotside 7" Casing. 3a) If coment is below useable water or 10" shoe; Art sq holes a squeeze with 75 st coment. 3b) If coment is above useable water or 10" shoe; Run thog to 850 a circulate coment to surface with 150 sts coment. All without a fill 7" annulus with 1-25 sts. 4) Ramosu Digart (cut off 4 below ground a welch ID Plato Cost Cost Cost Lig 28 his a 300 whr 2550 Cut 412 Csg, CBL & pert xg holes = 7000 av Buckhoe, welder, water trk a 800 = 3000 av Cainc Tools, tongs a adapter spoils = 1200			_	•	
2) NU BOP & TIH with so 1850, mix a spot 50.45 (Comero) to cover Anhydrite. All up hole with se 1100' & spot 50.54.5 (Comero) with 100 (bs cotton seed hulls up to water 850' to cover possible Glorietta Costeok. All withs 800' & woc. 3) Loud & test Cosq @ 300 psi. Ru wineline & run CBL from TOC inside 7" casing to verify Toc actside 7" Casing. 30) If cement is below useable water or 10" shoe; Run to 850' & circulate coment. 3b) If cement is above useable water or 10" shoe; Run to 850' & circulate coment to surface Anhydrite with 150 sxs coment. All withof & fill 7 annulus en 150 sxs coment. All withof & fill 7 annulus with 25 sxs. 4) Romosu Digout/(at off 4' below ground & weld to Photo Cost Co			_	•	•
to cover Anhydrite. All up hole with a e 100' & spot 150 sts. Class "C coment wil 100 lbs cottonseed hulls up to 150 sts. Class "C coment wil 100 lbs cottonseed hulls up to 150 sts. Class "C coment wil 100 lbs cottonseed hulls up to 150 sts. Class "C coment wil 100 lbs cottonseed hulls up to 150 sts. Council with the constance of 10" shoe; 150 sts. Coment is below useable water or 10" shoe; 150 sts. Coment is above useable water or 10" shoe; 150 sts. Coment is above useable water or 10" shoe; 150 sts. coment. All wilting. A fill 7'annulus 150 sts. coment. All wilting. A fill 7'annulus 150 sts. coment. All wilting apound & welch ID Alab 1500' 1500 sts. coment. All wilting apound & welch ID Alab 1500' 1500 sts. coment. (350 sts.) 2 setups = 12,300 ob 1500 class to the coment. (350 s		10	•	by@ 1850, mix a spot 5	OSKS Class"C" CEMENT
Usable useful 350' to cover possible Glorietta Cssleck. Authoritis 850' to cover possible Glorietta Cssleck. Authoritis 800' & WOC. 3) Load & test Csg @ 300 psi. Ru Wireline & run CBL from TOC ! Aside 7" Casing to verify TOC outside 7" Casing. 3a) If cement is below useable water or 10" shoe; hert so holes a squeeze wi 75 sks coment. 3b) If cement is above useable water or 10" shoe; Run thog to 850' a circulate cement to surface wil 150 sks coment. Do Hwitting. A fill 7'annulus wil 11- 25 sks. 4) Romosu Digart/cut off 4' below ground & weld IO Plato Cost Lig 28 his @ 300 whr = 8400 ob Carent & trucks (350 sks) 2 setups = 12,300 ob Carent & trucks (350 sks) 2 setups = 12,300 ob Carent & trucks (350 sks) 2 setups = 3000 ob Carent & trucks (350 sks) 2 setups = 3000 ob Carent & trucks (350 sks) 2 setups = 12,300 ob Carent & trucks (350 sks) 2 setups = 12,300 ob Carent & trucks (350 sks) 2 setups = 12,300 ob Carent & trucks (350 sks) 2 setups = 12,300 ob Carent & trucks (350 sks) 2 setups = 12,300 ob Carent & trucks (350 sks) 2 setups = 12,300 ob Carent & trucks (350 sks) 2 setups = 12,300 ob Carent & trucks (350 sks) 2 setups = 12,300 ob Carent & trucks (350 sks) 2 setups = 12,300 ob Carent & trucks (350 sks) 2 setups = 12,300 ob Carent & Trucks (350 sks) 2 setups = 12,300 ob Carent & Trucks (350 sks) 2 setups = 12,300 ob Carent & Trucks (350 sks) 2 setups = 12,300 ob Carent & Trucks (350 sks) 2 setups = 12,300 ob Carent & Trucks (350 sks) 2 setups = 12,300 ob Carent & Trucks (350 sks) 2 setups = 12,300 ob Carent & Trucks (350 sks) 2 setups = 12,300 ob Carent & Trucks (350 sks) 2 setups = 12,300 ob Carent & Trucks (350 sks) 2 setups = 12,300 ob Carent & Trucks (350 sks) 2 setups = 12,300 ob Carent & Trucks (350 sks) 2 setups = 12,300 ob Carent & Trucks (350 sks) 2 setups = 12,300 ob Carent & Trucks (350 sks) 2 setups = 12,300 ob Carent & Trucks (350 sks) 2 setups = 12,300 ob Carent & Trucks (350 sks) 2 setups = 12,300 ob Carent & Trucks (350 sks) 2 setups = 12,300 ob Carent & Trucks (350 sks) 2 setups = 12,300		650		· · · · · · · · · · · · · · · · · · ·	_
Useful Water 850 to cover possible Glorietta Cosleck. Alt withs 800. A woc. 3) Loud & test Cosq @ 300 psi. Ru wireline & run CBL from TOC ! aside ?" Casing to verify Toc outside ?" Casing. 30) If cement is below useable water or 10" shoe; Pert sq holes & squeeze wi 75 sxs coment. 3b) If cement is above useable water or 10" shoe; Run thog to 850 & circulate cement to surface wil 150 sxs coment. All without 8 fill 7 annulus wil 150 sxs coment. All without 8 fill 7 annulus wil 17- 25 sxs. 4) Rumosu Diquet/cut off 4 below ground & welcl To Alab Cost C			ia a.		•
3) Loud & test Csq @ 300 psi. Ru Wireline & run CBL from TOC inside 7" casing to verify Toc outside 7" Casing. 30) If cement is below useable water or 10" shoe; Pert sq hules a squeeze w 75 sts coment. 3b) If cement is above useable water or 10" shoe; Run thog to 850' & circulate cement to surface Alhydrite w 150 sts coment. Poth withog. & fill 7'annulus wil 150 sts coment. Poth withog. & fill 7'annulus Wil 11- 25 sts. 4) Romosu Digart (cut off 4' below ground & weld Io Aleb Cost Cast Cast	-				<u>.</u>
from TOC inside 7" casing to verify Toc actside 7" Casing. 3a) If coment is below useable water or 10" shoe; Pert so holes a squeeze w 75 sts coment. 3b) If coment is above useable water or 10" shoe; Run thog to 850' a circulate coment to surface Anhydrite w 150 sts coment. POH withog. A fill 7'annulus W 11-25 sts. 4) Rumosu Diquat/cat off 4' below ground a weld ID Alabo Cost Cost Cost Cost Cannot a trucks (350 sts) 2 setups = 12,300 Cut 412 Csq, CBL a pert so holes = 7000 Bockhoe, welder, water tok a 800 = 3000 Casing Tools, tongs a adapter species = 1200		800.	& WOC.		
from TOC inside 7" casing to verify Toc actside 7" Casing. 3a) If coment is below useable water or 10" shoe; Pert so holes a squeeze w 75 sts coment. 3b) If coment is above useable water or 10" shoe; Run thog to 850' a circulate coment to surface Anhydrite w 150 sts coment. POH withog. A fill 7'annulus W 11-25 sts. 4) Rumosu Diquat/cat off 4' below ground a weld ID Alabo Cost Cost Cost Cost Cannot a trucks (350 sts) 2 setups = 12,300 Cut 412 Csq, CBL a pert so holes = 7000 Bockhoe, welder, water tok a 800 = 3000 Casing Tools, tongs a adapter species = 1200			3) Loud & test Csg	e 300 psi. Ru Wirelin	e & run CBL
Casing. 30) If Coment is below useable water or 10" shoe; Pert sq holes a squeeze w1 75 sks coment. 3b) If coment is above useable water or 10" shoe; Run thog to 850' & Circulate coment to surface Anhydrite w1 150 sks coment. At Hill thog. & fill 7 annulus 1800' w1 71- 25 sks. 4) Romosu Digart (cut off 4' below ground & weld ID Plato Cost Cost Lig 28 has e 300 ab/hr = 8400 ab/ 2214 Canent & tracks (350 sks) 2 setups = 12,300 ab/ 2355' Canent & tracks (350 sks) 2 setups = 12,300 ab/ 2458' Cut 412 Csq, CBL & pert sq holes = 7000 ab/ Backhoe, welder, water tak a BOP = 3000 ab/ Casing Tools, tongs a adapter spools = 1200			-		
Act so holes a squeeze wi 755K1 coment. 3b) If coment is above useable water or 10" shoe; Run thog to 850' & circulate coment to surface Arhydrite wi 150 sxs coment. Poth withog. & fill 7'annulus 1800' with 7- 25 sxs. 4) Romosu Digout/cut off 4' below ground & weld Io Plato Cost Cost Canent & trucks (350 sxs) 2 setups = 12,300 av. 2598' Cut 412 Csq. CBL & pert & holes = 7000 Backhoe, welder, water tok a BOP = 3000 av. Casing Tools, tongs a adapter speols = 1200					
Run thog to 850' & circulate coment to surface Anhydrite who see coment. At the off of the fill 7'annulus 1800' WHI - 25 sts. 4) Romosu Diquet/cut off 4' below ground & weld ID Plato Cost Lig 28 hrs e 300 Whr = 8400 or 2355' Canent & trucks (350 sts) 2 setups = 12,300 or 2398' Cut 412 Csq, CBL & pert so holes = 7000 Bockhoe, welder, wester tok a 200 = 3000 or Casing Tools, tongs a adapter speals = 1200			30) If coment i	s below useable water	er or 10" shoe;
Run tho to 850' & circulate coment to surface Anhydrite who is seenent. At Hultby. & fill 7'annulus Cost Cost Cost Lig 28 hrs @ 300 and Cost Canent & trucks (350 sxs) 2 setups = 12,300 and Cut 4/2 Csq., CBL & pert x holes = 7000 Backhoe, welder, water tok & BOP = 3000 and Casing Tools, tongs & adapter species = 1200			Pert sq holes	d squeeze wi 75 sks	coment.
Anhydrite white white to Hultby. A fill 7'anneles 1800' WHI - 25 sks. 4) Romosu Diquet/cut off 4' below ground & weld ID Plato Cost Lig 28 hrs @ 300 Whr = 8400 00, 02355' Coment & trucks (350 sks) 2 setups = 12,300 av, 2598' Cut 4/2 Csq, CBL & pert so holds = 7000 Backhoe, welder, water tok a 80P = 3000 00, Casing Tools, tongs & adapter socols = 1200			36) If coment	is above useable water	or 10" shoe;
1800' WI TI- 25 Sts. 4) Romosu Digout/(at off 4 below ground & weld ID Plato Cost Lig 28 hrs @ 300 Whr = 8400 os. 0 2355' Coment & tracks (350 sts) 2 setups = 12,300 ov. 2598' Cut 4/2 Csq, CBL & pert x holes = 7000 ov. Bockhoe, welder, wester tok a BOP = 3000 ov. Casing Tools, tongs a adapter speols = 1200			Runths to 8	50' à circulate ceme	nt to surface
4) Romosu Diquet/cut off 4 below ground & welcl JD Plato Cost Lig 28 hrs @ 300 Whr = 8400 08, Canent & trucks (350 sxs) 2 setups = 12,300 00, Cut 4/2 Csq, CBL & pert x holes = 7000 00, Cut 4/2 Csq, CBL & pert x holes = 3000 00, Cusing Tools, tongs & adapter species = 1200			w/ 150 sxs co	ment. AOHWHG. &	fill 7 annulus
Cost Lig 28 hrs e 300 Whr = 8400 00, 0 2355' Cement & tracks (350 sxs) 2 setups = 12,300 00, 0 2598' Cut 4/2 Csq, CBL & pert x holes = 7000 00, Bookhoe, welder, water tok a BOD = 3000 00, Casing Tools, tongs a adapter species = 1200		1800′	WI 71- 25 SKJ.		
Cost Lig 28 hrs e 300 Whr = 8400 00, 0 2355' Cement & tracks (350 sxs) 2 setups = 12,300 00, 0 2598' Cut 4/2 Csq, CBL & pert x holes = 7000 00, Bookhoe, welder, water tok a BOD = 3000 00, Casing Tools, tongs a adapter species = 1200			4) Romosu Digoui	1/cut off 4 below grow	nd & weld ID Plato
c 2355 Coment & tracks (350 sxs) 2 setups = 12,300 av, c 2598 Cut 4/2 Csq, CBL & pert x holes = 7000 av, backhoe, welder, water tok a BOD = 3000 av, c 2603 Casing Tools, tongs a adapter speals = 1200	2214		,	Cost	
c 2355 Coment & tracks (350 sxs) 2 setups = 12,300 av, c 2598 Cut 4/2 Csq, CBL & pert x holes = 7000 av, backhoe, welder, water tok a BOD = 3000 av, c 2603 Casing Tools, tongs a adapter speals = 1200	X /	135 4	Rig 28 hrse:	300 ayhr	= 8400 m
Buckhoe, welder, water tok a BOP = 3000 00 00 00 00 00 00 00 00 00 00 00 0		4 2355	Council & tracks	(350 sxs) 2 setus	= 12,300
Casing Tools, tongs a adapter speals = 1200		2 2598	Cut 442 Csq, (LBL k pert so holes	- 1000
Casing Tools, tongs a adapter speals = 1200				•	= 3000
31,900	Ţ	7 2603	Casing Tools, t	ongs a adapter spools	= 1200
	}	}			<u>31,900</u>

Conservation Division Finney State Office Building 130 S. Market, Rm. 2078 Wichita, KS 67202-3802



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Mark Sievers, Chairman Ward Loyd, Commissioner Thomas E. Wright, Commissioner

June 20, 2012

DeAnn Smyers BP America Production Company 2225 W OKLAHOMA AVE ULYSSES, KS 67880-8416

Re: Plugging Application API 15-093-00267-00-00 SHIELDS 1 N/2 Sec.04-25S-35W Kearny County, Kansas

Dear DeAnn Smyers:

This letter is to notify you that the Conservation Division has received your plugging proposal, form CP-1, for the above well and has reviewed the proposal for completeness. The central office will now forward your CP-1 to the district office listed below for review of the proposed plugging method. Please contact the district office for approval of your proposed plugging method at least five (5) days before plugging the well, pursuant to K.A.R. 82-3-113(b). If a workover pit will be used during the plugging of the well it must be permitted. A CDP-1 form must be filed and approved prior to the use of the pit in accordance with K.A.R. 82-3-600.

The Conservation Division's review of form CP-1, either in the central or district office, does not include an inquiry into well ownership or the filing operator's legal right to plug the well. This notice in no way constitutes authorization to plug the above well by persons not having legal rights of ownership or interest in the well.

This notice is void after December 17, 2012. The CP-1 filing does not bring the above well into compliance with K.A.R 82-3-111 with regard to the Commission's temporary abandonment requirements.

Sincerely, Production Department Supervisor

cc: District 1

(620) 225-8888