

RCA WELL SERVICE REPORT

Well Name & No. Akins # 42 COMPANY NAME: Daystar
 County: _____ Report Date: 1 - 17 - 2014

TBG DATA	SIZE	# OF JOINTS	# & SIZE OF SUBS	STATOR SIZE & LOC	MUD ANCHOR SIZE & LOC	S/N LOC
<u>Working string</u>	<u>2 3/8</u>	<u>49</u> <u>1362</u>				
ROD DATA	SIZE	# OF RODS	# & SIZE OF PONYS	ROTOR	INSERT PUMP DESCRIPTION	

ACTIVITY LAST 24 HOURS

TIME ON LOCATION	TIME OFF LOCATION	RIG #	OPERATOR	RIG HANDS	DEPTH OF FAILURE

RIG MOVE IN/OUT: _____

CREW TRUCK: _____

SPECIAL TOOLS USED: Tongs x2Tubing TR, Working string

DESCRIPTION OF WORK PERFORMED: Loggers Perked 4 1/2 at 250' and 790'
Ran 49 joints Taped bottom at 1362. Pull one joint leaving 1345'
Pump Plug. Trip to 811' pump second Plug Trip to 278' pump cement
to surface. Lay rest of tubing out, top 76' off and Flush Working string.
Rig down.

Part failed:	Trouble:	Cause:
Tubing	Hole	Corrosion
Rods	Split	Erosion
Pump	Stuck	Fatigue
Rotor	Parted	Paraffin
Stator	Twisted Off	Rod Wear
	Collapse	Sand
	Debris	Over Pumping
	Slipping	Normal Wear
	Not pumping	Torque

MATERIALS USED/REPLACED

CHARGED:

	YES/NO
	YES/NO
	YES/NO
	YES/NO
	YES/NO

Location:	Severity:	Action:
Body	Light	Replace
Coupling	Moderate	Repair
Barrel	Severe	Remove
Plunger	N/A	Change Type
Screen		None

RCA WELL SERVICE
 615 N. POPLAR
 EUREKA, KS 67045
 (620) 583-5545 - OFFICE