

RCA WELL SERVICE REPORT

Well Name & No. Akins # 53 COMPANY NAME: Daystar
 County: _____ Report Date: 1-12-20

TBG DATA	SIZE	# OF JOINTS	# & SIZE OF SUBS	STATOR SIZE & LOC	MUD ANCHOR SIZE & LOC	S/N LOC
working string	2 3/8	47 1473				
ROD DATA	SIZE	# OF RODS	# & SIZE OF PONYS	ROTOR	INSERT PUMP DESCRIPTION	

ACTIVITY LAST 24 HOURS

TIME ON LOCATION	TIME OFF LOCATION	RIG #	OPERATOR	RIG HANDS	DEPTH OF FAILURE

RIG MOVE IN/OUT: _____

CREW TRUCK: _____

SPECIAL TOOLS USED: Tongs &Working String, Tubing TR.

DESCRIPTION OF WORK PERFORMED: Loggers Perfed 4 1/2 at 250' and 820'
Taped at 1473' picked off bottom a few feet Pump First Plug. Trip 20
Salts to 847' Pump second plug, Trip 19 Salts to 847' Pump third
Plug to surface. Removed tubing top off from surface. Flush working string.
Rig down.

Part failed:	Trouble:	Cause:
Tubing	Hole	Corrosion
Rods	Split	Erosion
Pump	Stuck	Fatigue
Rotor	Parted	Paraffin
Stator	Twisted Off	Rod Wear
	Collapse	Sand
	Debris	Over Pumping
	Slipping	Normal Wear
	Not pumping	Torque

MATERIALS USED/REPLACED

CHARGED:

	YES/NO
	YES/NO
	YES/NO
	YES/NO
	YES/NO

Location:	Severity:	Action:
Body	Light	Replace
Coupling	Moderate	Repair
Barrel	Severe	Remove
Plunger	N/A	Change Type
Screen		None

RCA WELL SERVICE
 615 N. POPLAR
 EUREKA, KS 67045
 (620) 583-5545 - OFFICE