BASIC* ENERGY SERVICES PRESSURE PUMPING & WIRELINE

10244 NE Hwy. 61 P.O. Box 8613 Pratt, Kansas 67124 Phone 620-672-1201

FIELD SERVICE TICKET

1718 1674 A

The Street of th	PRESSI	URE PUN	IPING & WIRELINE	5-	195	111/		DATE	TICKET NO				
DATE OF JOB	20	-10	DISTRICT Pratt	Tan	I NEW = OLD								
CUSTOMER	Prol	ifi	Resources	1 417	J4 J	ONDER NO.:							
ADDRESS	4 1 10 3		- 1100100		LEASE PANNING B WELL NO. 2								
CITY	***		STATE		COUNTY Barton STATE Tansas								
AUTHORIZED	PV		SIMIE		SERVICE CREW C. Messick: M. Mattal: D. Phye								
EQUIPMEN		HRS	EQUIPMENT#	JOB TYPE: C.N.W Plug To Abandon									
19,966		1.75	EGOII MENT#	HRS	EQU	IIPMENT#	HRS	TRUCK CA		19. C	E AM	TIME 30	
						ARRIVED A	The second secon	-19-11	AM PM	145			
19,903-1	9,905	1.75						START OPE		-19-1	AM I	30	
10 033 31	010	175					FINISH OPE	RATION 4	120-6	O PM	15		
17,052 dl,0				RELEASED 5000 SM 1:45									
			TRACT CONDITIONS: (This co						M STATION T	O W⊭LI	- 55		
ITEM/PRICE	this contra	ct without	execute this contract as an age of and only those terms and co the written consent of an office	er of Basic	Energy Ser	vices LP.	or triis doi	IGNED:	ER, OPERATOR	te terms	and/or conditio	ons shal	
REF. NO.	17.0		ATERIAL, EQUIPMENT A		/ICES USE	D	UNIT	QUANTITY	UNIT PRI	CE	\$ AMOU	NT	
C 103	160	140	Poz Cement				Sh	185-		市	2,220	06	
										J.			
CC 200	Ce	ment	Gel				Lh	320 -	Company of the Compan	4	20		
							Com C.	300		7		00	
CF 153		oden	DI 05/211										
	W OC	$2\alpha = n$	1109, 0 78	-			ea	1		\$	160	00	
									-	++			
E 100	111	TUP	Mileage				mi	55		韦	233	ra	
F 113	RIL	TYF		eage			mi	10		5	770	00	
	וועעו	LDS	livery				tm	440		1\$	T04	00	
CE 204 CE 240	Cem	ent	and Mixing S	of To	4,000	Teet i	Job	1.		\$	2.160	00	
CL 810	nien	CHAG	and Mixing S	ervi	(6		5h	185		\$ 1	259	00	
										1			
5003	Ser	vice	Supervisor				Job	1		4	- No. 100		
							1001	- submir	0110 ==	\$	175	00	
CHE	EMICAL / A	ACID DATA	A:	18					SUB TO	MAL			

SERVICE REPRESENTATIVETIENE R. M. gasid

THE ABOVE MATERIAL AND SERVICE ORDERED BY CUSTOMER AND RECEIVED BY:

MATERIALS

SERVICE & EQUIPMENT

Shawa EP

TOTAL

FIELD SERVICE ORDER NO.

(WELL OWNER OPERATOR CONTRACTOR OR AGENT)

%TAX ON \$

%TAX ON \$



TREATMENT REPORT

Customer	Lea	se No.					Date			47							
Lease D	Well #								1.								
Field Order # Station Pratt Tans						Casing) 1 De	Count	Barton	1	State		
Type Job	1. Iv Pl	Ug		9 bun			Formation					Legal Description					
PIPE	DATA	PERF	ORAT	TING E	NG DATA FLUID USED)	TREATMENT RESUME							
Casing Size	ing Size Tubing Size			t _D		Acid			0185 Sarks			RATE PRESS I USIP					
Depth	Depth	oth T			То	To Pre Pad 3.8			816	l/Sa	Max 906 al./5/			4 5 Min. FT. / St.			
Volume	Volume From				То		Pad				Min			10 Min.			
Max Press	Press Max Press		From		То		Frac			Avg				15 Min.			
Well Connection	ell Connection Annulus Vol.		From		То		347				HHP Us	sed		Pressure			
Plug Depth	Packer Dep	epth From			То	То		Flush Drillin		lvda	Gas Volume		Water	Total Load			
Customer Repre	esentative	d	Ros	1ch		Station	Mar	nager Do	wíd	500	1	Tre	ater dience R	Me	ssich		
Service Units	9.866	19.	903	19.9	05 [9,83	12	21,010									
Driver Names	ssich		Mat	tal		P	h	ye									
Time 7.1	Casing Pressure		ubing essure	Bbls	s. Pumpe	ed	Rate			Service Log							
10:45				TI	Uch	son	lg	ation	and	holo	Isafe	nyte	eeting.				
厚			*******************************			1	Sly	Plug 3	28	OFe	<u>et / i</u>	75 =	achs ce	nent			
11.32		450					5 Start				Fresh Water Pre-Flush.						
			-50	50 J		0		5		Start Mixing cement.							
			- 00		26		5_		5	Start Fresh Water Spacer.							
			250		26,		5 5			Start Drilling Mod Displacement.							
11:35		-6	9 -		(6)		- mil/151		5	STOP DUMPING							
					***************************************			2 7 Klug		510 Feet / 80 sacks coment							
1242		0	75			5		15	Start Mixing coment								
				29	29 H		9		Start Fresh Water Displacement								
12,45		-0-			$d \perp$		314 Plus		9	Step puncing 350Feet / 40 sacks							
		1 -				-	7	Fly	15	<u> 50t</u>	eet/	400	acks				
12:53		179		10					Start Mixing coment,								
	1	-0-		77		7			Start Freshwater displacement.								
12.55		~<	2-	1_	- Look		LIT	NDI	5	op p	MAP.	00-					
		-5 -					thy Plug HOFE		1/100	et/10 sacts Mixinacementalterinseting wood plyninter							
110		-0	2		-	+		7	157								
110					4->			3 Plus Pot			CITO	cuculated to Surface, Stop pumping.					
1.17		-0-								Plug Rat Hole							
1.45		 								Wash up pumptruck. Tob Complete.							
1117						\dashv)	00 (<u> 001</u>	JIETE		_ fs /			
										Thank You: Clarence, Mike, Dale							