ALLIED OIL & GAS SERVICES, LLC 052844 Federal Tax I.D.# 20-5975804

REMIT TO P.O. BOX 31 RUSSELL, KANSAS 676	65		SER	VICE POINT:	ral.
DATE 05-04-15 SEC. TWP. 97-5	RANGE 34W	CALLED OUT	ON LOCATION	JOB START	JOB FINISH
LEASE TOUES WELL # 2-16	LOCATION S. W.	ete N to CRS	SO LUGAL	COUNTY	STATE
OLDOR NEW (Circle one)		2M, W. AM. (LK5
CONTRACTOR Medina W. TYPE OF JOB Squeeze		^	ASILLAS PE		Corp.
HOLE SIZE 778 T.D		CEMENT		1324	
CASING SIZE 5.5 /5.5#DE	PTH 4200-f++	_ AMOUNT OR	DERED <u>100</u>	ISK olo	155 A
	PTH 3791 -{ F PTH				
TOOL DE	PTH		Δ.		
	NIMUM	_ COMMON	9. 100 sk		1,79000
MEAS. LINE SHO CEMENT LEFT IN CSG.	DE JOINT	_ POZMIX GEL		_@	-
PERFS.		_ CHLORIDE _	100 Lb	_@ <u> </u>	110.00
DISPLACEMENT 21.9/ MAX	26 BBIS	ASC			
EQUIPMENT				(a)	
PUMP TRUCK CEMENTER 3	bea Chause	_		- [@]	
#531-541 HELPER Cesas	Paris				-
BULK TRUCK	Λ ,			_ @ @	·
# 956-841 DRIVER JOSE BULK TRUCK	Calderon.			_ @	
# DRIVER				@	
		HANDLINGMILEAGE			
REMARKS:		(g65.00		TOTAL	1,900.00
		(362.00	10000		**: A DOM:
		- 	SERVI	CE	
		_ Mathandlin	19. 200 c.f	@ 2.48	496.00
1		PUMP TRUCK		@2,75	1,292.50
3		_ Dragage *	200 50 MI		385,50
The second secon		MANIFOLD		@	
		Light Vehi	cle 50 Mi	@4.40.00	220.00
CHARGE TO: CASILLAS PETE	Days w Page	Jana by N			
		- 1975.5	51 / 35 %	TOTAL	5,6443
STREET		_ **			7.5
CITYSTATE	ZIP	_	PLUG & FLOA	T EQUIPME	NT
		201 7 - 01 		@	
To: Allied Oil & Gas Services, LLC					* : ***********************************
You are hereby requested to rent cer				_ @	
and furnish cementer and helper(s) t contractor to do work as is listed. T					
done to satisfaction and supervision				TOTAL	
contractor. I have read and understa	and the "GENERAL	CALTOTAN	If Anna		
TERMS AND CONDITIONS" lister	d on the reverse side	ALES IAX (If Any)	u 34	
V. D		TOTAL CHAR	RGES LOT	25%	
PRINTED NAME LEAT P	WDERGRA	El DISCOUNT	2,640,51.	IF PA	ID IN 30 DAYS
SIGNATURE Last Par	legist	(NIE9=L	1,903,83		
1	01	- (100.			



CEMENTING LOG

						CEMENT DATA
		rict Libera			52844	Spacer Type
Company	Name	PETROLEUM		MEDIA WEL		Amt. Sks Yield ft³/sk Density PPG
Lease		ONES		Description (2-16	
County Location	H	ASKELL	Sta	te K	S	LEAD: Time hrs. Type CLASS A
Field —		* * * *				Excess
Casing Data	Conducto	r PTA	[] c	queeze	Misc.	Amt. 100 Sks Yield 1.18 ft³/sk Density 15.6 PPG
Casing Data	Surface		ediate Pr	roduction	Liner	TAIL: Time hrs. Type CLASS A NEAT
Sizo E	Desire Control of the	e		15.5 # Collar		Excess
3126	1/2 тур	E	weight _	13.3 # Collai		Amt. Sks Yield ft³/sk Density PPG
		· · · · · · · · ·	h			WATER Lead Gal/sk Tail Gal/sk Total BBLS
5	12/2 12/2			HERD		With code out sk full out sk fotal bbb
Casing Depth				4200 FT	PLUS	Pump Trucks Used: 956-841
	-					Bulk Equipment 531-541
Drill Pipe:	BBLS/	LIN. FT		. FT/BBL		
Open Hole:	BBLS/	LIN. FT	LIN	. FT/BBL		Float Equipment: Manufacturer
Capacity Fac	tors: BBLS/	LIN. FT	LIN	. FT/BBL		Shoe: Type Depth 4200 FT.
Casing	BBLS/	LIN. FT 🔣 0		. FT/BBL		Float: Type Depth
Open Holes	BBLS/	LIN. FT 🔣	LIN	. FT/BBL		Centralizers: Quantity Plugs Top Bottom
Drill Pipe	BBLS/	LIN. FT 🔝	LIN	. FT/BBL		Stage Collars
Annulus	BBLS/	LIN. FT 0		. FT/BBL		Special Equipment
	BBLS/	LIN. FT	LIN	. FT/BBL		Disp: Fluid Type MUD Amt 20 bbls Weight 9.4 PPG
Perforations	From 40	00-4005 ft	to 4055-40	160 ft Am	60 FT	Mud Type Weight
				\triangle		
)	1 1	1) 0	LA	
COMPANY R	EPRESENTAT	IVE	ent	Tenter	= cull	CEMENTER RUBEN CHAVEZ
			0, 1			
TIME	DDECCI	V	- C - SSSS			
THVIL	PRESSU	JRES PSI	FLU	ID PUMPED D	DATA	
	DRILL PIPE	ASSESSMENT OF THE PARTY OF THE	TOTAL	PUMPED PER	RATE	REMARKS
AM/PM	= 10-50 to = 517-90-90-90 to 0	ANNULUS		T		REMARKS
	DRILL PIPE	ASSESSMENT OF THE PARTY OF THE	TOTAL	PUMPED PER	RATE	Got to location spot rucks and rig up
AM/PM 9:00 AM, 10:00 AM.	DRILL PIPE	ASSESSMENT OF THE PARTY OF THE	TOTAL	PUMPED PER	RATE	Got to location spot rucks and rig up Safety meeting
9:00 AM, 10:00 AM. 10:20	DRILL PIPE CASING	ASSESSMENT OF THE PARTY OF THE	TOTAL FLUID	PUMPED PER TIME PERIOD	RATE BBLS/MIN	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to3000 psi
9:00 AM, 10:00 AM. 10:20 10:22	DRILL PIPE CASING	ASSESSMENT OF THE PARTY OF THE	TOTAL FLUID	PUMPED PER TIME PERIOD	RATE BBLS/MIN	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi .
9:00 AM, 10:00 AM. 10:20	DRILL PIPE CASING	ASSESSMENT OF THE PARTY OF THE	TOTAL FLUID 27 58	PUMPED PER TIME PERIOD 27 31	RATE BBLS/MIN	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi. Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200
9:00 AM, 10:00 AM. 10:20 10:22 10:35	DRILL PIPE CASING	ASSESSMENT OF THE PARTY OF THE	TOTAL FLUID 27 58 68	PUMPED PER TIME PERIOD 27 31 10	RATE BBLS/MIN 2.5 3	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi . Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm.
9:00 AM, 10:00 AM. 10:20 10:22 10:35	DRILL PIPE CASING	ASSESSMENT OF THE PARTY OF THE	27 58 68 89	27 31 10 21	2.5 3 3	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to 3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi. Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104	27 31 10 21 15	2.5 3 2 1.5	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to 3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi. Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48	DRILL PIPE CASING	ASSESSMENT OF THE PARTY OF THE	27 58 68 89	27 31 10 21	2.5 3 3	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to 3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi . Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104 109	27 31 10 21 15 5	2.5 3 2 1.5 0.4	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to 3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi . Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05 1:17	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104	27 31 10 21 15	2.5 3 2 1.5	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi . Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines Start reversing out at 2.5 bpm.
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05 1:17	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104 109	27 31 10 21 15 5	2.5 3 2 1.5 0.4	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi . Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines Start reversing out at 2.5 bpm. Finished reversing
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05 1:17	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104 109	27 31 10 21 15 5	2.5 3 2 1.5 0.4	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to 3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi . Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines Start reversing out at 2.5 bpm. Finished reversing Rig start pulling out tubbing
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05 1:17	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104 109	27 31 10 21 15 5	2.5 3 2 1.5 0.4	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to 3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi. Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines Start reversing out at 2.5 bpm. Finished reversing Rig start pulling out tubbing Put 1000 psi on tubbing
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05 1:17	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104 109	27 31 10 21 15 5	2.5 3 2 1.5 0.4	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to 3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi. Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines Start reversing out at 2.5 bpm. Finished reversing Rig start pulling out tubbing Put 1000 psi on tubbing Job finished
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05 1:17	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104 109	27 31 10 21 15 5	2.5 3 2 1.5 0.4	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi. Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines Start reversing out at 2.5 bpm. Finished reversing Rig start pulling out tubbing Put 1000 psi on tubbing Job finished Rig down
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05 1:17	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104 109	27 31 10 21 15 5	2.5 3 2 1.5 0.4	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to 3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi. Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines Start reversing out at 2.5 bpm. Finished reversing Rig start pulling out tubbing Put 1000 psi on tubbing Job finished
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05 1:17	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104 109	27 31 10 21 15 5	2.5 3 2 1.5 0.4	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi. Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines Start reversing out at 2.5 bpm. Finished reversing Rig start pulling out tubbing Put 1000 psi on tubbing Job finished Rig down
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05 1:17	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104 109	27 31 10 21 15 5	2.5 3 2 1.5 0.4	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi. Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines Start reversing out at 2.5 bpm. Finished reversing Rig start pulling out tubbing Put 1000 psi on tubbing Job finished Rig down
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05 1:17	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104 109	27 31 10 21 15 5	2.5 3 2 1.5 0.4	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi. Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines Start reversing out at 2.5 bpm. Finished reversing Rig start pulling out tubbing Put 1000 psi on tubbing Job finished Rig down
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05 1:17	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104 109	27 31 10 21 15 5	2.5 3 2 1.5 0.4	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi. Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines Start reversing out at 2.5 bpm. Finished reversing Rig start pulling out tubbing Put 1000 psi on tubbing Job finished Rig down
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05 1:17	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104 109	27 31 10 21 15 5	2.5 3 2 1.5 0.4	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi. Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines Start reversing out at 2.5 bpm. Finished reversing Rig start pulling out tubbing Put 1000 psi on tubbing Job finished Rig down
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05 1:17	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104 109	27 31 10 21 15 5	2.5 3 2 1.5 0.4	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi. Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines Start reversing out at 2.5 bpm. Finished reversing Rig start pulling out tubbing Put 1000 psi on tubbing Job finished Rig down
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05 1:17	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104 109	27 31 10 21 15 5	2.5 3 2 1.5 0.4	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi. Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines Start reversing out at 2.5 bpm. Finished reversing Rig start pulling out tubbing Put 1000 psi on tubbing Job finished Rig down
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05 1:17	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104 109	27 31 10 21 15 5	2.5 3 2 1.5 0.4	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi. Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines Start reversing out at 2.5 bpm. Finished reversing Rig start pulling out tubbing Put 1000 psi on tubbing Job finished Rig down
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05 1:17	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104 109	27 31 10 21 15 5	2.5 3 2 1.5 0.4	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi. Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines Start reversing out at 2.5 bpm. Finished reversing Rig start pulling out tubbing Put 1000 psi on tubbing Job finished Rig down
9:00 AM, 10:00 AM. 10:20 10:22 10:35 12:35 12:48 12:48 1:05 1:17	DRILL PIPE CASING 500 0	ASSESSMENT OF THE PARTY OF THE	27 58 68 89 104 109	27 31 10 21 15 5	2.5 3 2 1.5 0.4	Got to location spot rucks and rig up Safety meeting Pressure test pumping lines to3000 psi Start pumping h20 on back side, 27 bbls and put 500 psi. Start pumping h20 in tubbing at 3 bpm; then at 5 bpm, 31bbls dow -200 On bacum ,took 10 bbls h20 at 3 bpm. Start mixing and pumping 50 sk with 2 5 cc; and 50 sk cement 21 bls slurr Start displacement on vacum Start pumping .5 bpm Wash up pump lines Start reversing out at 2.5 bpm. Finished reversing Rig start pulling out tubbing Put 1000 psi on tubbing Job finished Rig down

BLEEDBACK .5 bbls BBLS

THANK YOU

FINAL DISP. PRESS. 2600 PSI BUMP PLUG TO PSI