



TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

Test Ticket

NO. 38356 14879

OCT 18 2010

Well Name & No. Stoecker Unit #2-25 Test No. 1 Date 9-27-10
 Company Murfin Drilling Co. Inc. Elevation 3056 KB 3055 GL
 Address 250 N. Water St 300 Wichita KS 67202
 Co. Rep / Geo. Tom Funk Rig Murfin #22
 Location: Sec. 25 Twp. 12S Rge. 33W Co. Logan State KS

Interval Tested 4590 - 4640 Zone Tested Johnson
 Anchor Length 50' Drill Pipe Run 513 4087 Mud Wt. 9.3
 Top Packer Depth 4585 Drill Collars Run 513 Vis 46
 Bottom Packer Depth 4590 Wt. Pipe Run Ø WL 6.8
 Total Depth 4640 Chlorides 4700 ppm System LCM 1.5

Blow Description IF: Weak Surface Blow
FS: No Return Blow
FF: No Blow
FS: No Return Blow

Rec	Feet of	%gas	%oil	%water	%mud
<u>10</u>	<u>M with oil spots</u>			<u>100</u>	
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 10 BHT 123 Gravity 1 API RW 1 @ 1 °F Chlorides 1 ppm
 (A) Initial Hydrostatic 2343 ☒ Test 1225.00 T-On Location 09:30
 (B) First Initial Flow 32 ☐ Jars 11:03
 (C) First Final Flow 36 ☐ Safety Joint 13:19
 (D) Initial Shut-In 929 ☒ Circ Sub ND Charge T-Pulled 16:20
 (E) Second Initial Flow 41 ☐ Hourly Standby 19:02 T-Out
 (F) Second Final Flow 41 ☒ Mileage 86 RT = \$107.50 Comments milage x 2
 (G) Final Shut-In 353 ☐ Sampler 107.50 No Test Load Tools
 (H) Final Hydrostatic 2231 ☐ Straddle

Initial Open 30 ☐ Shale Packer ☐ Ruined Shale Packer
 Initial Shut-In 60 ☐ Extra Packer ☐ Ruined Packer
 Final Flow 30 ☐ Extra Recorder ☐ Extra Copies 2 = 10
 Final Shut-In 60 ☐ Day Standby ☐ Sub Total 10
 Sub Total \$1332.50 Total 1023000 1490

Approved By [Signature] Our Representative Mike Roberts

Trilobite Testing Inc. shall not be liable for damaged or any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.