


Formation Testing Service Report


Computer Inventoried

RECEIVED
JUL 26 1977
YUCCA #1



15-32-33W


HALLIBURTON SERVICES
DUNCAN, OKLAHOMA



274732-207

PRESSURE

TIME



274732-200

Each Horizontal Line Equal to 1000 p.s.i.



	O. D.	I. D.	LENGTH	DEPTH
Reversing Sub	5.75"	2.25"	1'	
Water Cushion Valve				
Drill Pipe		3.826"	-	
Drill Collars		2 1/4"	690'	
Handling Sub & Choke Assembly	5.75"	1.50"	62"	
Dual CIP Valve	5"	.87"	48.92"	
Dual CIP Sampler				
Hydro-Spring Tester	5"	.75"	60.21"	5426'
Multiple CIP Sampler				
Extension Joint				
AP Running Case	5"	3.75"	49.63"	5431'
Hydraulic Jar	5.03"	1.75"	60.00"	
VR Safety Joint	5.00"	1.00"	33.40"	
Pressure Equalizing Crossover				
Packer Assembly	5.06"	1.53"	69.73"	5449'
Distributor				
Packer Assembly				
Flush Joint Anchor				
Pressure Equalizing Tube				
Blanked-Off B.T. Running Case				
Drill Collars				
Anchor Pipe Safety Joint				
Packer Assembly				
Packer Assembly				
Anchor Pipe Safety Joint				
Side Wall Anchor				
Drill Collars	5 3/4"	2 3/4"	27'	
Flush Joint Anchor	5"	3.25"	40.50'	
Blanked-Off B.T. Running Case	5.75"	2.50"	3.50'	5516'