## RECEIVED

## MAR 2 2 2004 KCC WICHITA

# KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

## **WELL PLUGGING APPLICATION**

Please TYPE Form and File ONE Copy

Form CP-1 September 2003 This Form must be Typed Form must be Signed All blanks must be Filled

indicate original spud or completion date $12/27/95$ .		()
Well Operator: Chesapeake Operating, Inc. (Owner/Company Name)	KCC License #:32334	<i>/</i> 1
(Owner Company Name)	city: Oklahoma City	tor's)
State: OK Zip Code: 7315	4-0496 Contact Phone: (405 ) 848-8000	
Lease: MLP Rooney B Well #: 2-5	Sec. 5 Twp.30S S. R. 34W	Fast X West
- NE - NW - SE Spot Location / QQQQ	County: Haskell	
2070 Feet (in exact footage) From North / X South (fro.	n nearest outside section corner) Line of Section (Not Lease L	ine)
Feet (in exact footage) From X East / West (fro. Check One: X Oil Well Gas Well D&A Cathodia	promises	ine)
C and them C back C cathodic	Water Supply Well	
	t # Other:	
Conductor Casing Size: Set at:	Cemented with:	Sacks
Surface Casing Size: 8-5/8  Set at: 1745  Frequentian Casing Size: 4-1/2!!	Cemented with: 6/5	Sacks
Production Casing Size: 4-1/2" Set at: 5749	Cemented with: 175	Sacks
List (ALL) Perforations and Bridgeplug Sets: 5596*-5620*		
Elevation: 2992 ([X(a.L./[]K.B.)] T.D.: 5750 PBTD:		
Elevation: 2332 (LASE) Inc. 3730 PRTD.		
	Anhydrite Depth:(Stone Corral Formation)	
Condition of Well: X Good Poor Casing Leak	(Stone Corral Formation)  Junk in Hole	
Condition of Well: X Good Poor Casing Leak	(Stone Corral Formation)  Junk in Hole	RIH w/dump
Condition of Well: X Good Poor Casing Leak	(Stone Corral Formation)  Junk in Hole	RIH w/dump
Condition of Well: X Good Poor Casing Leak  Proposed Method of Plugging (attach a separate page if additional space is needed):  ailer & cap CIBP w/2 sx cmt, RIH w/2-3/8" tbg candonment mud, TIH w/free point tool, shoot  c cmt plug. @base of surf csg. TIH w/tbg to 66	Junk in Hole  FIH w/4-1/2" CIBP & set @ ±5545,  to 5500 & displace hole w/9 ppg  off csg at free point, POOH to ±1  Displace hole w/9 ppg  off csg at free point, POOH to ±1  Displace hole w/9 ppg	RIH w/dump & 36 visc. 760', pump 40', pump s
Condition of Well: X Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): ailer & cap CIBP w/2 sx cmt, RIH w/2-3/8" tbg pandonment mud, TIH w/free point tool, shoot c cmt plug,@base of surf csg, TIH w/tbg to 66 Lug, TOOH & LD tbg, weld on plate, clean up 16	Junk in Hole  TIH w/4-1/2" CIBP & set @ ±5545', to 5500' & displace hole w/9 ppg off csg at free point, POOH to ±1 0', pump 30 sx cmt plug, POOH to ocation, RDMO service unit	RIH w/dump & 36 visc. 760', pump 40', pump s
Condition of Well: X Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): ailer & cap CIBP w/2 sx cmt, RIH w/2-3/8" tbg candonment mud, TIH w/free point tool, shoot c cmt plug, @base of surf csg, TIH w/tbg to 66 ug, TOOH & LD tbg, weld on plate, clean up less well Log attached to this application as required?  Well Log attached to this application as required?  Yes No Is ACO-	Junk in Hole  FIH w/4-1/2" CIBP & set @ ±5545', to 5500' & displace hole w/9 ppg off csg at free point, POOH to ±1 0', pump 30 sx cmt plug, POOH to ocation, RDMO service unit  1 filed? XYes No	RIH w/dump & 36 visc. 760', pump 40', pump s
Condition of Well: X Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): ailer & cap CIBP w/2 sx cmt, RIH w/2-3/8" tbg candonment mud, TIH w/free point tool, shoot c cmt plug, @base of surf csg, TIH w/tbg to 66 ug, TOOH & LD tbg, weld on plate, clean up less well Log attached to this application as required?  Well Log attached to this application as required?  Yes No Is ACO-	Junk in Hole  FIH w/4-1/2" CIBP & set @ ±5545', to 5500' & displace hole w/9 ppg off csg at free point, POOH to ±1 0', pump 30 sx cmt plug, POOH to ocation, RDMO service unit  1 filed? XYes No	RIH w/dump & 36 visc. 760', pump 40', pump s
Condition of Well: X Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): ailer & cap CIBP w/2 sx cmt, RIH w/2-3/8" tbg candonment mud, TIH w/free point tool, shoot c cmt plug, @base of surf csg, TIH w/tbg to 66 Lug, TOOH & LD tbg, weld on plate, clean up 1 s Well Log attached to this application as required? Yes No is ACO- f not explain why?	Junk in Hole  TIH w/4-1/2" CIBP & set @ ±5545', to 5500' & displace hole w/9 ppg off csg at free point, POOH to ±1 0', pump 30 sx cmt plug, POOH to ocation, RDMO service unit  1 filed? XYes No	
Condition of Well: X Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): ailer & cap CIBP w/2 sx cmt, RIH w/2-3/8" tbg candonment mud, TIH w/free point tool, shoot c cmt plug, @base of surf csg, TIH w/tbg to 66 Lug, TOOH & LD tbg, weld on plate, clean up 1 s Well Log attached to this application as required? Yes No is ACO- f not explain why?	Junk in Hole  TIH w/4-1/2" CIBP & set @ ±5545', to 5500' & displace hole w/9 ppg off csg at free point, POOH to ±1 0', pump 30 sx cmt plug, POOH to ocation, RDMO service unit  1 filed? XYes No	
Condition of Well: X Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): ailer & cap CIBP w/2 sx cmt, RIH w/2-3/8" tbg candonment mud, TIH w/free point tool, shoot of care plug, @base of surf csg, TIH w/tbg to 660 Lug, TOOH & LD tbg, weld on plate, clean up loss well Log attached to this application as required? Yes No Is ACO- inot explain why?	Junk in Hole  ITH w/4-1/2" CIBP & set @ ±5545', to 5500' & displace hole w/9 ppg off csg at free point, POOH to ±1 0', pump 30 sx cmt plug, POOH to ocation, RDMO service unit  1 filed? XYes No	
Condition of Well: X Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): ailer & cap CIBP w/2 sx cmt, RIH w/2-3/8" tbg candonment mud, TIH w/free point tool, shoot c cmt plug, @base of surf csg, TIH w/tbg to 66 lug, TOOH & LD tbg, weld on plate, clean up 1 s Well Log attached to this application as required? Yes No Is ACO- f not explain why?  Plugging of this Well will be done in accordance with K.S.A. 55-101 et. seq. an ist Name of Company Representative authorized to be in charge of plugging oper	Junk in Hole  TIH w/4-1/2" CIBP & set @ ±5545', to 5500' & displace hole w/9 ppg off csg at free point, POOH to ±1 0', pump 30 sx cmt plug, POOH to ocation, RDMO service unit  1 filed? XYes No	
Condition of Well: X Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): ailer & cap CIBP w/2 sx cmt, RIH w/2-3/8" tbg bandonment mud, TIH w/free point tool, shoot of company (base of surf csg, TIH w/tbg to 66) Lug, TOOH & LD tbg, weld on plate, clean up loss well Log attached to this application as required? Yes No is ACO- inot explain why?  Plugging of this Well will be done in accordance with K.S.A. 55-101 et. seq. an ist Name of Company Representative authorized to be in charge of plugging open Bud Neff  ddress: 4532 W. Jones Avenue	Junk in Hole  TIH w/4-1/2" CIBP & set @ ±5545', to 5500' & displace hole w/9 ppg off csg at free point, POOH to ±1 0', pump 30 sx cmt plug, POOH to ocation, RDMO service unit  1 filed? XYes No  d the Rules and Regulations of the State Corporation Corations:  Phone: (620) 277-0803  City / State: Garden City, KS 67846	ommission.
Condition of Well: X Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): ailer & cap CIBP w/2 sx cmt, RIH w/2-3/8" tbg bandonment mud, TIH w/free point tool, shoot of candonment mud, shoot of candonment mud, shoot of	Junk in Hole  TIH w/4-1/2" CIBP & set @ ±5545', to 5500' & displace hole w/9 ppg off csg at free point, POOH to ±1 0', pump 30 sx cmt plug, POOH to ocation, RDMO service unit  1 filed? XYes No  d the Rules and Regulations of the State Corporation Corations:  Phone: (620) 277-0803  City / State: Garden City, KS 67846	ommission.
Condition of Well: X Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): ailer & cap CIBP w/2 sx cmt, RIH w/2-3/8" tbg candonment mud, TIH w/free point tool, shoot of candonment mud, TIH w/free point tool, shoot of cmt plug, @base of surf csg, TIH w/tbg to 66- ug, TOOH & LD tbg, weld on plate, clean up loss well Log attached to this application as required? Yes No is ACO- not explain why?  Iugging of this Well will be done in accordance with K.S.A. 55-101 et. seq. an ist Name of Company Representative authorized to be in charge of plugging ope Bud Neff  ddress: 4532 W. Jones Avenue  lugging Contractor: Allied Cementing Co., Inc.  (Company Name)	Junk in Hole  TIH w/4-1/2" CIBP & set @ ±5545', to 5500' & displace hole w/9 ppg off csg at free point, POOH to ±1 0', pump 30 sx cmt plug, POOH to ocation, RDMO service unit  1 filed? XYes No  d the Rules and Regulations of the State Corporation Corations:  Phone: (620) 277-0803  City / State: Garden City, KS 67846  KCC License #:	ommission.
Condition of Well: X Good Poor Casing Leak  Proposed Method of Plugging (attach a separate page if additional space is needed): ailer & cap CIBP w/2 sx cmt, RIH w/2-3/8" tbg bandonment mud, TIH w/free point tool, shoot of case cmt plug, @base of surf csg, TIH w/tbg to 66. Lug, TOOH & LD tbg, weld on plate, clean up loss well Log attached to this application as required? Yes No is ACO- f not explain why?  Plugging of this Well will be done in accordance with K.S.A. 55-101 et. seq. an and ist Name of Company Representative authorized to be in charge of plugging open Bud Neff  Address: 4532 W. Jones Avenue  Plugging Contractor: Allied Cementing Co., Inc.  (Company Name)  Address: P. O. Box 31, Russell, KS 67665	Junk in Hole  TIH w/4-1/2" CIBP & set @ ±5545', to 5500' & displace hole w/9 ppg off csg at free point, POOH to ±1 0', pump 30 sx cmt plug, POOH to ocation, RDMO service unit  1 filed? Yes No  d the Rules and Regulations of the State Corporation Corations:  Phone: (620) 277-0803  City / State: Garden City, KS 67846  KCC License #:  (Contractor's) Phone: (785) 483-2627	ommission.
Condition of Well: X Good Poor Casing Leak Proposed Method of Plugging (attach a separate page if additional space is needed): ailer & cap CIBP w/2 sx cmt, RIH w/2-3/8" tbg bandonment mud, TIH w/free point tool, shoot of case and plug, @base of surf csg, TIH w/tbg to 66. Lug, TOOH & LD tbg, weld on plate, clean up loss well Log attached to this application as required? Yes No Is ACO- f not explain why?  Plugging of this Well will be done in accordance with K.S.A. 55-101 et. seq. and ist Name of Company Representative authorized to be in charge of plugging ope Bud Neff  Address: 4532 W. Jones Avenue  Plugging Contractor: Allied Cementing Co., Inc. (Company Name) Address: P. O. Box 31, Russell, KS 67665	Junk in Hole  TIH w/4-1/2" CIBP & set @ ±5545', to 5500' & displace hole w/9 ppg off csg at free point, POOH to ±1 0', pump 30 sx cmt plug, POOH to ocation, RDMO service unit  1 filed? Yes No  d the Rules and Regulations of the State Corporation Corations:  Phone: (620) 277-0803  City / State: Garden City, KS 67846  KCC License #: (Contractor's) Phone: (785) 483-2627	ommission.
Condition of Well: X Good Poor Casing Leak  Proposed Method of Plugging (attach a separate page if additional space is needed): ailer & cap CIBP w/2 sx cmt, RIH w/2-3/8" tbg bandonment mud, TIH w/free point tool, shoot of the control of the contr	Junk in Hole  TIH w/4-1/2" CIBP & set @ ±5545', to 5500' & displace hole w/9 ppg off csg at free point, POOH to ±1 0', pump 30 sx cmt plug, POOH to ocation, RDMO service unit  1 filed? Yes No  d the Rules and Regulations of the State Corporation Corations:  Phone: (620) 277-0803  City / State: Garden City, KS 67846  KCC License #: (Contractor's) Phone: (785) 483-2627	ommission.

Kathleen Sebelius, Governor

Brian J. Moline, Chair

John Wine, Commissioner

Robert E. Krehbiel, Commissioner

### NOTICE OF RECEIPT OF WELL PLUGGING APPLICATION (CP-1)

Chesapeake Operating, Inc. PO Box 18496 6200 N Western Ave. Oklahoma City, OK 73154-0496

March 24, 2004

Re: MLP ROONEY B #2-5

API 15-081-20987-00-00

NENWSE 5-30S-34W, 2070 FSL 1855 FEL

HASKELL COUNTY, KANSAS

#### Dear Operator:

This letter is to notify you that the Conservation Division is in receipt of your plugging proposal, form CP-1, for the above-captioned well.

Your CP-1 has been reviewed by the Conservation Division central office for completeness and to verify license numbers. The plugging proposal will now be forwarded to the district office listed below for review of your proposed method of plugging.

Please contact the district office for approval of your proposed plugging method at least five (5) days before plugging the well, pursuant to K.A.R. 82-3-113 (b). If a workover pit will be used during the plugging of the well it must be permitted. A CDP-1 form must be filed and approved prior to the use of the pit.

The Conservation Division's review of form CP-1, either in the central or district office, does not include an inquiry into well ownership or the filing operator's legal right to plug the well.

This notice in no way constitutes authorization to plug the above-captioned well by persons not having legal rights of ownership or interest in the well. This notice is void after ninety (90) days from the above date.

District: #1

210 E Frontview, Suite A

Dodge City, KS 67801

(620) 225-8888

David P. Williams

**Production Supervisor**