C. M. Copeland, Supt. Helmerich & Payne, Inc. Drilling Contractors.

STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely Make Required Affidavit Mail or Deliver Report to: Conservation Division State Corporation Commission 800 Bitting Building

WELL PLUGGING RECORD

 \mathbf{or}

FORMATION PLUGGING RECORD

Strike out upper line when reporting plugging off formations.

State Corporation Commission 800 Bitting Building Wichita, Kansas					PM Hys. PM		
NORTH	Location as "NI			om lines	•		
0							
	Office Address	Mutual	Bldg., T	lulsa, Oklah	oma	***************************************	
	Character of W	ell (completed a	s Oil, Gas or I	Dry Hole)	ry hole		
				.43			
				-43			
	Application for	plugging appro	ved	·43 ·43		19.	
		Plugging completed 5-12-43 19 Reason for abandonment of well or producing formation Bry hole					
				•••••			
	i iii			production			
Locate well correctly on above	. -		1	ion Division or i	_		
Section Plat ne of Conservation Agent who	menced?			A Torson dom			
ducing formation							
w depth and thickness of all w	•			-	cour popul or	77 021	
OIL, GAS OR WATER RECO					\mathbf{C}	ASING RECOR	
Formation	Content	From	То	Size	Put In	Pulled Out	
buckle			-			None	
	Marat	1	-	, ,			
	1			i i			
			1 1		1		
		1			1		
		-					
feet for each Drill pipe was r s laid down stopped er bottom of surface le with mud to 26°.	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F	hole and ho with heav	ole circul y mud at e L5 sacks o	lated with heach 500 fee	eavy rotar t. Bridge top of br	y mud. As plug push idge. Fil	
prill pipe was reas laid down stopped ear bottom of surface ole with mud to 26'.	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F	hole and ho with heav	ole circul y mud at e L5 sacks o	lated with heach 500 fee	eavy rotar t. Bridge top of br	y mud. As plug push idge. Fil	
feet for each Drill pipe was r as laid down stopped ear bottom of surfac Dle with mud to 26°.	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F	hole and ho with heav	ole circul y mud at e L5 sacks o	lated with heach 500 fee	eavy rotar t. Bridge top of br	y mud. As plug push idge. Fil	
feet for each Drill pipe was r s laid down stopped er bottom of surface le with mud to 26°.	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F	hole and ho with heav	ole circul y mud at e L5 sacks o	lated with heach 500 fee	eavy rotar t. Bridge top of br	y mud. As plug push idge. Fil	
feet for each Drill pipe was r s laid down stopped ar bottom of surfac le with mud to 26°.	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F	hole and ho with heav	ole circul y mud at e L5 sacks o	lated with heach 500 fee	eavy rotar t. Bridge top of br	y mud. As plug push idge. Fil	
feet for each Drill pipe was r s laid down stopped ar bottom of surfac le with mud to 26°.	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F	hole and ho with heav	ole circul y mud at e L5 sacks o	lated with heach 500 fee	eavy rotar t. Bridge top of br	y mud. As plug push idge. Fil	
feet for each Drill pipe was r s laid down stopped ar bottom of surfac le with mud to 26°.	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F	hole and ho with heav	ole circul y mud at e L5 sacks o	lated with heach 500 fee	eavy rotar t. Bridge top of br	y mud. As plug push idge. Fil	
feet for each Drill pipe was r s laid down stopped ar bottom of surfac le with mud to 26°.	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F	hole and ho with heav	ole circul y mud at e L5 sacks o	lated with heach 500 fee	eavy rotar t. Bridge top of br	y mud. As plug push idge. Fil	
feet for each Drill pipe was r s laid down stopped ar bottom of surfac le with mud to 26°.	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F	hole and ho with heav	ole circul y mud at e L5 sacks o	lated with heach 500 fee	meavy rotar ot. Bridge a top of br to 6'.	y mud. As plug pushed pidge. Fill Welded plat	
feet for each Drill pipe was r s laid down stopped ar bottom of surfac le with mud to 26°.	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F	hole and ho with heav	ole circul y mud at e L5 sacks o	lated with heach 500 fee	meavy rotar ot. Bridge a top of br to 6'.	y mud. As plug push idge. Fil	
feet for each Drill pipe was r s laid down stopped ar bottom of surfac le with mud to 26°.	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F	hole and ho with heav	ole circul y mud at e L5 sacks o	lated with heach 500 fee	meavy rotar ot. Bridge a top of br to 6'.	y mud. As plug push idge. Fil: Welded pla	
feet for each Drill pipe was r as laid down stopped ear bottom of surfac Dle with mud to 26°.	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F	hole and ho with heav	ole circul y mud at e L5 sacks o	lated with heach 500 fee	meavy rotar ot. Bridge a top of br to 6'.	y mud. As plug pushed pidge. Fill Welded plat	
feet for each Drill pipe was r as laid down stopped ear bottom of surface le with mud to 26'. For top of surface c	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F asing. Fill 500	hole and howith heav Pumped Illed solid SEC 34 K PAGE 24 K PAGE 24	y mud at of the second with central second with central second with second with second with second with second sec	lated with heach 500 fee of cement on 26	meavy rotar ot. Bridge a top of br to 6'.	y mud. As plug push idge. Fil: Welded pla	
feet for each Drill pipe was r s laid down stopped ar bottom of surface le with mud to 26'. er top of surface c	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F asing. FILI BOO (If additional d s well should be addressed	hole and howith heav Pumped illed solid SEC 34 K PAGE 24 escription is necessal to	ole circuly mud at ole to sacks of with central with cent	lated with heach 500 fee of cement on 26	May 20	y mud. As plug push idge. Fil: Welded pla	
feet for each Drill pipe was r s laid down stopped ar bottom of surface le with mud to 26'. er top of surface c	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F asing. Fill 500	hole and howith heav Pumped illed solid SEC 34 K PAGE 24 escription is necessal to	ole circuly mud at ole to sacks of with central with cent	lated with heach 500 fee of cement on 26	May 20	y mud. As plug push idge. Fil: Welded pla	
feet for each Drill pipe was r s laid down stopped ar bottom of surface le with mud to 26'. er top of surface c Correspondence regarding this	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F asing. (If additional d s well should be addressed	hole and howith heav Pumped I Illed solid SEC 34 K PAGE 24 Rescription is necessal to Nad Mut	y mud at of the second with central second secon	his sheet)	May 20	y mud. As plug pushed pidge. Fill Welded plat	
feet for each Drill pipe was r s laid down stopped ex bottom of surface le with mud to 26'. Fer top of surface c	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F asing. (If additional d s well should be addressed	hole and howith heav Pumped Illed solid SEC 24 K PAGE 74 K PAGE 74 Ito. Nad Mut	ole circuly mud at on the sacks of the central sacks of the central sacks of the sa	his sheet) men, Tulsa, , ss.	neavy rotar ot. Bridge a top of br to 6'. MAY 20 5-20 Oklahoma	y mud. As plug pushed plug plug pushed plu	
Correspondence regarding this late of the contract of the cont	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F asing. (If additional d s well should be addressed	hole and howith heav Pumped Illed solid FEC 34 K PAGE 24 K PAGE 24 Mut Y OF TUI	y mud at of the sacks of the sa	his sheet) men, Tulsa, ce) or (owner or o	neavy rotar ot. Bridge top of br to 6'. Oklahoma operator) of the	y mud. As plug pushed plug pus	
Correspondence regarding this rest duly sworn on oath, say	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F asing. (If additional d s well should be addressed set to the country of the count	hole and howith heav Pumped illed solid FEC 34 K PAGE 24 K PAGE 24 Mut Y OF TUI ge of the facts,	y mud at of the sacks of the sa	his sheet) men, Tulsa, ce) or (owner or o	neavy rotar ot. Bridge top of br to 6'. Oklahoma operator) of the	y mud. As plug pushed plug pus	
Correspondence regarding thidress	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F asing. (If additional d s well should be addressed set to the country of the count	hole and howith heav Pumped illed solid SEC 34 K PAGE 24 K PAGE 24 Ito Nad Mut Y OF TUL (enge of the facts, et. So help me	y mud at of the sacks of the sa	his sheet) man ing, Tulsa, ss. er) or (owner or or or or matters herein	neavy rotar ot. Bridge top of br to 6'. Oklahoma operator) of the	y mud. As plug pushed plug pus	
Correspondence regarding thidress	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F asing. (If additional d s well should be addressed set to the country of the count	hole and howith heav Pumped illed solid FEC 34 K PAGE 24 K PAGE 24 Mut Y OF TUI ge of the facts,	y mud at of the sacks of the sa	his sheet) man ing, Tulsa, ss. er) or (owner or or or or matters herein	neavy rotar ot. Bridge top of br to 6'. Oklahoma operator) of the	y mud. As plug pushed plug pus	
feet for each Drill pipe was r as laid down stopped ear bottom of surface le with mud to 26'. For top of surface c	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F asing. (If additional d s well should be addressed set to the country of the count	hole and howith heav Pumped illed solid SEC 34 K PAGE 24 K PAGE 24 Ito Nad Mut Y OF TUL (enge of the facts, et. So help me	y mud at of the sacks of the sa	his sheet) man ing, Tulsa, ss. er) or (owner or or or or matters herein	neavy rotar ot. Bridge top of br to 6'. Oklahoma operator) of the	y mud. As plug pushed plug pus	
Correspondence regarding this dress. Correspondence regarding this dress. Correspondence regarding this dress. Correspondence regarding this dress.	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F asing. (If additional d is well should be addressed ye. COUNT ye: That I have knowled e same are true and corre	hole and howith heaver with heaver pumped illed solid	with centry, use BACK of tel & Gussiual Build: SA ployee of own statements, an God.	his sheet) men Tulsa, er) or (owner or of matters herein	Delahoma Oklahoma Oklahoma Oklahoma	above-described the log of the ab	
Correspondence regarding this late of the control of surface control o	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F asing. (If additional d is well should be addressed ye. COUNT ye: That I have knowled e same are true and corre	hole and howith heaver with heaver pumped illed solid	y mud at of the sacks of the sa	his sheet) men Tulsa, er) or (owner or of matters herein	Delahoma	above-described the log of the ab	
Correspondence regarding this last duly sworn on oath, say ribed well as filed and that the	plug set. un to bottom of and filled hole e casing at 635' Set bridge. F asing. (If additional d is well should be addressed ye. COUNT ye: That I have knowled e same are true and corre	hole and howith heaver with heaver pumped illed solid	with centry, use BACK of tel & Gussiual Build: SA ployee of own statements, an God.	his sheet) men Tulsa, er) or (owner or of matters herein	Delahoma Oklahoma Oklahoma Oklahoma	above-described the log of the ab	