State of Kansas



## State Corporation Commission

## CONSERVATION DIVISION

(Oil, Gas and Water) 245 North Water WICHITA, KANSAS, 67202

VERBAL PERMIT FORM
(To Be Filed By Plugging Agent)

Received 6-26-78

J. Lewis Brock Administrator 245 North Water Wichita, Kansas 67202

Dear Sir:

date requested permission to plug the following described well:  Mr. Draper guarantees payment of the plugging fee.  Operator's full Name: Isern Petreleum Co.  Complete Address: Bex 486 Ellinwood, Kansas 67526  Lease Name: Bartlett Well No. 1  Location: NE SE SW Sec. 29 Twp. 10 Rge. 15 (W) (W)  County: Osborne Total Depth 3676' Oil Well  Gas Well Input Well SWD Well D & A X Lost Hole  Mr. Draper was instructed to plug the well as follow  Fill hele with mud and spot 50 sx cement at 500'.  Fill hele with mud and spot 25 sx cement at 240'.  Fill hele with mud to 40' % ½ sx hulls, plug, % 10 sx	<b>;</b>
Operator's full Name: Isern Petroleum Co.  Complete Address: Box 486 Ellinwood, Kansas 67526  Lease Name: Bartlett Well No. 1  Location: NE SE SW Sec. 29 Twp. 10 Rge. 15 (W) (W)  County: Osborne Total Depth 3676' Oil Well  Gas Well Input Well SWD Well D & A X Lost Hole  Mr. Draper was instructed to plug the well as follow  Fill hole with mud and spot 50 sx cement at 500'.  Fill hole with mud and spot 25 sx cement at 240'.	
Complete Address: Box 486 Ellinwood, Kansas 67526  Lease Name: Bartlett	
Lease Name: Bartlett Well No. 1  Location: NE SE SW Sec. 29 Twp. 10 Rge. 15 (W) (W)  County: Osberne Total Depth 3676' Oil Well  Gas Well Input Well SWD Well D & A X Lost Hole  Mr. Draper was instructed to plug the well as follow  Fill hele with mud and spet 50 sx cement at 500'.  Fill hele with mud and spet 25 sx cement at 240'.	
Location: NE SE SW  Sec. 29 Twp. 10 Rge.15 (W) (W)  County: Osberne  Total Depth 3676' Oil Well  Gas Well Input Well SWD Well D & A X Lost Hole  Mr. Draper was instructed to plug the well as follow  Fill hele with mud and spot 50 sx cement at 500'.  Fill hele with mud and spot 25 sx cement at 240'.	CO-MOTIFICATION
County: Osberne Total Depth 3676' Oil Well  Gas Well Input Well SWD Well D & A X Lost Hole  Mr. Draper was instructed to plug the well as follow  Fill hele with mud and spet 50 sx cement at 500'.  Fill hele with mud and spet 25 sx cement at 240'.	
Gas Well Input Well SWD Well D & A X Lost Hole  Mr. Draper was instructed to plug the well as follow  Fill hele with mud and spot 50 sx cement at 500'.  Fill hele with mud and spot 25 sx cement at 240'.	Χ.
Mr. Draper was instructed to plug the well as follow Fill hele with mud and spot 50 sx cement at 500'.  Fill hele with mud and spot 25 sx cement at 240'.	
Fill hole with mud and spot 50 sx cement at 500'.  Fill hole with mud and spot 25 sx cement at 240'.	
Fill hole with mud and spot 25 sx cement at 240'.	s:
Fill hole with mud to 40' % ½ sx hulls, plug, % 10 sz	
And the second s	cem
2 sx cement in rat hele	Manage supplement
257' of 8 5/8" surface casing cement circ.	Marin EAGOAD

Very truly yours,

Conservation Division Agent