

P

Form CP-3
Rev. 6-4-68

KANSAS

STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

FEB 17 1978
2-17-78

J. Lewis Brock
Administrator
245 North Water
Wichita, KS 67202

API Number 15 -141-20,036-00-00 (of this well)

Operator's Full Name Crude Producers, Inc.

Complete Address P. O. Box 55, Russell, Kansas 67665

Lease Name E. E. Beck Well No. 1

Location ^{SW NE} SE 1/4 Sec. 20 Twp. 10 Rge. 15 ~~XX~~ (W) X

County Osborne Total Depth 3705
3700'

Abandoned Oil Well Gas Well Input Well SWD Well D & A X

Other well as hereafter indicated _____

Plugging Contractor Revlin Drlg., Inc. & Allied Cementing Co.

Address Box 88, Russell, Kansas 67665 License No. _____

Operation Completed: Hour 6:00 PM Day 15 Month 2 Year 1978

The above well was plugged as follows:

Filled hole with mud and spotted 40 sx cement at 600'.

Filled hole with mud and spotted 20 sx cement at 240'.

Filled hole with mud to 40' and 1/2 sx hulls, plug, and
10 sx cement to bottom of celler.

2 sx cement in rat hole.

244' of 8 5/8" surface casing cement circ.

I hereby certify that the above well was plugged as herein stated.

... VOICED

Signed: *Deanna Rankin*
Well Plugging Supervisor

DATE 2-17-78
INV. NO. 6778-64



State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)
245 North Water
WICHITA, KANSAS 67202

VERBAL PERMIT FORM
(To Be Filed By Plugging Agent)

RECEIVED
STATE CORPORATION COMMISSION
FEB 17 1968
2-17-78
CONSERVATION DIVISION
WICHITA, KANSAS

J. Lewis Brock
Administrator
245 North Water
Wichita, Kansas 67202

Dear Sir:

Mr. Lingreen of Revlin Drlg. Inc. has this date requested permission to plug the following described well:

Mr. Lingreen guarantees payment of the plugging fee.

Operator's full Name: Crude Producers, Inc.

Complete Address: P. O. Box 55, Russell, Kansas 67665

Lease Name: E. E. Beck Well No. 1

SW NE
Location: SE/4 Sec. 20 Twp. 10 Rge. 15 (R) (W) X

County: Osborne Total Depth 3705 3700' Oil Well

Gas Well Input Well SWD Well D & A X Lost Hole

Mr. Lingreen was instructed to plug the well as follows:

Fill hole with mud and spot 40 sx cement at 600'.

Fill hole with mud and spot 20 sx cement at 240'.

Fill hole with mud to 40' & 1/2 sx hulls, plug, & 10 sx cem.

2 sx cement in rat hole.

244' of 8 5/8" surface casing cement circ.

Very truly yours,

Dwain Rankin
Conservation Division Agent