STATE OF KANSAS TE CORPORATION COMMISSION

Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Cornoration Commission

NSERVATION BIVISIOH Wichita, Kanaca

WELL PLUGGING RECORD

NORTH	Location as "N	NE/CNW%SW%	or footage fron	n imesow/	SEAME		
	Lease Owner_	Lease Owner Temple Brilling Company, Inc. Lohmann + Johnson					
	Lease Name_	H. C. Nels	son	· · ·		Well No. 1	
	Office Address 511 W. 20th. Hays, Kansas						
	Date well con		······································			1	
	Application for	r plugging filed	yes		,]	
	Application for	Application for plugging approved Yes 1					
	Plugging commenced 7-27- 19						
	Plugging completed 7-30- 19						
	Reason for aba	andonment of we	ell or producing	formation			
		<u> </u>					
						1	
Locate well correctly on above				tion Division	or its agents befor	e plugging wa	
Section Plat		уе					
Name of Conservation Agent who su							
Producing formation			Bottom_		Total Depth of V	Vell_3530_	
Show depth and thickness of all wat	ter, oil and gas formatio	ns.					
OIL, GAS OR WATER RECO	RDS				C	ASING RECO	
FORMATION	CONTENT	EDGY	T T				
PURMATION	SUNIENI	FROM	ТО	SIZE	PUT IN	PULLED OU	
		-	+	<u>5a"</u>	shot at	25201	
		 	+				
							
		+	1		_		
	 		1				
		 	1		-	··	
		 	+			···	
	<u> </u>						
Measured into The Plugging starter Plugged off both shot 5 to 300 and with heavy mid	d 7-27-56. Fin tom with sand t at 2520'. Pul set permanent	o 3490* an led pipe c rock bridg	d dumped but of hole e. Dumped	and plu 1 20 sack	ги ГГөн бөрр	th heavy	
Plugging started Plugged off both shot 5 to 300 and	0 3530°. d 7-27-56. Fin tom with sand t at 2520°. Pul set permanent	o 3490* an led pipe c rock bridg	d dumped but of hole e. Dumped	and plu 1 20 sack	ги ГГөн бөрр	th heavy	
Plugging started Plugged off both shot 5 to 300 and	0 3530°. d 7-27-56. Fin tom with sand t at 2520°. Pul set permanent	o 3490* an led pipe c rock bridg	d dumped but of hole e. Dumped	and plu 1 20 sack	ги ГГөн бөрр	th heavy	
Plugging started Plugged off both shot 5 to 300 and	0 3530°. d 7-27-56. Fin tom with sand t at 2520°. Pul set permanent	o 3490* an led pipe c rock bridg	d dumped but of hole e. Dumped	and plu 1 20 sack	ги ГГөн бөрр	th heavy	
Plugging started Plugged off both shot 5 to 300 and	0 3530°. d 7-27-56. Fin tom with sand t at 2520°. Pul set permanent	o 3490* an led pipe c rock bridg	d dumped but of hole e. Dumped	and plu 1 20 sack	ги ГГөн бөрр	th heavy	
Plugging started Plugged off both shot 5 to 300 and	0 3530°. d 7-27-56. Fin tom with sand t at 2520°. Pul set permanent	o 3490* an led pipe c rock bridg	d dumped but of hole e. Dumped	and plu 1 20 sack	ги ГГөн бөрр	th heavy	
Plugging started Plugged off both shot 5 to 300 and	0 3530°. d 7-27-56. Fin tom with sand t at 2520°. Pul set permanent	o 3490* an led pipe c rock bridg	d dumped but of hole e. Dumped	and plu 1 20 sack	ги ГГөн бөрр	th heavy	
Plugging started Plugged off both shot 5 to 300 and	0 3530°. d 7-27-56. Fin tom with sand t at 2520°. Pul set permanent	o 3490* an led pipe c rock bridg	d dumped but of hole e. Dumped	and plu 1 20 sack	ги ГГөн бөрр	th heavy	
Plugging started Plugged off both shot 5 to 300 and	0 3530°. d 7-27-56. Fin tom with sand t at 2520°. Pul set permanent	o 3490* an led pipe c rock bridg	d dumped but of hole e. Dumped	and plu 1 20 sack	ги ГГөн бөрр	th heavy	
Plugging started Plugged off both shot 5 to 300 and	0 3530°. d 7-27-56. Fin tom with sand t at 2520°. Pul set permanent	o 3490* an led pipe c rock bridg	d dumped but of hole e. Dumped	and plu 1 20 sack	ги ГГөн бөрр	th heavy	
Plugging started Plugged off both shot 5 to 300 and	0 3530°. d 7-27-56. Fin tom with sand t at 2520°. Pul set permanent	o 3490* an led pipe c rock bridg	d dumped but of hole e. Dumped	and plu 1 20 sack	ги ГГөн бөрр	th heavy	
Plugging started Plugged off both shot 5 to 300 and	0 3530°. d 7-27-56. Fin tom with sand t at 2520°. Pul set permanent	o 3490* an led pipe c rock bridg	d dumped but of hole e. Dumped	and plu 1 20 sack	ги ГГөн бөрр	th heavy	
Plugging started Plugged off both shot 5 to 300 and	0 3530. d 7-27-56. Fin tom with sand t at 2520. Pul set permanent to 35. and mixe	o 3490° an led pipe c rock bridg d 10 sacks	d dumped but of hole e. Dumped for cap o	e and plu 1 20 sack on well.	ги ГГөн бөрр	th heavy	
Plugging started Plugged off both shot 5 to 300 and	0 3530. d 7-27-56. Fin tom with sand t at 2520. Pul set permanent to 35. and mixe	led pipe c rock bridg d 10 sacks	d dumped by ut of hole e. Dumped for cap o	e and plud 20 sack on woll.	gged well wi	th heavy	
Plugging started Plugged off both shot 5 to casing gind to 300 and writh heavy mid	0 3530 d 7-27-56. Fin tom with sand tat 2520 Pul set permanent to 35 and mixe	led pipe or rock bridged 10 sacks I description is need /b/a Forbe	d dumped by ut of hole e. Dumped for cap of ssary, use BACK of s Casing P	e and plud 20 sack on woll.	gged well wi	th heavy	
Plugging started Plugged off both shot 5½" casing good to 300 and writh heavy mid Name of Plugging Contractor	0 3530: d 7-27-56. Fin tom with sand t at 2520: Pul set permanent to 35! and mixe (If additiona	led pipe or rock bridged 10 sacks I description is need /b/a Forbe	d dumped by ut of hole e. Dumped for cap of ssary, use BACK of s Casing P	e and plud 20 sack on woll.	gged well wi	th heavy	
Plugging started Plugged off both shot 5½" casing gind to 300° and writh heavy mid	0 3530°. d 7-27-56. Fin tom with sand t at 2520°. Pul set permanent to 35° and mixe (If additiona J. O. Forbes d Box 221, Great	led pipe or rock bridged 10 sacks I description is need by a Forbe Bend, Kan	d dumped by ut of hole e. Dumped for cap of ssary, use BACK of s Casing P	e and plud 20 sack on woll.	gged well wi	th heavy	
Plugging started Plugged off both shot 5½" casing good to 300 and writh heavy mid Name of Plugging Contractor	0 3530°. d 7-27-56. Fin tom with sand t at 2520°. Pul set permanent to 35° and mixe (If additiona J. O. Forbes d Box 221, Great	led pipe or rock bridged 10 sacks I description is nece /b/a Forber Bend, Kan	d dumped by ut of hole e. Dumped for cap of sessary, use BACK of s Casing P sas	f this sheet)	ompany , ss.	th heavy	
Plugging started Plugged off both Shot 5 to casing gind to 300 and writh heavy mid Name of Plugging Contractor Address	O 3530'. d 7-27-56. Fin tom with sand t at 2520'. Pul set permanent to 35' and mixe (If additiona J. O. Forbes d Box 221, Great , COU	led pipe or rock bridged 10 sacks I description is neceed by a Forber Bend, Kan	d dumped by ut of hole e. Dumped for cap of ssary, use BACK of s Casing P sas employee of ow	f this sheet) vulling (company , ss. ner or operator) of	th heavy illed ho	
Plugging started Plugged off both shot 5 to casing gind to 300 and writh heavy mid writh heavy mid started of Plugging Contractor. Address STATE OF STATE	O 3530: d 7-27-56. Fin tom with sand t at 2520: Pul set permanent to 35' and mixe (If additiona J. O. Forbes d Box 221, Great , COU	led pipe or rock bridged 10 sacks I description is need by a Forbe Bend, Kan UNTY OF	d dumped by ut of hole e. Dumped for cap of for cap of sasy, use BACK of s Casing P sas employee of ow facts, statement	f this sheet) vulling (company , ss. ner or operator) of	th heavy illed ho	
Plugging started Plugged off both Shot 5 to casing gind to 300 and writh heavy mid Name of Plugging Contractor Address	O 3530: d 7-27-56. Fin tom with sand t at 2520: Pul set permanent to 35' and mixe (If additiona J. O. Forbes d Box 221, Great , COU	led pipe or rock bridged 10 sacks I description is need by a Forbe Bend, Kan UNTY OF	d dumped by ut of hole e. Dumped for cap of for cap of sasy, use BACK of s Casing P sas employee of ow facts, statement	f this sheet) vulling (company , ss. ner or operator) of	th heavy illed ho	
Plugging started Plugged off both shot 5 to casing gind to 300 and writh heavy mid writh heavy mid started of Plugging Contractor. Address STATE OF STATE	O 3530: d 7-27-56. Fin tom with sand t at 2520: Pul set permanent to 35' and mixe (If additiona J. O. Forbes d Box 221, Great , COU	led pipe or rock bridged 10 sacks I description is need by a Forbe Bend, Kan UNTY OF	d dumped by ut of hole e. Dumped for cap of for cap of sasy, use BACK of s Casing P sas employee of ow facts, statement	f this sheet) vulling (company , ss. ner or operator) of	th heavy illed ho	
Plugging started Plugged off both shot 5 to casing gind to 300 and writh heavy mid writh heavy mid started of Plugging Contractor. Address STATE OF STATE	O 3530: d 7-27-56. Fin tom with sand t at 2520: Pul set permanent to 35' and mixe (If additiona J. O. Forbes d Box 221, Great , COU	led pipe or rock bridged 10 sacks I description is necedity to the lead of the lead of the lead correct. Second control of the lead correct.	d dumped by ut of hole e. Dumped for cap of for cap of sasy, use BACK of s Casing P sas employee of ow facts, statement	f this sheet) vulling (company , ss. ner or operator) of	th heavy illed ho	
Plugging started Plugged off both shot 5 to casing gind to 300 and writh heavy mid writh heavy mid started of Plugging Contractor. Address STATE OF STATE	O 3530: d 7-27-56. Fin tom with sand t at 2520: Pul set permanent to 35' and mixe (If additiona J. O. Forbes d Box 221, Great , COU	led pipe or rock bridged 10 sacks I description is necedity to the lead of the lead of the lead correct. Second control of the lead correct.	d dumped by ut of hole e. Dumped for cap of for cap of sasy, use BACK of s Casing P sas employee of ow facts, statement	f this sheet) vulling (company , ss. ner or operator) of	th heavy illed ho	
Plugging started Plugged off both shot 5 to casing gind to 300 and writh heavy mid writh heavy mid started of Plugging Contractor. Address STATE OF STATE	O 3530° d 7-27-56. Fin tom with sand to at 2520°. Pull set permanent to 35° and mixed to 35	I description is necederal form of the control of t	d dumped by ut of hole e. Dumped for cap of for cap of sasy, use BACK of s Casing P sas employee of ow facts, statement	f this sheet) vulling (company , ss. mer or operator) of ers herein contained (Address)	th heavy illed ho	
Plugging started Plugged off both shot 5½" casing gind to 300° and writh heavy mid with heavy mid started for the short started for	O 3530° d 7-27-56. Fin tom with sand to at 2520°. Pull set permanent to 35° and mixed to 35	led pipe or rock bridged 10 sacks I description is nece /b/a Forbe Bend, Kan UNTY OF	d dumped by ut of hole e. Dumped for cap of for cap of sasy, use BACK of s Casing P sas employee of ow facts, statement	f this sheet) vulling (Company , ss. mer or operator) of ers herein contained	th heavy illed ho	
Plugging started Plugged off both shot 5½ casing gind to 300 and writh heavy mid with heavy mid started of Plugging Contractor. Address STATE OF Started well, being first duly sworn on oath above-described well as filed and the Subscribed well as filed and the s	of 7-27-56. Fin tom with sand to at 2520. Pull set permanent to 35! and mixed and to 35! and mixed are true at the same are true are fore me this.	led pipe or rock bridged 10 sacks I description is nece /b/a Forbe Bend, Kan UNTY OF	d dumped by ut of hole e. Dumped for cap of for cap of sasy, use BACK of s Casing P sas employee of ow facts, statement	f this sheet) vulling (company , ss. mer or operator) of ers herein contained (Address)	th heavy illed ho	
Plugging started Plugged off both shot 5½ casing gind to 300 and writh heavy mid with heavy mid started of Plugging Contractor. Address STATE OF Started well, being first duly sworn on oath above-described well as filed and the Subscribed well as filed and the s	O 3530° d 7-27-56. Fin tom with sand to at 2520°. Pull set permanent to 35° and mixed to 35	led pipe or rock bridged 10 sacks I description is nece /b/a Forbe Bend, Kan UNTY OF	d dumped by ut of hole e. Dumped for cap of for cap of sasy, use BACK of s Casing P sas employee of ow facts, statement	f this sheet) vulling (company , ss. mer or operator) of ers herein contained (Address)	th heavy illed ho	
Plugging started Plugged off both shot 5 to casing gind to 300 and writh heavy mid with heavy mid started by the short of Plugging Contractor. Address STATE OF Subscribed well as filed and the shove-described well as filed and the showe-described well as file	of 7-27-56. Fin tom with sand to at 2520. Pull set permanent to 35! and mixed and to 35! and mixed are true at the same are true are fore me this.	led pipe or rock bridged 10 sacks I description is nece /b/a Forbe Bend, Kan UNTY OF	d dumped by ut of hole e. Dumped for cap of for cap of sasy, use BACK of s Casing P sas employee of ow facts, statement	f this sheet) vulling (company , ss. mer or operator) of ers herein contained (Address)	th heavy illed ho	
Plugging started Plugged off both Shot 5 casing gind to 300 and writh heavy mid with heavy mid well, being first duly sworn on oath above-described well as filed and the Subscribed well as filed and	of 3530° do 7-27-56. Find tom with sand to at 2520°. Pull set permanent to 35° and mixed and mixed at 221. Great g	led pipe or rock bridged 10 sacks I description is need /b/a Forbet Bend, Kan UNTY OF (nowledge of the nd correct. Second correct.	d dumped by ut of hole e. Dumped for cap of for cap of sessary, use BACK of s Casing P sas employee of ow facts, statement help me God.	f this sheet) vulling (company , ss. mer or operator) of ers herein contained (Address)	th heavy illed ho	
Plugging started Plugged off both shot 5th casing find to 300 and writh heavy mid with heavy mid started by the short of t	of 3530° do 7-27-56. Find tom with sand to at 2520°. Pull set permanent to 35° and mixed and mixed at 221. Great g	led pipe or rock bridged 10 sacks I description is nece /b/a Forbe Bend, Kan UNTY OF	d dumped by ut of hole e. Dumped for cap of for cap of sessary, use BACK of s Casing P sas employee of ow facts, statement help me God.	f this sheet) vulling (company , ss. mer or operator) of ers herein contained (Address)	th heavy illed ho	
Plugging started Plugged off both Shot 5 casing gind to 300 and writh heavy mid with heavy mid well, being first duly sworn on oath above-described well as filed and the Subscribed well as filed and	O 3530° d 7-27-56. Fin tom with sand to at 2520°. Pull set permanent to 35° and mixed Box 221. Great permanent to 35° and mixed to 35° and mix	led pipe or rock bridged 10 sacks I description is need /b/a Forbet Bend, Kan UNTY OF (nowledge of the nd correct. Second correct.	d dumped by the tof hole e. Dumped for cap of for cap of sas employee of ow facts, statement help me God.	f this sheet) vulling (company , ss. mer or operator) of ers herein contained (Address)	th heavy illed ho	