RECEIVED FEB 1 7 2006

Operator: License # 3293

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

API No. 15 - 065-23088-00-00

ORIGINAL

Form ACO-1 September 1999 Form Must Be Typed

KCC WICHITA WELL COMPLETION FORM WELL HISTORY - DESCRIPTION OF WELL & LEASE

| Name: Russell Oil, Inc. | County: Graham |
|--|---|
| Address: PO Box 1469 | E/2 - E/2 - SW - SE Sec. 13 Twp. 10 S. R. 23 ☐ East West |
| City/State/Zip: Plainfield, IL 60544 | 720 feet from S / (circle one) Line of Section |
| Purchaser: NA | 1470 feet from (E) W (circle one) Line of Section |
| Operator Contact Person: LeRoy Holt II | Footages Calculated from Nearest Outside Section Corner: |
| Phone: (_815) _609-7000 | (circle one) NE SE NW SW |
| Contractor: Name: Shields Oil Producers | Lease Name: Amyx Well #: #1-13 |
| License: 5184 | Field Name: Wildcat |
| Wellsite Geologist: Todd Morgenstern | Producing Formation: NA |
| Designate Type of Completion: | Elevation: Ground: 2353' Kelly Bushing: 2358' |
| New Well Re-Entry Workover | Total Depth: 4100' Plug Back Total Depth: |
| Oil SWD SIOW Temp. Abd. | Amount of Surface Pipe Set and Cemented at 234 Feet |
| Gas ENHR SIGW | Multiple Stage Cementing Collar Used? |
| Dry Other (Core, WSW, Expl., Cathodic, etc) | If yes, show depth setFeet |
| If Workover/Re-entry: Old Well Info as follows: | If Alternate II completion, cement circulated from |
| Operator: | feet depth tosx cmt. |
| Well Name: | 10/0/0 |
| Original Comp. Date: Original Total Depth: | Drilling Fluid Management Pfard (Data must be collected from the Reserve Pit) |
| Deepening Re-perf Conv. to Enhr./SWD | Chloride content 2000 ppm Fluid volume 585 bbls |
| Plug Back Plug Back Total Depth | Dewatering method used evaporation |
| Commingled Docket No | |
| Dual Completion Docket No | Location of fluid disposal if hauled offsite: |
| Other (SWD or Enhr.?) Docket No | Operator Name: |
| 9-1-2005 9-8-2005 9-8-2005 | Lease Name: License No.: 3293 |
| Spud Date or Date Reached TD Completion Date or | Quarter Sec TwpS. R 🔲 East 🗸 West |
| Recompletion Date Recompletion Date | County: Docket No.: |
| | |
| Kansas 67202, within 120 days of the spud date, recompletion, workow Information of side two of this form will be held confidential for a period of | the Kansas Corporation Commission, 130 S. Market - Room 2078, Wichita, er or conversion of a well. Rule 82-3-130, 82-3-106 and 82-3-107 apply. 12 months if requested in writing and submitted with the form (see rule 82-3-130) and geologist well report shall be attached with this form. ALL CEMENTING Submit CP-111 form with all temporarily abandoned wells. |
| | ate the oil and gas industry have been fully complied with and the statements |
| herein are complete and correct to the best of my knowledge. | |
| Signature: Grandely slove | KCC Office Use ONLY |
| Title: President Date: 2-14-2006 | Letter of Confidentiality Received |
| With Tabala | If Denied, Yes Date: |
| Subscribed and sworn to before me this 14 day of PEDEW | Wireline Log Received |
| $O_{0} \longrightarrow U_{0}$ | Geologist Report Received |
| Notary Public: Page 1770 | |
| Date Commission Expires: 7/23/2008 NOTICE | SEAL UIC Distribution |
| MY COLARISCIC. 11. | 74T: OF ILLINOIS |
| The state of the s | ************************************** |

Side Two

| Operator Name: Russe | eli Oli, inc. | | Lease I | Name: Amy | yx | | Well #: _#1- | 13 | |
|--|---|--|---------------------------------|--|--------------------|--------------------------------|------------------|--------------|--------|
| Sec. 13 Twp. 10 | | | County: | Graham | | | | | |
| tested, time tool open temperature, fluid reco | and closed, flowir very, and flow rate | and base of formations ng and shut-in pressures es if gas to surface test, final geological well site | , whether shu along with fir | ut-in pressu | ure reached | d static level, hydr | ostatic pressu | res, botto | m hole |
| Drill Stem Tests Taken (Attach Additional St | | ✓ Yes No | | √ Log | Forma | tion (Top), Depth | and Datum | | Sampl |
| Samples Sent to Geole | · | Yes No | | Name | ahad aaala | alat manant | Тор | | Datum |
| Cores Taken | ogioui ourroy | ☐ Yes ✓ No | | | _ | ogist report tion listings. | | | |
| Electric Log Run | | ✓ Yes No | | ioi comp | ocic iornia | don natings. | | | |
| (Submit Copy) | | | | | | | RECE | EIVE | |
| List All E. Logs Run: | | | | | | | FEB 1 | 7 2000 | • |
| CNL-CDL, DIL | , MEL, BHC | S | | | | | KCCW | | |
| | | CASING Report all strings set | G RECORD -conductor, sur | ✓ New face, interme | Used ediate, produ | ection, etc. | | | |
| Purpose of String | Size Hole Drilled | Size Casing Set (In O.D.) | Weigl | | Setting Depth | Type of Cement | # Sacks Used | | and Pe |
| Surface | 12 1/4 | 8 5/8" | 23# | 23 | 34' | 60/40 poz | 200 | 3% сс, | , 2% g |
| | | | | | | | | | |
| | | | | | | | | | |
| | | ADDITIONA | L CEMENTIN | G / SQUEE | ZE RECOF | RD | | | |
| Purpose: Perforate | Depth Top Bottom | Type of Cement | #Sacks \ | Jsed | | Type and | Percent Additive | es . | |
| Protect Casing Plug Back TD Plug Off Zone | | | | | | | | | |
| | | | | | | | | | - |
| Shots Per Foot | ugs Set/Type erforated | | | racture, Shot, Cemer Amount and Kind of M | | ord | De | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| TUBING RECORD | Size | Set At | Packer At | L | iner Run | Yes N | o . | | |
| Date of First, Resumerd | Production, SWD or | Enhr. Producing Me | ethod | Flowing | Pum | ping Gas L | ift Ott | ner (Explair | 1) |
| Estimated Production | Oil | Bbls. Gas | Mcf | Water | | Bbls. | Gas-Oil Ratio | | Gra |

TREATMENT REPORT

| Continuer D Continuer D Continuer D Continuer D Continuer Russel Oil Lease No. West 1-13 Find Control Find Co | | | | (| . | | | | | <u></u> | | | | |
|--|-------------|-------------|--|--|-------------|--|---------------|--|---------------------|--------------|---------------------------|------------------|---------------------------------------|--|
| Continued Russes Oil | <u>Q.</u> | | , | • | = | الو عليه | | (| TREA | TMENTR | EPORT | | | |
| Comparison Com | jæ | \ | | | | | _ | | | Dete | 0 - | | | |
| Comparison Com | | | | | Cus | storner | Pussel | 1011 | | 1 - | 8-C | 5 | | |
| PIPE DATA PERFORATING PERFORMANCE PERFORATION DATA PERFORATION | | | | | Les | A P | √MX | 15-4 | | | | 1-1 | | |
| PREPARA PERFORATING DATA FLUID USED TRAINER RESUME PIPE DATA PROBLEM PROBLEM TO 13.3.2 + 1/6.1.3.2 oct. 1.5 oc | 10795 | Station | Pratt | | | | 472" | | | Gra Gra | | | TS. | |
| Trucking local Property of the | Ceme | nt-Plu | | | | | | L | | | 13-105 | <u>-23W</u> | | |
| Volume Max Press Max Press From To Max Max Promote To Plant To Plant To Plant To Plant To Plant To Station Manager To | | | | | NG DAT | ΓΑ | | | | | | | | |
| Volume Prices Man Prices Prices To Rece Ang 15 Man. Vivia Copyrisation Annalism Vol. From To To Push Prices Price | | | Shourt | | | | 20050 | 2005 acts 60140 Poz with 68 Ge 18 44 #1 Str Ce | | | | | Te | |
| Truck Truc | | | From | | To | | 13.32+ | t/Gal., 8. | 09Gal | 15/2. 1.59cl | ft./sk. | <u> </u> | | |
| Time Processor | | | | | То | | | | | Avg | | | | |
| Customer Representative Burt Beery Station Manager Dave Scott Treatment Representative Burt Beery Station Manager Dave Scott Treatment Representative Burt Beery Service Units Time F.M. Presente Products Babb. Pumped Rate Trucktsen location and held Safety Meeting 19th Plug 25 sackts at 1925' 2:00 300 5 Start Fresh H.O. Pre-Flush 2:04 300 27 5 Start Must Displacement 2:40 225 5 Start Fresh H.O. Pre-Flush 3:20 200 5 Start Fresh H.O. Pre-Flush 3:21 200 5 Start Fresh H.O. Pre-Flush 3:22 200 5 Start Fresh H.O. Pre-Flush 3:23 200 5 Start Fresh H.O. Pre-Flush 3:23 200 5 Start Fresh H.O. Pre-Flush 3:23 200 16 5 Start Fresh H.O. Displacement 4:30 4 2 Fill Surface Pipe with Cement 4:30 4 2 Plug rathole with 15 sackts cement 5:00 KCCWICHTT/ Trucktsen location and held Safety Meeting Trucktsen location and held Safety Meeting Service Log Trucktsen location and held Safety Meeting Trucktsen location and held Safety Meeting Service Log Trucktsen location and held Safety Meeting Trucktsen location and held Safety Meeting Service Log Trucktsen location and held Safety Meeting T | | | From | | То | | | | | HHP Used | _ | Annulus Pressure | | |
| Customer Representation Britisher Manager Dave Scott Truction of the Casaing Trubing The Preseure Blobs. Pumped Rate Truction location and hold Safety meeting 134 Plug 25 sacts at 1925' 2:00 300 5 Start Fresh H.O. Pre-Flush 2:06 300 27 5 Start Mix 25 sacts seement 2:06 300 27 5 Start Fresh H.O. Pre-Flush 2:06 300 27 5 Start Fresh H.O. Pre-Flush 2:06 300 27 5 Start Fresh H.O. Pre-Flush 2:07 Plug 100 sacts cement 2:08 25 5 Start Fresh H.O. Pre-Flush 2:44 225 5 Start Fresh H.O. Pre-Flush 2:44 225 5 Start Fresh H.O. Pre-Flush 2:44 225 5 Start Fresh H.O. Pre-Flush 3:20 200 5 Start Fresh H.O. Pre-Flush 3:20 200 5 Start Fresh H.O. Pre-Flush 3:21 200 5 Start Fresh H.O. Pre-Flush 3:22 200 5 Start Fresh H.O. Pre-Flush 3:23 200 5 Start Fresh H.O. Displacement 4:30 4 2 Fill Surface Pipe with Comment 4:30 7 Plug 100 sacts at 40' Push weeden plug-dewnwith Irelly 4:30 7 Plug 100 sacts at 40' Push weeden plug-dewnwith Irelly 4:30 8 Plug rathole with 15 sacts cement 4:33 Plug rathole with 15 sacts cement 5:00 KCC-WICHTT/ Tructican location and hold Safety meeting Tructican location and hold Safe | | | From | | То | | Flush | | | Ges Volume | | Total Load | | |
| Time P.M. Procesure Procesure Blob. Pumped Rate Someo Log Tructis on location and hold safety meeting 12:30 Tructis on location and hold safety meeting 13th Plug 25 sacts at 1925' Start Fresh H.O Pre-Flush 2:06 300 27 5 Start Mux 25 sacts cement 2:06 300 27 5 Start Mux 25 sacts cement 2:06 300 27 5 Start Mux Displacement 2** Plug 100 sacts 10 25' 2:40 225 2:40 225 2:40 225 3:20 5 Start Fresh H.O Pre-Flush 3:41 225 3:20 200 5 Start Fresh H.O Fresh Displacement 3** Plug 40 sacts cement 3:27 Plug 10 sacts at 285' 3:20 200 5 Start Fresh H.O Pre-Flush 3:21 200 5 Start Fresh H.O Pre-Flush 3:23 200 16 5 Start Fresh H.O Displacement 4** Y Plug 10 sacts at 40' Push weeden plug down with 15 sacts cement 4:30 4:30 4:30 4:30 4:30 4:30 4:30 4:30 4:30 4:30 4:30 4:30 4:30 4:30 5 CCC WICHITA Tructis on location and hold safety meeting Tructis on location and hold safety meeting 5 Start Fresh H.O Pre-Flush 5 Start Fresh H.O Pre-Flush 2:40 2:50 225 3:40 225 | • • | . 1 | From | | | n Mana | ger D | <u> </u> | | Tregter | <u> </u> | | | |
| Time P. Pressure Pressure Bobs. Pumped Rate Tructise on location and hold Safety Meeting. 1319 Plug 25 sacts at 1925 | | B | urt Bee | | <u> </u> | | Dave | | | Clare | nce K. // | essich | • | |
| Tructisen location and hold Safety Meeting 134 Plug 25 sacts at 1925' 2:00 300 S Start Fresh H.O Pre-Flush 2:06 300 27 S Start Mix 25 sacts cement 2:40 225 S Start Fresh H.O Pre-Flush 2:44 225 20 S Start Fresh H.O Pre-Flush 2:50 225 48 S Start Fresh H.O Pre-Flush 2:50 225 48 S Start Fresh H.O Pre-Flush 2:50 225 48 S Start Fresh H.O Pre-Flush 3:20 200 S Start Fresh H.O Pre-Flush 3:21 200 S Start Fresh H.O Pre-Flush 3:22 200 S Start Fresh H.O Pre-Flush 3:23 200 S Start Fresh H.O Pre-Flush 3:24 200 S Start Fresh H.O Pre-Flush 3:25 200 S Start Fresh H.O Displacement 4:36 RECEIVED 3 2 Plug reshed with 10 suchs cement 4:36 RECEIVED 3 2 Plug mouse hole with 10 suchs cement 4:36 RECEIVED 3 2 Plug mouse hole with 10 suchs cement 5:00 KCC WICHITA Thanks. Clarence R.Messich Thanks. Clarence R.Messich | | Casing | Tubing | | | 26 | | 570 | J | Seni | ne Log | | | |
| 194 Plus 25 sacts at 1925' | |), Pressure | Pressure | Bbls. Pt | umped | - | Rate | | . 1 | | - | 0-4 44 | | |
| S Start Fresh H.O Pre-Flush 2:04 300 2:05 Start Mix 25 such scement 2:06 300 27 S Start Mud Displacement 2:40 225 2:40 225 2:40 225 2:44 225 2:50 225 48 S Start Fresh H.O Pre-Flush 3:20 200 5 Start Fresh H.O Pre-Flush 3:20 200 5 Start Fresh H.O Pre-Flush 3:20 200 5 Start Fresh H.O Pre-Flush 3:21 200 5 Start Fresh H.O Pre-Flush 3:23 200 16 S Start Fresh H.O Pre-Flush 3:23 200 16 S Start Mix 40 sacks ecement 4:77 Plug 10 sacks at 40' Push wooden plug down with Itelly 4:30 4:36 RECEIVED 3 2 Plug rathole with 15 sacks cement Wash up pump truck 5:00 KCC WICHITA Tob Complete Thanks, Clarence R.Messick | 12:30 | | | | | \vdash | | 1 ruch | <u>50010</u> †Di | Carlon and | <u>neia 5a</u> . 1970' | I ery me | ering | |
| 2:04 300 27 5 Start Mix 25 sights cement 2:06 300 27 5 Start Mud Displacement 2°9 Plug 100 sachs at 1025' 2:40 225 5 Start Fresh H.O Pre-Flush 2:50 225 48 5 Start Fresh H.O Flush Displacement 2:50 225 48 5 Start Fresh H.O Flush Displacement 3:20 200 5 Start Fresh H.O Pro-Flush 3:20 200 5 Start Fresh H.O Pro-Flush 3:21 200 5 5 Start Mix 40 sachs accement 3:23 200 16 5 Start Fresh H.O Displacement 4*17 Plug 10 sachs at 40' Push wooden plugdown with Itelly 4:30 3 2 Fill Surface Pipe with cement 4:33 4 2 Plug mouse hole with 15 sachs cement 4:36 RECEIVED 3 2 Plug mouse hole with 10 sachs cement 5:00 KCC WICHITA Then the Messach Complete Thanks, Clarence R. Messich | | | | | | - | ζ | | | | | | | |
| 2:06 300 27 S Start Mud Displacement 2" Plug 100 sacks at 1025' 2:40 225 S Start Fresh H.O Pre-Flush 2:44 225 20 S Start mix 100 sacks cement 2:50 225 48 S Start Fresh H.O Flush Displacement 3:20 200 S Start Fresh H.O Pre-Flush 3:20 200 S Start Fresh H.O Pre-Flush 3:21 200 S S Start mix 40 sacks ecement 3:23 200 I6 S Start Fresh H.O Displacement 4*19 Plug 10 sacks at 40' Push wooden plugdown with Itelly 4:30 3 2 Fill Surface Pipe with cement 4:33 4 2 Plug mouse hole with 15 sacks cement 4:36 RECEIVED 3 2 Plug mouse hole with 10 sacks cement 5:00 KCC WICHITA To Complete Thanks, Clarence R. Messick | | | | 3.0 | | | <u>ر</u> د | T i | | • | | | | |
| 2'40 225 2'40 225 2'44 225 20 5 5 Start Fresh H.O Pre-Flush 2'50 225 48 5 5 Start Fresh H.O Fresh Displacement 2'50 225 3'20 200 5 5 Start Fresh H.O Pre-Flush 3'20 200 5 5 Start Fresh H.O Pre-Flush 3'21 200 5 5 Start Fresh H.O Pre-Flush 3'23 200 6 5 Start Fresh H.O Displacement 3'23 200 6 7 Start Fresh H.O Displacement 4'17 Plug LOSachs at 40' Push wooden plugdown with Itelly 4'30 4'30 7 8 Fill Surface Pipe with cement 4'30 8 Plug rathole with IS sachs coment 4'36 RECEIVED 3 7 Plug mouse hole with IS sachs coment Wash up pump truck 5:00 KCC WICHITA Thanks. Clarence R.Messick | | | | | <u> </u> | | | | | | | | | |
| 2:40 225 2:44 229 20 5 Start Fresh H. O Pre-Flush 2:50 225 48 5 Start Fresh H. O Flush Displacement 3:20 200 3:20 S Start Fresh H. O Flush Displacement 3:21 200 5 Start Fresh H. O Pre-Flush 3:21 200 5 Start Fresh H. O Pre-Flush 3:23 200 16 S Start Mix 40 sacts o Cement 3:23 200 16 S Start Fresh H. O Displacement 4** Y Plug 10 sects at 40' Push wooden plugdown with Itelly 4:30 4:33 4 Plugrathole with 15 sacts coment 4:36 RECEIVED 3 2 Plugrathole with 15 sacts coment Wash up pump trucht 5:00 KCC WICHITA To b Complete Thanks. Clarence R. Messich | | 500 | | | | | | | 4 | | • | 5' | | |
| 2:44 225 2:50 225 48 5 5 Start Fresh H. Offish Displacement 3:20 200 5 5 Start Fresh H. Offish Displacement 3:20 200 5 Start Fresh H. Offish 3:21 200 5 Start Mix 40 sacts occment 3:23 200 16 5 Start Fresh H. O Displacement 4" Plug Losacts at 40' Push wooden plugdown with Itelly 4:30 4:30 4:33 4 2 Plug mouse hole with Issacts coment 4:36 RECEIVED 3 2 Plug mouse hole with Issacts coment Wash up pump truckt 5:00 KCC WICHITA Tob Complete Thanks, Clarence R. Messick | | 225 | | - 7. | | | 5 | | | | | | | |
| 2:50 225 48 5 Start Fresh H. O. Flush Displacement 3:20 200 5 Start Fresh H. O. Pro-Flush 3:21 200 5 Start Mix 40 sacts occment 3:23 200 16 S Start Fresh H. O. Displacement 4:47 Plug 10 sechs at 40' Push wooden plugdown with Itelly 4:30 3 2 Fill Surface Pipe with cement 4:33 4 2 Plug mouse hole with 15 sacts cement 4:36 RECEIVED 3 2 Plug mouse hole with 10 sacts cement FEB 7 2005 Wash up pump truckt 5:00 KCC WICHITA Tob Complete Thanks. Clarence R. Messick | | | | 20 | | | | | | | | | | |
| 3:20 200 5 Start Fresh H.O Pre-Flush 3:21 200 5 Start Fresh H.O Displacement 3:23 200 16 S Start Fresh H.O Displacement 4:47 Plug Losachs at 40' Push wooden plugdown with Itelly 4:30 4:33 4 2 Plug rathole with Issachs cement 4:36 RECEIVED 3 2 Plug mouse hole with Issachs cement FEB 72005 KCC WICHITA Thanks, Clarence R. Messich | | | | 1 | | | | 1 | | • | | | | |
| 5 Start Fresh Ho Pre-Flush 3.21 200 5 S Start Mix 40 sacts occment 3:23 200 16 S Start Fresh Ho Displacement 20 4th Plug 10 sects at 40' Push wooden plugdown with Itelly 4:30 3 2 Fill Surface Pipe with cement 4:33 4 2 Plugrathole with 15 sacts coment 4:36 RECEIVED 3 2 Plug mouse hole with 10 suchs cement Wash up pump truckt 5:00 KCC WICHIT! Thanks. Clarence R. Messick | _ | | | | | | | | | | | | | |
| 3:23 200 16 5 5 5 5 5 5 5 5 5 5 5 5 5 | | 200 | | | | | -5 | | | | | | | |
| 3:23 200 16 5 Start Fresh the Displacement 20 4th Plug Losacts at 40' Push wooden plugdown with Itelly 4:30 3 2 Fill Surface Pipe with cement 4:33 4 2 Plugnathole with Issactscement 4:36 RECEIVED 3 2 Plugnouse hole with Issactscement FEB 72005 Wash up pumpt rucht 5:00 KCC WICHITA Thanks. Clarence R. Messich | | | | 9 | | | S | | | | | | · · · · · · · · · · · · · · · · · · · | |
| 4:30 4:30 4:30 7 Push wooden plugdown with Itelly 4:30 4:33 4 2 Plug at hole with 15 sacts coment 4:36 RECEIVED 3 2 Plug mouse hole with 10 sacts coment Wash up pump tructs 5:00 KCC WICHITA Thanks, Clarence R. Messick | | | | 16 | | | S | Start | | | | | | |
| 4:30 4:33 4 2 Fill Surface Pipe with Cement 4:33 4:36 RECEIVED 3 2 Plug mouse hole with 10 sacks cement FEB 17 2005 5:00 KCCWICHITA Thanks. Clarence R. Messick | | | | 20 |) | | | | | | | | | |
| 4:33 4:36 RECEIVED 3 Plug mouse hole with 15 sacts cement Plug mouse hole with 10 sacts cement Wash up pump truck 5:00 KCC WICHITA Thanks, Clarence R. Messick | | | | | | | | | | • • | | <u>ly</u> | | |
| 4:36 RECEIVED 3 2 Plug mouse hole with loscets cement Wash up pump tructs 5:00 KCC WICHITA Tob Complete Thanks, Clarence R. Messick | 4:30 | | | 3 | | | _ဍ | | | | | - | | |
| FEB 7 2005 Wash up pump truct Tob Complete Thanks, Clarence R. Messick | 4:33 | | | | | | | Plugr | at hole | with 15 Sac | tscomen | <u>f</u> | | |
| 5:00 KCC WICHITA Job Complete Thanks, Clarence R. Messick | 4:36 | RE(| EIVED | 3 | | - | <u>a</u> | | | | | ement | | |
| Thanks, Clarence R. Messick | | FEB | 7 2005 | ļ | | | | | , , | • | · | | | |
| hants. Clarence R. Messick | <u>5:00</u> | KCC | WICHIT | 4 | | - | | 1 Job | Comp | lete | D 44 | . 1 | | |
| | | ' | | 1 | 0040 | | w KO-CT | Th | lants. | Clarence | K./Nessi | 620) 672- | 5383 | |

| | - | | 0 | | | <u></u> | | |
|-----------------|----------------|-----------------------|-------------|-----------------|------------------|--------------------|-------------|-------------|
| <u>Ě</u> | | INVOICE N | Э. | Subles | t to Correction | FIELD | ORDER | 11618/ |
| | | 11618 Date | | Lease | | Well # | Legai | |
| | | 9-1-6 Customer II | 5 | County Y M | <u>X</u> | State | Station | 0c-23w |
| SERV | / C E S , | | | Graham Depth | Formation | Ks | Shoe Joint | |
| c Ru | ssello | iL | | 234 set | e | New wel | 1 15' | <u></u> " |
| H A | | | | Casing S | Casing Depth | 237 | 8-5/8 54 | rface_ |
| R ——— G | | | | Customor Barros | entative | Treater | N F. West | 4 |
| E | | | | Burt B | erry - | | 70 1.004 1. | |
| AFE Number | | PO Number | <u> </u> | Materials | v 13 | A 92 | | |
| | , | | | Received by | X Du | ston P | eery Acco | UNTING |
| Product Code | QUANTITY | MATERIAL, EQUIP | MENT and SE | RVICES USED | UNIT PRICE | AMOUNT | CORRECTION | AMOUNT |
| 0203 | 175 sk | 60/40 | | | | | | |
| | | / | | | | | | |
| C194 | 44 16 | cell Flake | | | | | | |
| C310 | 45 3 1b | calicum ch | loride | | <u> </u> | · . | | |
| | | | | | | · | | |
| F163 | lea | wooden P | lug | - | <u> </u> | | · | |
| | | | <i></i> | | | | | |
| E100 | 165mi | HEAVY Ve | hicle n | i 1-WAY | | | | |
| £101 | | Pickup m | | | | | | |
| E104 | 1 | BIK Del cha | | | | | | <u> </u> |
| £107 | 175 sk | Cont services | cha. | | | | | |
| R200 | /en | csqcmt Pu cmt Hend | mper O | -300 | | | | |
| Riol | lep | cmt Hend | Renta | L | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | ····· | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | Piscoun | ted 1 | rice | | | | |
| | | Plus tr | KPS | | \$ 120.61 | | | |
| | | | | | | | RECEIN | /En |
| | | | | | | | | |
| | | | | <u></u> | | | FEB 17; | 2006 |
| | | | | | | | KCC WIC | HITA |
| | | | | | | <u> </u> | | |
| 10244 NE | Hiway 61 · P.C |). Box 8613 · Pratt, | KS 67124-8 | 3613 · Phone (6 | 20) 672-1201 - 1 | Fax (620) 672-5383 | TOTAL | |