Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

Kansas Corporation Commission Oil & Gas Conservation Division

JUL 1 2 2010

RECEIVED

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

WELL PLUGGING RECORD K.A.R. 82-3-117

KCC WICHITA

OPERATOR: License #:3	1001			PI No. 15 - 163-23858		
Name: Maralex R	esources, Inc.					
Address 1: P.O. Box 3	338		N	E.NE.SE Sec.36	Twp. 6 S. R. 18 East	√ We
Address 2:				2,310 Feet fro	m North / 🗸 South Line o	i Sectio
City: Ignacio State: CO zip: 81137 + Contact Person: Doris Ney Phone: (970_) 563-4000 Type of Well: (Check one) SH Well Gas Well OC D&A Cathodic Water Supply Well Other: SWD Permit #: ENHR Permit #: Gas Storage Permit #: Is ACO-1 filed? Yes No If not, is well log attached? Yes No			+			
			Fo			
			0			
			I LE			
			l Di			
					oproved on: <u>5/6/10</u>	
Producing Formation(s): List A			3550		(KCC District Agen	
Arbuckle Depth to			"'		/10	.
		ottom: T.D.	I PI	ugging Completed:5/7	/10	,
Depin to) lop: B	ottom: T.D				
Show depth and thickness of a	all water, oil and gas fo	ormations.				
Oil, Gas or Water	Records		Casing Reco	rd (Surface, Conductor & Pro	duction)	
Formation	Content	Casing	Size	Setting Depth	Pulled Out	
	Oil	surface	8-5/8"	297'		
Arbuckle		- Canage		·		
Arbuckle				,	3	
Arbuckle						
Arbuckle						
Describe in detail the manner				ced and the method or met	hods used in introducing it into the	hole. I
Describe in detail the manner cement or other plugs were us Logs were sent direct Plugging procedure: of logs from TD to su Mix & pump 25 sk plu	ed, state the characte tly from logger. Drill to TD of 35 urface csg. shoe ug of 60/40 poz	r of same depth placed fro ACO-1 to be filed 550'. Circ. and con e. RD loggers. TII w/4% gel & 1/4# F	om (bottom), to (top) . Well not com nd. mud. Run H w/ collars, LE Floseal/sk cmt.	ced and the method or met for each plug set. spleted as logs show sruvey. TOH w/bit. O collars. TIH open Pump to top of Arb	ved no production poten RU loggers. Run full so -ended w/DP. RU cemte ouckle. TOH LD 68 jts D	tial. uite ers.
Describe in detail the manner sement or other plugs were us Logs were sent direct Plugging procedure: of logs from TD to su Mix & pump 25 sk plu	ed, state the characte tly from logger. Drill to TD of 35 urface csg. shoe ug of 60/40 poz	r of same depth placed fro ACO-1 to be filed 550'. Circ. and con e. RD loggers. TII w/4% gel & 1/4# F	om (bottom), to (top) . Well not com nd. mud. Run H w/ collars, LE Floseal/sk cmt.	ced and the method or met for each plug set. pleted as logs show sruvey. TOH w/bit. O collars. TIH open Pump to top of Arb	ved no production poten RU loggers. Run full so -ended w/DP. RU cemte ouckle. TOH LD 68 jts D	tial. uite ers.
Describe in detail the manner cement or other plugs were us Logs were sent direct Plugging procedure: of logs from TD to su Mix & pump 25 sk plu Plugging Contractor License #	ed, state the characte tly from logger. Drill to TD of 35 urface csg. shoe ug of 60/40 poz	r of same depth placed fro ACO-1 to be filed 550'. Circ. and cor e. RD loggers. TII w/4% gel & 1/4# F	om (bottom), to (top) . Well not com nd. mud. Run H w/ collars, LE Floseal/sk cmt. Name: A Address 2:	ced and the method or met for each plug set. pleted as logs show sruvey. TOH w/bit. D collars. TIH open Pump to top of Arb merican Eagle Drill P.O. Box 66	ved no production poten RU loggers. Run full so -ended w/DP. RU cemte ouckle. TOH LD 68 jts D	tial. uite ers.
Describe in detail the manner sement or other plugs were us Logs were sent direct Plugging procedure: of logs from TD to su Mix & pump 25 sk plu Plugging Contractor License #	ed, state the characte tly from logger. Drill to TD of 35 urface csg. shoe ug of 60/40 poz 33493 hington	r of same depth placed fro ACO-1 to be filed 550'. Circ. and cor e. RD loggers. TII w/4% gel & 1/4# F	om (bottom), to (top) . Well not com nd. mud. Run H w/ collars, LE Floseal/sk cmt. Name: A Address 2:	ced and the method or met for each plug set. pleted as logs show sruvey. TOH w/bit. D collars. TIH open Pump to top of Arb merican Eagle Drill P.O. Box 66	ved no production poten RU loggers. Run full so -ended w/DP. RU cemte ouckle. TOH LD 68 jts D	tial. uite ers.
Describe in detail the manner cement or other plugs were us Logs were sent direct Plugging procedure: of logs from TD to su Mix & pump 25 sk plu Plugging Contractor License #	ed, state the characte tly from logger. Drill to TD of 35 urface csg. shoe ug of 60/40 poz 33493 hington	r of same depth placed fro ACO-1 to be filed 550'. Circ. and cor e. RD loggers. TII w/4% gel & 1/4# F	om (bottom), to (top) . Well not com nd. mud. Run H w/ collars, LE Floseal/sk cmt. Name: A Address 2:	ced and the method or met for each plug set. pleted as logs show sruvey. TOH w/bit. D collars. TIH open Pump to top of Arb merican Eagle Drill P.O. Box 66	ved no production poten RU loggers. Run full so -ended w/DP. RU cemte ouckle. TOH LD 68 jts D	tial. uite ers.
Describe in detail the manner sement or other plugs were us Logs were sent direct Plugging procedure: of logs from TD to su Mix & pump 25 sk plu Plugging Contractor License #	ed, state the characte tly from logger. Drill to TD of 35 urface csg. shoe ug of 60/40 poz 33493 hington	r of same depth placed fro ACO-1 to be filed 550'. Circ. and core. RD loggers. TII w/4% gel & 1/4# F	om (bottom), to (top) . Well not com nd. mud. Run H w/ collars, LE Floseal/sk cmt. Name: A Address 2: Sta	ced and the method or met for each plug set. pleted as logs show sruvey. TOH w/bit. O collars. TIH open Pump to top of Arb merican Eagle Drill P.O. Box 66	ved no production poten RU loggers. Run full si ended w/DP. RU cemte buckle. TOH LD 68 jts D ing, LLC zip: 67663 +	tial. uite ers.
Describe in detail the manner rement or other plugs were us Logs were sent direct Plugging procedure: of logs from TD to su Mix & pump 25 sk plu Plugging Contractor License # address 1:700 S. Was Sity:Plainville	ed, state the characte tly from logger. Drill to TD of 35 urface csg. shoe ug of 60/40 poz 33493 hington	r of same depth placed fro ACO-1 to be filed 550'. Circ. and core. RD loggers. TII w/4% gel & 1/4# F	om (bottom), to (top) . Well not com nd. mud. Run H w/ collars, LE Floseal/sk cmt. Name: A Address 2: Sta	ced and the method or met for each plug set. pleted as logs show sruvey. TOH w/bit. O collars. TIH open Pump to top of Arb merican Eagle Drill P.O. Box 66	ved no production poten RU loggers. Run full si ended w/DP. RU cemte buckle. TOH LD 68 jts D ing, LLC zip: 67663 +	tial. uite ers.
Describe in detail the manner tement or other plugs were us Logs were sent direct Plugging procedure: of logs from TD to su Mix & pump 25 sk plugging Contractor License # Address 1: 700 S. Was Dity: Plainville Phone: (785) 434-20 Jame of Party Responsible for State of Colorado	ed, state the characte tly from logger. Drill to TD of 38 urface csg. shoe ug of 60/40 poz 33493 hington Plugging Fees: Ma	aralex Resources,	om (bottom), to (top) . Well not com nd. mud. Run H w/ collars, LE Floseal/sk cmt. Name: A Address 2: Sta Inc.	ced and the method or met for each plug set. pleted as logs show sruvey. TOH w/bit. O collars. TIH open Pump to top of Arb merican Eagle Drill P.O. Box 66	ved no production poten RU loggers. Run full si ended w/DP. RU cemte buckle. TOH LD 68 jts D ing, LLC zip: 67663 +	tial. uite ers. P