4-<u>061026</u>

12-1	API Number: 15-051 -0000
TO: STATE CORPORATION COMMISSION	API Number: 15-101- 1937-
CONSERVATION DIVISION - PLUGGING	<u>NE NW NE/4 SEC22, 11 S,17 </u>
130 SOUTH MARKET, SUITE 2078	4950 feet from S section line
WICHITA, KANSAS 67202	1650 feet from E section line
Operator license#_8925	Lease Johansen Well # A-2
Onesset and Committee Committee Committee	and Country William
Operator: Liberty Operations & Completi	
Address: 308 W. Mill	Well total depth 3449 //2.09 feet
Plainville, Kansas 67663	
	Surface pipe 10 3/4 Inch @ 1136 feet
Aband. oil well <u>x</u> , Gas well, Input	well . SWD . D & A
Plugging contractor: Co Tools	License#
Address:	
Company to plug at: Hour: 11:30 A.M. Day	: 16 Month: December Year: 1996
Plugging proposal received from: Charl	ie_Farr
Company: Consultant	Phone:
	12-23-9
Plugging Proposal Received by: <u>Herb Dei</u> Plugging operations attended by agent? A	
Completed: Hour: 1:30 P.M., Day: 16, M	onth: December , Year: 1996
3 about 3 ad 3 and 4 and	
	/4" to 1136'. 7" to 3443'. Remove casing hanger
and orange neel 10 3/4" to 7" casing wit	
	h collar. Tied onto 7" casing and pumped 75 sxs
cement with 500# hulls, 20 sxs gel and 225	h collar. Tied onto 7" casing and pumped 75 sxs sxs cement. Max. P.S.I. 500#. S.I.P. 200#. Tied
cement with 500# hulls, 20 sxs gel and 225	h collar. Tied onto 7" casing and pumped 75 sxs sxs cement. Max. P.S.I. 500#. S.I.P. 200#. Tied
cement with 500# hulls, 20 sxs gel and 225	h collar. Tied onto 7" casing and pumped 75 sxs sxs cement. Max. P.S.I. 500#. S.I.P. 200#. Tied
cement with 500# hulls, 20 sxs gel and 225	h collar. Tied onto 7" casing and pumped 75 sxs sxs cement. Max. P.S.I. 500#. S.I.P. 200#. Tied
cement with 500# hulls, 20 sxs gel and 225	h collar. Tied onto 7" casing and pumped 75 sxs sxs cement. Max. P.S.I. 500#. S.I.P. 200#. Tied
cement with 500# hulls, 20 sxs gel and 225 onto annulus with instant 500# S.I.P.	h collar. Tied onto 7" casing and pumped 75 sxs sxs cement. Max. P.S.I. 500#. S.I.P. 200#. Tied
cement with 500# hulls, 20 sxs gel and 225 onto annulus with instant 500# S.I.P. Remarks: Allied Cementing.	h collar. Tied onto 7" casing and pumped 75 sxs sxs cement. Max. P.S.I. 500#. S.I.P. 200#. Tied
cement with 500# hulls, 20 sxs gel and 225 onto annulus with instant 500# S.I.P. Remarks: Allied Cementing. Condition of casing(in hole): GOOD_X BAD Bottom plug(in place): YES, CALC_X, N	h collar. Tied onto 7" casing and pumped 75 sxs sxs cement. Max. P.S.I. 500#. S.I.P. 200#. Tied Anhy.plug: YES_X NO Dakota plug: YES_X, NO
Comment with 500# hulls, 20 sxs gel and 225 onto annulus with instant 500# S.I.P. Remarks: Allied Cementing. Condition of casing(in hole): GOOD_X BAD Bottom plug(in place): YES, CALC_X_, N Plugged through TUBING, CASING_X	h collar. Tied onto 7" casing and pumped 75 sxs sxs cement. Max. P.S.I. 500#. S.I.P. 200#. Tied Anhy.plug: YES_X NO Dakota plug: YES_X, NO
Remarks: Allied Cementing. Condition of casing(in hole): GOOD_X BAD Bottom plug(in place): YES, CALC_X, N Plugged through TUBING, CASING_X	h collar. Tied onto 7" casing and pumped 75 sxs sxs cement. Max. P.S.I. 500#. S.I.P. 200#. Tied Anhy.plug: YES_X NO Dakota plug: YES_X NO Elevation:1921
Remarks: Allied Cementing. Condition of casing(in hole): GOOD_X BAD Bottom plug(in place): YES, CALC_X, N Plugged through TUBING, CASING X I did [] Adid not[X] observe the plu	h collar. Tied onto 7" casing and pumped 75 sxs sxs cement. Max. P.S.I. 500#. S.I.P. 200#. Tied Anhy.plug: YES_X NO Dakota plug: YES_X, NO Elevation: GL
Remarks: Allied Cementing. Condition of casing(in hole): GOOD_X BAD Bottom plug(in place): YES, CALC_X, N Plugged through TUBING, CASING_X I did [[]	h collar. Tied onto 7" casing and pumped 75 sxs sxs cement. Max. P.S.I. 500#. S.I.P. 200#. Tied Anhy.plug: YES_X NO Dakota plug: YES_X NO Elevation:1921
cement with 500# hulls, 20 sxs gel and 225 onto annulus with instant 500# S.I.P. Remarks: Allied Cementing. Condition of casing(in hole): GOOD_X BAD	Anhy.plug: YES X NO Dakota plug: YES X NO GL Gging.