STATE OF KANSAS STATE CORPORATION COMMISSION

15-169-00568-00-00 Form CP-4

State Corporation Commission P. O. Box 17027 Wichita, Kansas 67217	Saline		County	y. Sec. 5	Twp. 16_ Rge.	.3_ (1	E)_W(W	
Wichita, Kansas 67217 NONTH	Location as "l	YE/CNWKSWX" o	r footage from	m linesN	W NE NW			
The second secon	Lease Owner_	Tom C. &	E. Melva	a Brown				
1 1	Lesso Name_	Church I	roperty	77 - (	7/5/	. Well N	0	
	Office Address	Box 387,	Lindsbor	rg, Ks 6	/456 of 1		<u> </u>	
	Character of	Well (completed a	s Oil, Gas or	Dry Hole) _	OII		19	
	Date well cor	npleted <u>ur</u>	Tuna	a 12			19_74	
	Application fo	or plugging filed					19.7/	
	Application to	r plugging approvemenced	June	2 14	,			
	Plugging com	pleted	June	e 25			19_7/	
	Reason for ab	andonment of well		g formation	depleted			
		Reason for abundonment of well or producing formationdepleted						
	If a producing	g well is abandone	ed, date of la	st production.			19	
The second secon		on obtained from		ation Division	or its agents being	ore plugg	ing was co	
Locate well correctly on above Section Plat	menced?		yes Mr.	Gilbert '	Toman			
Section Plat ne of Conservation Agent who supe	rvised plugging of t	his well	Dallan		Total Death of	Well	3395 <b>'F</b>	
ducing formation		Deput to top	Botton	I <u> </u>	_ 10th Depth of	TV Cal		
ow depth and thickness of all water,	OH RUG BUS TORMER	(CELS.			•			
OIL, CAS OR WATER RECORD	)S		· · · · · · · · · · · · · · · · · · ·			CASING	RECORD	
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	PU	LLED OUT	
E METTALE THE				5½''	unknown	2441	.83'	
							· · · · · · · · · · · · · · · · · · ·	
and the second s						<u> </u>		
					<del></del>	<b></b>		
			<u> </u>			<del> </del>	<del></del>	
	<u> </u>			ļ				
			<u> </u>	<del> </del>	<del></del>	<del> </del>		
feet for each plug so	nent or other plugs et.  lar. Dump	were used, state ti	of sand.	of same and de	ridged at 3	351' a	ind	
Rig up and dig out celdumped 5 sacks of come	lar. Dump nt. Tools a	80 gallons ond 2900' of	of sand. wire li	. Hole b	ridged at 33 n hole. Bot 220 to 210	351' a ttom o	ind of tools	
Rig up and dig out cel dumped 5 sacks of ceme left in hole is approx added 25 sacks of ceme	lar. Dump nt. Tools a imately 2900	80 gallons ond 2900' of	of sand. wire li	. Hole b	ridged at 33 n hole. Bot 220 to 210	351' a ttom o	ind of tools	
Rig up and dig out cel dumped 5 sacks of ceme left in hole is approxadded 25 sacks of ceme	lar. Dump nt. Tools a imately 2900	80 gallons ond 2900' of	of sand. wire li	. Hole b	ridged at 3: n hole. Bot 220 to 210 and added	351' a ttom o ' and 10 sac	ind of tools	
Rig up and dig out cel dumped 5 sacks of ceme left in hole is approxadded 25 sacks of ceme	lar. Dump nt. Tools a imately 2900	80 gallons ond 2900' of	of sand. wire li	. Hole b	ridged at 3: n hole. Bot 220 to 210 and added	351' a ttom o ' and 10 sac	ind of tools	
Rig up and dig out cel dumped 5 sacks of ceme left in hole is approxadded 25 sacks of ceme	lar. Dump nt. Tools a imately 2900	80 gallons ond 2900' of	of sand. wire li	. Hole b	ridged at 3: n hole. Bot 220 to 210 and added	351' a ttom o ' and 10 sac	ind of tools	
Rig up and dig out cel dumped 5 sacks of ceme left in hole is approx added 25 sacks of ceme	lar. Dump nt. Tools a imately 2900	80 gallons ond 2900' of	of sand. wire li	. Hole b	ridged at 3: n hole. Bot 220 to 210 and added	351' a ttom o ' and 10 sac	ind of tools	
Rig up and dig out cel dumped 5 sacks of ceme left in hole is approxadded 25 sacks of ceme	lar. Dump nt. Tools a imately 2900	80 gallons ond 2900' of	of sand. wire li	. Hole b ne lost i bridge at 0' to 30'	ridged at 3: n hole. Bot 220 to 210 and added	351' attom of and 10 sac	ind of tools oks of	
Rig up and dig out cel dumped 5 sacks of ceme left in hole is approx added 25 sacks of ceme	lar. Dump nt. Tools a imately 2900	80 gallons ond 2900' of	of sand. wire li	. Hole b ne lost i bridge at 0' to 30'	ridged at 3: n hole. Bot 220 to 210 and added	351' attom of and 10 sac	ind of tools oks of	
feet for each plug so reach plug and dig out cel dumped 5 sacks of ceme left in hole is approx	lar. Dump nt. Tools a imately 2900 nt. Put a I ace.	80 gallons ond 2900' of	of sand. wire li	. Hole b ne lost i bridge at 0' to 30'	ridged at 3: n hole. Bot 220 to 210 and added	351' attom of and 10 sac	ind of tools oks of	
Rig up and dig out cel dumped 5 sacks of ceme left in hole is approxadded 25 sacks of ceme	lar. Dump nt. Tools a imately 2900	80 gallons ond 2900' of	of sand. wire li	. Hole b ne lost i bridge at 0' to 30'	ridged at 3: n hole. Bot 220 to 210 and added	351' attom of and 10 sac	ind of tools oks of	
Rig up and dig out cel dumped 5 sacks of ceme left in hole is approxadded 25 sacks of ceme	lar. Dump nt. Tools a imately 2900 nt. Put a I ace.	80 gallons ond 2900' of	of sand. wire li	. Hole b ne lost i bridge at 0' to 30'	ridged at 3: n hole. Bot 220 to 210 and added	351' attom of and 10 sac	ind of tools oks of	
Rig up and dig out cel dumped 5 sacks of ceme left in hole is approxadded 25 sacks of ceme	lar. Dump nt. Tools a imately 2900 nt. Put a I ace.	80 gallons ond 2900' of	of sand. wire li	. Hole b ne lost i bridge at 0' to 30'	ridged at 3: n hole. Bot 220 to 210 and added	351' attom of and 10 sac	ind of tools oks of	
introducing it into the hole. If cenfeet for each plug so  Rig up and dig out cel dumped 5 sacks of ceme left in hole is approx added 25 sacks of ceme cement to plug to surf	lar. Dump nt. Tools a imately 2900 nt. Put a I ace.	80 gallons ond 2900' of '. Put a le 0' rock-brie	of sand. wire lin	. Hole b ne lost i oridge at O' to 30'	ridged at 3: n hole. Bot 220 to 210 and added	351' attom of and 10 sac	ind of tools oks of	
introducing it into the hole. If cen feet for each plug so  Rig up and dig out cel dumped 5 sacks of ceme left in hole is approx added 25 sacks of ceme cement to plug to surf	nent or other plugs et.  lar. Dump nt. Tools a imately 2900 nt. Put a I ace.  THE BUCKEYE	80 gallons on 2900' of '. Put a 160' rock-brick	of sand. wire lin	. Hole b ne lost i oridge at O' to 30'	ridged at 3: n hole. Bot 220 to 210 and added	351' attom of and 10 sac	ind of tools oks of	
introducing it into the hole. If cen feet for each plug so  Rig up and dig out cel dumped 5 sacks of ceme left in hole is approx added 25 sacks of ceme cement to plug to surf	nent or other plugs et.  lar. Dump nt. Tools a imately 2900 nt. Put a I ace.  THE BUCKEYE	80 gallons on 2900' of '. Put a 160' rock-brick	of sand. wire lin	. Hole b ne lost i oridge at O' to 30'	ridged at 3: n hole. Bot 220 to 210 and added	351' attom of and 10 sac	ind of tools oks of	
introducing it into the hole. If cen feet for each plug so  Rig up and dig out cell dumped 5 sacks of ceme left in hole is approx added 25 sacks of ceme cement to plug to surf	lar. Dump nt. Tools a imately 2900 nt. Put a I ace.  THE BUCKEYE ado, Kansas	80 gallons on 2900' of '. Put a 16 O' rock-bris	of sand. wire ling rock lige at 40	. Hole b ne lost i oridge at O' to 30'	ridged at 3: n hole. Bot 220 to 210 and added	351' attom of and 10 sac	ind of tools oks of	
introducing it into the hole. If cen  feet for each plug so  Rig up and dig out cel dumped 5 sacks of ceme Left in hole is approx added 25 sacks of ceme cement to plug to surf  ame of Plugging Contractor ddress  WANSAS	lar. Dump nt. Tools a imately 2900 nt. Put a I ace.  THE BUCKEYE ado, Kansas	80 gallons on 2900' of '. Put a 16 O' rock-bris	of sand. wire ling rock lige at 40	. Hole bene lost in the lost i	ridged at 3: n hole. Bot 220 to 210 and added  STATE CORPOR,  CONSERVATION Wichita Ka	351' attom of and 10 sac	ind of tools oks of	
introducing it into the hole. If cen  feet for each plug so  Rig up and dig out cel dumped 5 sacks of ceme Left in hole is approx added 25 sacks of ceme cement to plug to surf  ame of Plugging Contractor ddress  WANSAS	lar. Dump nt. Tools a imately 2900 nt. Put a I ace.  THE BUCKEYE ado, Kansas	80 gallons on 2900' of '. Put a loo or rock-bridge CORPORATION 67042	of sand. wire lings rock lige at 40	. Hole bene lost it bridge at 0' to 30'	ridged at 3: n hole. Bon 220 to 210 and added  STATE CORPOR,  VICINITA K	351' a ttom o ' and 10 sac  FIVE MON CO	ind of tools one of tools one of tools	
introducing it into the hole. If cenfeet for each plug so  Rig up and dig out cell dumped 5 sacks of ceme Left in hole is approx added 25 sacks of ceme cement to plug to surf  ame of Plugging Contractor ddress Box 1020, El Dor  KANSAS Charles V. Cros	lar. Dump nt. Tools a imately 2900 nt. Put a I ace.  THE BUCKEYE ado, Kansas	80 gallons on 2900' of '. Put a 100' rock-bridge CORPORATION 67042	of sand. wire ling rock lige at 40  BUTLER (employee of	. Hole bene lost in the lost i	ridged at 3: n hole. Bot 220 to 210 and added  STATE CORPOR,  CONSERVATION  Vichita Ka	351' attom of and 10 sac	ind of tools oks of	
introducing it into the hole. If cen feet for each plug so  Rig up and dig out cel dumped 5 sacks of ceme left in hole is approx added 25 sacks of ceme cement to plug to surf  ame of Plugging Contractor ddress Box 1020, El Dor  KANSAS Charles V. Cros rell, being first duly sworn on cath,	lar. Dump nt. Tools a imately 2900 nt. Put a I ace.  THE BUCKEYE ado, Kansas	80 gallons of nd 2900' of '. Put a 16 0' rock-brie CORPORATION 67042	of sand. wire lingly rock light r	. Hole be not lost it bridge at 0' to 30'	ridged at 3: n hole. Bot 220 to 210 and added  STATE CORPOR,  CONSERVATION  Vichita Ka	351' attom of and 10 sac	ind of tools oks of	
introducing it into the hole. If cen  feet for each plug so  Rig up and dig out cel  dumped 5 sacks of ceme left in hole is approx added 25 sacks of ceme cement to plug to surf  ame of Plugging Contractor ddress Box 1020, El Dor  KANSAS  Charles V. Cros  rell, being first duly sworn on cath,	lar. Dump nt. Tools a imately 2900 nt. Put a I ace.  THE BUCKEYE ado, Kansas	80 gallons of nd 2900' of '. Put a 16 0' rock-brie CORPORATION 67042	of sand. wire ling rock lings at 40 lings at 40 BUTLER (employee of facts, states help me Go	. Hole bene lost in bridge at 0' to 30'  Kefthis sheet)	ridged at 3: n hole. Bot 220 to 210 and added  STATE CORPOR,  CONSERVATION  Vichita Ka	351' attom of and 10 sac	ind of tools oks of	
introducing it into the hole. If cenfeet for each plug so  Rig up and dig out cell dumped 5 sacks of ceme left in hole is approx added 25 sacks of ceme cement to plug to surf  ame of Plugging Contractor ddress Box 1020, El Dor	lar. Dump nt. Tools a imately 2900 nt. Put a I ace.  THE BUCKEYE ado, Kansas	80 gallons of nd 2900' of '. Put a 16 0' rock-brie CORPORATION 67042	essery, use BAC  BUTLER  (employee of facts, states help me Go	. Hole bene lost in bridge at 0' to 30'  Kefthis sheet)	ridged at 3: n hole. Bot 220 to 210 and added  STATE CURPOR  Vichita  Keeper or operator  State of the content	351' and thom of and the same a	ind of tools oks of	
introducing it into the hole. If cen feet for each plug so  Rig up and dig out cell dumped 5 sacks of ceme left in hole is approx added 25 sacks of ceme cement to plug to surf  ame of Plugging Contractor ddress Box 1020, El Dor  KANSAS TATE OF KANSAS Charles V. Cros rell, being first duly sworn on cath,	lar. Dump nt. Tools a imately 2900 nt. Put a I ace.  THE BUCKEYE ado, Kansas	80 gallons of nd 2900' of '. Put a 16 0' rock-brie CORPORATION 67042	essery, use BAC  BUTLER  (employee of facts, states help me Go	. Hole bene lost in bridge at 0' to 30'  Kefthis sheet)	ridged at 3: n hole. Bot 220 to 210 and added  STATE CURPOR  Vichita  Keeper or operator  State of the content	351' attom of and 10 sac	ind of tools oks of	
introducing it into the hole. If cen  feet for each plug so  Rig up and dig out cel  dumped 5 sacks of ceme left in hole is approx added 25 sacks of ceme cement to plug to surf  ame of Plugging Contractor ddress Box 1020, El Dor  KANSAS  Charles V. Cros  rell, being first duly sworn on cath,	lar. Dump int. Tools a imately 2900 imately	80 gallons of nd 2900' of '. Put a 16 0' rock-brie CORPORATION 67042	be character of sand.  Wire ling of rock ling at 40 lin	. Hole bene lost in bridge at 0' to 30'  Kefthis sheet)	ridged at 3: n hole. Bot 220 to 210 and added  STATE CURPOR,  Vichita Ka	351' and thom of and the same a	ind of tools oks of	

STATE NOTARY PUBLIC
Butler County, Ks.
My Commission Expires
June 30, 1975

5-16-3W SALEMSBORG CHURCH NW NE NW
SALINE County
2-4-53 IP 45 BOPD
Casing
5 <b>"</b> 3393
DP 3395: A CID 1000:
DP 3395: A CID 1000: SWB 7 BOPH/5 HRS:
SALEMSBORG POOL
h++++