
CP-3 6-26-62 Rev.

KANSAS

J. P. Roberts Administrator 500 Insurance Building Wichita 2, Kansas

INV. NO. _



Operator's Full Name Pickrell Drilling Company Complete Address: 705 4th Nat'l Bank Eldg., Wichita, Kansas Lease-Name Beardslee_"A" - Well No. 1 Location C NW SE Sec. 14 Twp. 20 Rge. 23 (E) (W) X County Ness Total Depth 4450' Abandoned Oil Well Gas Well Input Well SWD Well D & A X Other well as hereafter indicated: Plugging Contractor: Co. Tools Address: License No. Operation Completed: Hour 9 P Day 22 Month 10 Year 1967 The Above well was plugged as follows: RTD 4450' 8 5/8 csg set at 268' cwc 165 sc. Gunned pits, circulated heavy mud, set cementing plug at 660' and displaced 100 sc c thru drill pipe. Heavy mud to 260' set cementing plug and displaced 25 sc cement thru drill pipe. Heavy mud to 40' set cementing plug, 1/2 sc hulls and 10 sc cement to base of cellar. Plugged rat hole with 2 sc cement. No icellar Plugged Plugging Supervivor Plugging Supervivor	· · · · · · · · · · · · · · · · · · ·		* ,		300
Lease Name Beardslee-"A" - Well No. 1 Location C NW SE Sec. 14 Twp. 20 Rge, 23 (E) (W) X County Ness Total Depth 4450' Abandoned Oil Well Gas Well Input Well SWD Well D & A X Other well as hereafter indicated: Plugging Contractor: Co. Tools Address: License No. Operation Completed: Hour 9 P Day 22 Month 10 Year 1967 The Above well was plugged as follows: RTD 4450' 8 5/8 csg set at 268' cwc 165 sc. Gunned pits, circulated heavy mud, set cementing plug at 660' and displaced 100 sc c thru drill pipe. Heavy mud to 260' set cementing plug and displaced 25 sc cement thru drill pipe. Heavy mud to 40' set cementing plug, 1/2 sc hulls and 10 sc cement to base of cellar. Plugged rat hole with 2 sc cement. Address: Signed: Signed: Well Plugging Supervilor Well Plugging Supervilor	Operator's Full Name	, Pickrell Dri	lling Company		
Location C NW SE Sec. 14 Twp. 20 Rge. 23 (E) (W) X County Ness Total Depth 4450° Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated: Plugging Contractor: Co. Tools Address: License No. Operation Completed: Hour 9 P Day 22 Month 10 Year 1967 The Above well was plugged as follows: RTD 4450° 8 5/8 csg set at 268° cwc 165 sc. Gunned pits, circulated heavy mud, set cementing plug at 660° and displaced 100 sc c thru drill pipe. Heavy mud to 260° set cementing plug and displaced 25 sc cement thru drill pipe. Heavy mud to 40° set cementing plug, 1/2 sc hulls and 10 sc cement to base of cellar. Plugged rat hole with 2 sc cement. Above well was plugged as herein stated. Well Plugging Supervior	Complete Address:	705 4th Nat'	l Bank Bldg.,	Wichita, Kans	as
Location C NW SE Sec. 14 Twp. 20 Rge. 23 (E) (W) X County Ness Total Depth 4450° Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated: Plugging Contractor: Co. Tools Address: License No. Operation Completed: Hour 9 P Day 22 Month 10 Year 1967 The Above well was plugged as follows: RTD 4450° 8 5/8 csg set at 268° cwc 165 sc. Gunned pits, circulated heavy mud, set cementing plug at 660° and displaced 100 sc c thru drill pipe. Heavy mud to 260° set cementing plug and displaced 25 sc cement thru drill pipe. Heavy mud to 40° set cementing plug, 1/2 sc hulls and 10 sc cement to base of cellar. Plugged rat hole with 2 sc cement. Above well was plugged as herein stated. Well Plugging Supervior	Lease-Name	Beardslee-"A'	<u>"</u>	well Nol	e e e e e e e e e e e e e e e e e e e
County Ness Total Depth 4450* Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated: Plugging Contractor: Co. Tools Address: License No. Operation Completed: Hour 9 P Day 22 Nonth 10 Year 1967 The Above well was plugged as follows: RTD 4450* 8 5/8 csg set at 268* cwc 165 sc. Gunned pits, circulated heavy mud, set cementing plug at 660* and displaced 100 sc c thru drill pipe. Heavy mud to 260* set cementing plug and displaced 25 sc cement thru drill pipe. Heavy mud to 40* set cementing plug, 1/2 sc hulls and 10 sc cement to base of cellar. Plugged rat hole with 2 sc cement. The Above well was plugged as herein stated. Signed: License No. Well Plugging Superviour					
Other well as hereafter indicated: Plugging Contractor: Co. Tools Address: License No. Operation Completed: Hour 9 P Day 22 Nonth 10 Year 1967 The Above well was plugged as follows: RTD 4450° 8 5/8 csg set at 268° cwc 165 sc. Gunned pits, circulated heavy mud, set cementing plug at 660° and displaced 100 sc cement drill pipe. Heavy mud to 260° set cementing plug and displaced 25 sc cement threshold drill pipe. Heavy mud to 40° set cementing plug, 1/2 sc hulls and 10 sc cement to base of cellar. Plugged rat hole with 2 sc cement. hereby certify that the above well was plugged as herein stated. Signed: Well Plugging Supervisor	County	Ness			
Plugging Contractor: Co. Tools Address: License No. Operation Completed: Hour 9 P Day 22 Nonth 10 Year 1967 The Above well was plugged as follows: RTD 4450° 8 5/8 csg set at 268° cwc 165 sc. Gunned pits, circulated heavy mud, set cementing plug at 660° and displaced 100 sc c thru drill pipe. Heavy mud to 260° set cementing plug and displaced 25 sc cement thre drill pipe. Heavy mud to 40° set cementing plug, 1/2 sc hulls and 10 sc cement to base of cellar. Plugged rat hole with 2 sc cement. The Above well was plugged as herein stated. Signed: Well Plugging Supervisor	Abandoned O11 Well	Gas Well	Input Well_	SWD Well_	D & A X
Operation Completed: Hour 9 P Day 22 Month 10 Year 1967 The Above well was plugged as follows: RTD 4450° 8 5/8 csg set at 268° cwc 165 sc. Gunned pits, circulated heavy mud, set cementing plug at 660° and displaced 100 sc c thru drill pipe. Heavy mud to 260° set cementing plug and displaced 25 sc cement thru drill pipe. Heavy mud to 40° set cementing plug, 1/2 sc hulls and 10 sc cement to be of cellar. Plugged rat hole with 2 sc cement. hereby certify that the above well was plugged as herein stated. V O C E D Signed:	Other well as hereaf	ter indicated:	*****		
Operation Completed: Hour 9 P Day 22 Month 10 Year 1967 The Above well was plugged as follows: RTD 4450° 8 5/8 csg set at 268° cwc 165 sc. Gunned pits, circulated heavy mud, set cementing plug at 660° and displaced 100 sc centrular drill pipe. Heavy mud to 260° set cementing plug and displaced 25 sc cement threshold drill pipe. Heavy mud to 40° set cementing plug, 1/2 sc hulls and 10 sc cement to base of cellar. Plugged rat hole with 2 sc cement. The Above well was plugged as herein stated. Signed: Well Plugging Supervisor	Plugging Contractor:		Co. Tool	s	
Operation Completed: Hour 9 P Day 22 Month 10 Year 1967 The Above well was plugged as follows: RTD 4450' 8 5/8 csg set at 268' cwc 165 sc. Gunned pits, circulated heavy mud, set cementing plug at 660' and displaced 100 sc centru drill pipe. Heavy mud to 260' set cementing plug and displaced 25 sc cement thresholder between the drill pipe. Heavy mud to 40' set cementing plug, 1/2 sc hulls and 10 sc cement to be of cellar. Plugged rat hole with 2 sc cement. The Above well was plugged as herein stated. Signed: The Above Well Plugging Supervisor.	Address:			Į.i.«	cense No.
Gunned pits, circulated heavy mud, set cementing plug at 660° and displaced 100 sc c thru drill pipe. Heavy mud to 260° set cementing plug and displaced 25 sc cement thru drill pipe. Heavy mud to 40° set cementing plug, 1/2 sc hulls and 10 sc cement to base of cellar. Plugged rat hole with 2 sc cement. hereby certify that the above well was plugged as herein stated. Signed: Let 7. Marray well Plugging Supervisor	Operation Completed:	Hour 9 P Day	, 22 j		
thru drill pipe. Heavy mud to 260° set cementing plug and displaced 25 sc cement thru drill pipe. Heavy mud to 40° set cementing plug, 1/2 sc hulls and 10 sc cement to base of cellar. Plugged rat hole with 2 sc cement. hereby certify that the above well was plugged as herein stated. Signed: Let That well plugging Supervisor.				• •	,
thru drill pipe. Heavy mud to 260° set cementing plug and displaced 25 sc cement thru drill pipe. Heavy mud to 40° set cementing plug, 1/2 sc hulls and 10 sc cement to base of cellar. Plugged rat hole with 2 sc cement. hereby certify that the above well was plugged as herein stated. Signed: Let That well plugging Supervisor.	Gunned pits, circula	ited heavy mud, se	t cementing pl	lug at 660° and d	lisplaced 100 sc ce
drill pipe. Heavy mud to 40° set cementing plug, 1/2 sc hulls and 10 sc cement to base of cellar. Plugged rat hole with 2 sc cement. hereby certify that the above well was plugged as herein stated. Signed: Let 7 Marxan Well Plugging Supervisor					
of cellar. Plugged rat hole with 2 sc cement. hereby certify that the above well was plugged as herein stated. VOICED Signed: Let Flugging Supervisor					
Well Plugging Supervisor				AND THE RESIDENCE OF THE PROPERTY OF THE PROPE	
Well Plugging Supervisor	4	,			
Signed: Supervisor					
Signed: Supervisor				**************************************	
Signed: Supervisor	hereby certify that	the above well wa	as plugged as	herein stated.	
Well Plugging Supervisor	1.:V) I C F D	,	Signed: Sw	2 Marron
				Well Pla	ugging Supervisor