## State of Kansas

ROBERT B. DOCKING WILLIAM L. MITCHELL JAMES O. GREENLEAF DALE E. SAFFELS RAYMOND B. HARVEY E. EDWARD JOHNSON Gen. Counsel

Governor Chairman Commissioner Commissioner Secretary

Dear Sir:



## State Corporation Commission

## CONSERVATION DIVISION

(Oil, Gas and Water) 500 Insurance Bldg. 212 N. Market WICHITA, KANSAS 67202

## VERBAL PERMIT FORM (To Be Filed By Plugging Agent)



NOV 13 196/

J. P. Roberts Administrator 500 Insurance Building Wichita, Kansas 67202

COMSERVATION DIVISION Wichita, Kansas

date requested permission to plug the following described well:  Mr. Steincamp guarantees payment of the plugging fee.  Operator's full Name: R. V. Lehner  Complete Address: P. O. Box 398 Ness City, Kansas  Lease Name: Cranston Well No. 2  Location: C SE NE Sec. 25 Twp. 20 Rge. 24 (E)(W) X  County: Ness Total Depth 4413 Oil Well  Gas Well Input Well SWD Well D & A X Lost Hole  Mr. Steincamp was instructed to plug the well as follows:  Gun pits, cieculate heavy mud, set cementing plug at 720' and displace  100 sc cement thru drill pipe. Heavy mud to 300' set cementing plug and displace 25 sc cement thru drill pipe. Heavy mud to 40' set cementing plug 1/2 sc hulls and 10 sc cement to base of cellar. Plug rat hole with 2 sc	Wr.	Steincar	np '	of Str	ata Drlg.	Inc.,	has	this
Operator's full Name: R. V. Lehner  Complete Address: P. O. Box 398 Ness City, Kansas  Lease Name: Cranston Well No. 2  Location: C SE NE Sec. 25 Twp. 20 Rge. 24 (E)(W) X  County: Ness Total Depth 4413 Oil Well  Gas Well Input Well SWD Well D & A X Lost Hole  Mr. Steincamp was instructed to plug the well as follows: Gun pits, cieculate heavy mud, set cementing plug at 720' and displace  100 sc cement thru drill pipe. Heavy mud to 300' set cementing plug and displace 25 sc cement thru drill pipe. Heavy mud to 40' set cementing plug and		•	·			•		
Complete Address:  P. O. Box 398  Ness City, Kansas  Lease Name:  Cranston  Well No. 2  Location:  C SE NE  Sec. 25 Twp. 20 Rge. 24 (E)(W) X  County:  Ness  Total Depth 4413 Oil Well  Gas Well  Input Well  SWD Well  D & A X Lost Hole  Mr. Steincamp  Was instructed to plug the well as follows:  Gun pits, cieculate heavy mud, set cementing plug at 720' and displace  100 sc cement thru drill pipe. Heavy mud to 300' set cementing plug and displace 25 sc cement thru drill pipe. Heavy mud to 40' set cementing plug and				<del></del> -	·	of the p	lugging :	[00.
Lease Name: Cranston Well No. 2  Location: C SE NE Sec. 25 Twp. 20 Rge. 24 (E)(W) X  County: Ness Total Depth 4413 Oil Well  Gas Well Input Well SWD Well D & A X Lost Hole  Mr. Steincamp was instructed to plug the well as follows:  Gun pits, cieculate heavy mud, set cementing plug at 720' and displace  100 sc cement thru drill pipe. Heavy mud to 300' set cementing plug and displace 25 sc cement thru drill pipe. Heavy mud to 40' set cementing plug and	Ope	rator's full	Name:	v. Demier			····	
Location: C SE NE Sec. 25 Twp. 20 Rge. 24 (E) (W) X  County: Ness Total Depth 4413 Oil Well  Gas Well Input Well SWD Well D & A X Lost Hole  Mr. Steincamp was instructed to plug the well as follows:  Gun pits, cieculate heavy mud, set cementing plug at 720° and displace  100 sc cement thru drill pipe. Heavy mud to 300° set cementing plug and displace 25 sc cement thru drill pipe. Heavy mud to 40° set cementing plug and	Com	plete Address	P. 0.	Box 398	Ness Ci	ity, Kansa	s	
County: Ness Total Depth 4413 Oil Well  Gas Well Input Well SWD Well D&A X Lost Hole  Mr. Steincamp was instructed to plug the well as follows:  Gun pits, cieculate heavy mud, set cementing plug at 720° and displace  100 sc cement thru drill pipe. Heavy mud to 300° set cementing plug and displace 25 sc cement thru drill pipe. Heavy mud to 40° set cementing plug and	Lea	se Name:	Cranston			ell No	2	·
Gas Well Input Well SWD Well D & A X Lost Hole  Mr. Steincamp was instructed to plug the well as follows:  Gun pits, cieculate heavy mud, set cementing plug at 720' and displace  100 sc cement thru drill pipe. Heavy mud to 300' set cementing plug and displace 25 sc cement thru drill pipe. Heavy mud to 40' set cementing plug and displace 25 sc cement thru drill pipe. Heavy mud to 40' set cementing plug and displace 25 sc cement thru drill pipe.	Loc	ation:	C SE NE		Sec. <u>25</u> Tw	p. 20 Rg	. <u>24</u> (E)	) (W) <u>X</u>
Mr. Steincamp was instructed to plug the well as follows:  Gun pits, cieculate heavy mud, set cementing plug at 720° and displace  100 sc cement thru drill pipe. Heavy mud to 300° set cementing plug and  displace 25 sc cement thru drill pipe. Heavy mud to 40° set cementing plug	Cou	nty:	Ness	·	Total De	pth 4413	O11 We	
Gun pits, cieculate heavy mud, set cementing plug at 720° and displace 100 sc cement thru drill pipe. Heavy mud to 300° set cementing plug and displace 25 sc cement thru drill pipe. Heavy mud to 40° set cementing plug and	Gas	WellInp	ut Well	SWD Well_	D & A	X Los	t Hole	
100 sc cement thru drill pipe. Heavy mud to 300° set cementing plug and displace 25 sc cement thru drill pipe. Heavy mud to 40° set cementing plug	Mr.	Steincamp		as instruc	eted to pl	ug the wel	ll as fol	llows:
displace 25 sc cement thru drill pipe. Heavy mud to 40° set cementing place	Gun	pits, ciecula	ate heavy muc	d, set cem	enting plu	ıg at 720'	and dis	place
	100	sc cement thi	ru drill pipe	e. Heavy m	ud to 300	set ceme	nting pl	ug and
1/2 sc hulls and 10 sc cement to base of cellar. Plug rat hole with 2 sc	lisp	olace 25 sc ce	ement thru di	rill pipe.	Heavy muc	1 to 40 s	et cemen	ting plug
	1/2	sc hulls and	10 sc cement	t to base	of cellar.	. Plug rat	hole wi	th 2 sc
cement.	ceme	ent.						

Very truly yours,