	STATE OF KA	.NSAS
STATE	CORPORATION	COMMISSION
		. 42

STATE CONFORATION CO	AFIATT	3.51V
Give All Information Completely "	1. 1	17
Make Required Affidavit		
Mail or Deliver Report to:		٠.

WELL PLUGGING RECORD

State Corporation Commission 212 No. Market Wichita, Kansas 67202						
	L	ane		28 .	. 16 -	27 2 (***)
1 9.			Count	y. Sec. 7	NE NE Rge.	$\frac{27}{\sqrt{2}}$
NORTH	Location as "NI Lease Owner	E/CNWXSWX" (Ra ymo	nd Oil C	on lines		
	Lease Owner Lease Name	Let ch	ton #2			Well No.
	Office Address_	Wichi		as 67202		WEH NO
		ell (completed				
	Date well com	1 . 1				
i i	Application for	nlugging filed				
	Application for Plugging comm	plugging approv	ed .			19
i i i	Plugging comm	enced 3/	19/70	· · · · · · · · · · · · · · · · · · ·		19
	Plugging compl	3 /	23/70			19
		donment of wel	or producin	g formation	depleted.	
	If a producing	well is abandon	ed, date of la	ast production_		19
	1			_		ore plugging was com-
Locate well correctly on above Section Plat	menced?	yes				
lame of Conservation Agent who supe	ervised plugging of thi	3 W CU	chols			
roducing formation	Γ	Depth to top	Botton	n	Total Depth of	Well_4554* Feet
how depth and thickness of all water						
OIL, CAS OR WATER RECORD	os					CASING RECORD
					<u> </u>	
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	PULLED OUT
				8-5/8	287	none
	STATE COOP	Elva		417	1952*	411:
	STATE CORPOR	TION ED 2	/	<u></u>		
	APR	COMMISS		> \		
	CONSERVATI Wichita	1970	<i>γγ</i>	<u> </u>		
	WAT	ON O		ļ		<u></u>
	Wichita	Kana				
		"'Isas	<u>i</u>	<u> </u>	ļ	1
Checked hole		gged up ov	er $4\frac{1}{2}$ ", ed junk	shot pipea rack, lowe	t 410°, pi	p e nd
feet for each plug so Checked holo came losse. racked unit 35 sacks cei	et. e to 1600°, ri Pulled 14 jo	gged up ov ints, load ed 2 sacks mud, 25 sa	er $4\frac{1}{2}$ ", ed junk hulls,	shot pipea rack, lowe 10 sacks c	t 410°, pi red mast a	pe nd acks mud,
feet for each plug so Checked holo came losse. racked unit 35 sacks cei	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks	gged up ov ints, load ed 2 sacks mud, 25 sa	er $4\frac{1}{2}$ ", ed junk hulls,	shot pipea rack, lowe 10 sacks c	t 410°, pi red mast a	pe nd acks mud,
feet for each plug so Checked holo came losse. racked unit 35 sacks cei	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well.	gged up ov ints, load ed 2 sacks mud, 25 sa	er $4\frac{1}{2}$ ", ed junk hulls,	shot pipea rack, lowe 10 sacks c	t 410°, pi red mast a	pe nd acks mud,
Checked hole came losse. racked unit 35 sacks cer of cement to	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well.	gged up ov ints, load ed 2 sacks mud, 25 sa	er $4\frac{1}{2}$ ", ed junk hulls,	shot pipea rack, lowe 10 sacks c	t 410°, pi red mast a	pe nd acks mud,
Checked hole came losse. racked unit 35 sacks cer of cement to	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well.	gged up ov ints, load ed 2 sacks mud, 25 sa	er $4\frac{1}{2}$ ", ed junk hulls,	shot pipea rack, lowe 10 sacks c	t 410°, pi red mast a	pe nd acks mud,
Checked hole came losse. racked unit 35 sacks cer of cement to	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well.	gged up ov ints, load ed 2 sacks mud, 25 sa	er $4\frac{1}{2}$ ", ed junk hulls,	shot pipea rack, lowe 10 sacks c	t 410°, pi red mast a	pe nd acks mud,
Checked hole came losse. racked unit 35 sacks cer of cement to	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well.	gged up ov ints, load ed 2 sacks mud, 25 sa	er $4\frac{1}{2}$ ", ed junk hulls,	shot pipea rack, lowe 10 sacks c	t 410°, pi red mast a	pe nd acks mud,
Checked hole came losse. racked unit 35 sacks cer of cement to	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well.	gged up ov ints, load ed 2 sacks mud, 25 sa	er $4\frac{1}{2}$ ", ed junk hulls,	shot pipea rack, lowe 10 sacks c	t 410°, pi red mast a	pe nd acks mud,
Checked hole came losse. racked unit 35 sacks cer of cement to	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well.	gged up ov ints, load ed 2 sacks mud, 25 sa	er $4\frac{1}{2}$ ", ed junk hulls,	shot pipea rack, lowe 10 sacks c	t 410°, pi red mast a	pe nd acks mud,
Checked hole came losse. racked unit 35 sacks cer of cement to	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well.	gged up ov ints, load ed 2 sacks mud, 25 sa	er $4\frac{1}{2}$ ", ed junk hulls,	shot pipea rack, lowe 10 sacks c	t 410°, pi red mast a	pe nd acks mud,
Checked hole came losse. racked unit 35 sacks cer of cement to	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well.	gged up ov ints, load ed 2 sacks mud, 25 sa	er $4\frac{1}{2}$ ", ed junk hulls,	shot pipea rack, lowe 10 sacks c	t 410°, pi red mast a	pe nd acks mud,
Checked hole came losse. racked unit 35 sacks cer of cement to	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well.	gged up ov ints, load ed 2 sacks mud, 25 sa	er $4\frac{1}{2}$ ", ed junk hulls,	shot pipea rack, lowe 10 sacks c	t 410°, pi red mast a	pe nd acks mud,
Checked hol- came losse. racked unit 35 sacks cer of cement to	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well.	gged up ov ints, load ed 2 sacks mud, 25 sa	er $4\frac{1}{2}$ ", ed junk hulls,	shot pipea rack, lowe 10 sacks c	t 410°, pi red mast a	pe nd acks mud,
Checked hole came losse. racked unit 35 sacks cer of cement to	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well. MPLETE.	gged up ov ints, load ed 2 sacks mud, 25 sa	er 4½", ed junk hulls, cks ceme	shot pipea rack, lowe 10 sacks c nt, 5 sack	t 410°, pi red mast a	pe nd acks mud,
Checked hole came losse. racked unit 35 sacks cer of cement to	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well. MPLETE.	gged up ov ints, load ed 2 sacks mud, 25 sa	er 4½", ed junk hulls, cks ceme	shot pipea rack, lowe 10 sacks c nt, 5 sack	t 410°, pi red mast a ement, 4 s s mud and	pe nd acks mud,
Checked hold came losse. racked unit 35 sacks cell of cement to PLUGGING COI	et. e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well. MPLETE. (If additional KNIGHT	gged up ov ints, load ed 2 sacks mud, 25 sac	er 4½", ed junk hulls, cks ceme	shot pipea rack, lowe 10 sacks c nt, 5 sack	t 410°, pi red mast a ement, 4 s s mud and	pe nd acks mud,
feet for each plug so Checked hold came losse. racked unit 35 sacks cel of cement to PLUGGING CO	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well. MPLETE.	gged up ov ints, load ed 2 sacks mud, 25 sac	er 4½", ed junk hulls, cks ceme	shot pipea rack, lowe 10 sacks c nt, 5 sack	t 410°, pi red mast a ement, 4 s s mud and	pe nd acks mud,
Checked hold came losse. racked unit 35 sacks cell of cement to PLUGGING COI	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well. MPLETE. (If additional KNIGHT CHASE,	gged up ov ints, load ed 2 sacks mud, 25 sa description is neces CASING PUL	er 4½", ed junk hulls, cks ceme	shot pipea rack, lowe 10 sacks c nt, 5 sack	t 410°, pi red mast a ement, 4 s s mud and	pe nd acks mud,
Checked hold came losse. racked unit 35 sacks cell of cement to PLUGGING COI	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well. MPLETE. (If additional KNIGHT CHASE,	description is necessary of RIC	er 4½", ed junk hulls, cks ceme	shot pipea rack, lowe 10 sacks c nt, 5 sack	t 410', pi red mast a ement, 4 s s mud and	pe nd acks mud, 10 sacks
Checked hole Came losse. racked unit 35 sacks cer of cement to PLUGGING COI ame of Plugging Contractor ddress TATE OF KANSA	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well. MPLETE. (If additional KNIGHT CHASE,	description is necessary of ANSAS	er 4½", ed junk hulls, cks ceme	shot pipea rack, lowe 10 sacks c nt, 5 sack	t 410', pi red mast a ement, 4 s s mud and , ss. er or operator)	pe nd acks mud, 10 sacks of the above-describes
TATE OF KANS	et. e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well. MPLETE. (If additional KNIGHT CHASE, AS NOEL J. KNI says: That I have kni	description is necestable CASING PULKANSAS NTY OF RICONT CONTROL CONT	er 4½", ed junk hulls, cks ceme sary, use BACI LING CO.	shot pipea rack, lowe 10 sacks c nt, 5 sack (of this sheet) , INC.	t 410', pi red mast a ement, 4 s s mud and , ss. er or operator)	pe nd acks mud, 10 sacks of the above-describes
Checked hole Came losse. racked unit 35 sacks cer of cement to PLUGGING COI ame of Plugging Contractor ddress TATE OF KANSA	et. e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well. MPLETE. (If additional KNIGHT CHASE, AS NOEL J. KNI says: That I have kni	description is necestable CASING PULKANSAS NTY OF RICONT CONTROL CONT	er 4½", ed junk hulls, cks ceme sary, use BACI LING CO.	shot pipea rack, lowe 10 sacks c nt, 5 sack (of this sheet) , INC.	t 410', pi red mast a ement, 4 s s mud and , ss. er or operator)	pe nd acks mud, 10 sacks of the above-describes
TATE OF KANS	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well. MPLETE. (If additional KNIGHT CHASE, AS NOEL J. KNI says: That I have kno	description is necessary of the correct. So here	er 4½", ed junk hulls, cks ceme sary, use BACI LING CO.	shot pipea rack, lowe 10 sacks c nt, 5 sack (of this sheet) , INC.	t 410', pi red mast a ement, 4 s s mud and , ss. er or operator)	pe nd acks mud, 10 sacks of the above-describes
TATE OF KANS	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well. MPLETE. (If additional KNIGHT CHASE, AS NOEL J. KNI says: That I have kno	description is necestable CASING PULKANSAS NTY OF RICONT CONTROL CONT	er 4½", ed junk hulls, cks ceme sary, use BACI LING CO.	shot pipea rack, lowe 10 sacks c nt, 5 sack (of this sheet) , INC.	t 410°, pi red mast a ement, 4 s s mud and , ss. er or operator) s herein contain	pe nd acks mud, 10 sacks of the above-describes
TATE OF KANS	e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well. MPLETE. (If additional KNIGHT CHASE, AS NOEL J. KNI says: That I have kno	description is necessary of the correct. So here	er 4½", ed junk hulls, cks ceme sary, use BACI LING CO.	shot pipearack, lower lo sacks cont, 5 sacks	t 410°, pi red mast a ement, 4 s s mud and , ss. er or operator) s herein contain KANSAS	pe nd acks mud, 10 sacks of the above-describes
TATE OF KANS	et. e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well. MPLETE. (If additional KNIGHT CHASE, AS NOEL J. KNI says: That I have kni the same are true an	description is neces CASING PUL KANSAS NTY OF RIC GHT (cowledge of the id correct. So h	er 4½", ed junk hulls, cks ceme sary, use BACK LING CO.	shot pipea rack, lowe 10 sacks c nt, 5 sack of this sheet) , INC.	t 410', pi red mast a ement, 4 s s mud and , ss. er or operator) s herein contain KANSAS	of the above-described and the log of the
Checked hole came losse. racked unit 35 sacks cer of cement to PLUGGING COI PLUGGING COI TATE OF KANSA Tell, being first duly sworm on oath, a bove-described well as filed and that	et. e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well. MPLETE. (If additional KNIGHT CHASE, AS NOEL J. KNI says: That I have kni the same are true an	description is necessary of the correct. So here	er 4½", ed junk hulls, cks ceme sury, use BACI LING CO.	shot pipearack, lowers losacks cont, 5 sacks cont, 6 c	t 410°, pi red mast a ement, 4 s s mud and , ss. er or operator) s herein contain KANSAS	of the above-described and the log of the
TATE OF KANS	et. e to 1600', ri Pulled 14 jo Allied pump ment, 3 sacks o plug well. MPLETE. (If additional KNIGHT CHASE, AS NOEL J. KNI says: That I have kni the same are true an	description is neces CASING PUL KANSAS NTY OF RIC GHT (cowledge of the id correct. So h	er 4½", ed junk hulls, cks ceme sury, use BACI LING CO.	shot pipea rack, lowe 10 sacks c nt, 5 sack of this sheet) , INC.	t 410°, pi red mast a ement, 4 s s mud and , ss. er or operator) s herein contain KANSAS	of the above-described and the log of the