

DATE 7-20-98

- New Situation
- Response to Request
- Follow-up

OPERATOR Dennis F Roberts #

NAME & ADDRESS \_\_\_\_\_

LOCATION N/2-N/2-NE/4 SEC 23, T 19 S, R 29 W <sup>1/4</sup>

LEASE Hansen Well # 1

PHONE NO. \_\_\_\_\_  
OPER. \_\_\_\_\_ OTHER \_\_\_\_\_

COUNTY Lane

REASON FOR INVESTIGATION: (ALT. # competition)

Elevation K.B. 2826 GL 2818 Elevation 2818'  
T.D. Deciles 4650' Logger T.D. 4554 S.S @ 4650'

PROBLEM: \_\_\_\_\_

LEASE INSPECTION

PERSON(S) CONTACTED: Tom Larson (Consultant on Job)

FINDINGS: 8 1/2" @ 206.10 w/ 150 sx, 5 1/2" @ 4620' TOC  
@ 3550', Port Colloc @ 2146', Allied pressure tested to  
1500', opened port colloc had circulation started cement  
pump total 250 sx 65/35 8% w/ 1/4" Flow Seal  
circulated to surface.

COMPLAINT

JUL 23 1998  
 7-23-98

photos taken: \_\_\_\_\_

ACTION/RECOMMENDATIONS: Starting Time 9:00  
Completion Time 12:00

FIELD REPORT

Retain 1 copy Joint District Office  
Send 1 copy Conservation Division

By Kevin D Strube  
PIAT II