

KCC OIL/GAS REGULATORY OFFICE

DATE: 12/23/93

[] New Situation
[X] Response to Request
[] Follow-Up

LOCATION S/2 SW SW, SEC 14, T 19 S, R 22W

OPERATOR: Richlan Drilling

LICENSE #: 31086

ADDRESS: 598 2nd Ave.

LEASE/WELL NUMBER: Martin #1

ADDRESS: Beaver, KS 67517

COUNTY: Ness

PHONE #: 316-587-3605

API # 15-135-23768-0000

LEASE INSPECTION: <u> </u>	COMPLAINT: <u> </u>	FIELD REPORT: <u> X </u>
-------------------------------	------------------------	----------------------------

REASON FOR INVESTIGATION: The company requested a witness to the Alternate II cementing job.

PROBLEM: The Alternate II cementing requirements had not been met.

PERSONS CONTACTED: Rick Schreiber

FINDINGS: The port collar at 1460' was opened. Halliburton pumped Halliburton lite cement back to surface from 1460'. The job circulated 15 bbl. of cement to the pit.

PHOTOS TAKEN:

ACTION/RECOMMENDATIONS: The Alternate II cement job was completed successfully. Case closed.

RECEIVED
STATE CORPORATION COMMISSION
JAN 03 1994

BY Richard W. Lacey
12/23/93

