
STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission
211 No. Broadway
Wichita Konge

WELL PLUGGING RECORD

¥ 3 €

Wichita, Kansas NORTH	Location as "N Lease Owner_ Lease Name _		or footage fron	n lines C	NW NW	(E) 34 $(W$
•			タイプ ヘー・レヘナス			
	Lease Name _		ATCG LGC	LOTERM COM	pany	
	i		7.17		_	Well No.
		Box 1098		<u>ral, Kansa</u>	Dry Hole	
-	1	Well (completed :	as Oil, Gas or	Dry Hole)	July 7.	19 62
1 1 1	Date well con	- 1			July 7.	19 62
i		r plagging filed r plagging approv			Oury 19	19
		r progging approv	•		July 7.	19 62
	Plugging com		-		July 8	19 62
		indonment of wel	l or producing	formation -	Dry Hole	
i l	If a producing	well is abandon	ed, date of las	st production_		19
	Was permission	n obtained from	the Conserva	tion Division o		ore plugging was con
Locate well correctly on above Section Plat	menced?	Yes - Mr.				2.
me of Conservation Agent who	supervised plugging of the	is well Mr.	<u>Hugh Scot</u>	t t - _	Liberal,	
ducing formation None					Total Depth of	Well <u>5710</u> Fe
w depth and thickness of all w	rater, oil and gas formation	ons.				
OIL, GAS OR WATER REC	ORDS				(CASING RECORD
			1		<u> </u>	i
FORMATION	CONTENT	FROM	100	SIZE	PUT IN	PULLED OUT
Toronto Lansing	Saltwater Nothing	4070	4095	8-5/8	1881	None
Lansing Marmaton	Nothing Nothing	4477 4846	4490 4857		 	
St. Gen.	Nothing	5492	5505	· · · · · · · · · · · · · · · · · · ·	 	
one delle	MOOUTHE)47 <u>~</u>		.		
,	•					
· · · · · · · · · · · · · · · · · · ·		<u> </u>	 		 	ļ
		ľ				
Spotted heavy m Spotted 70 sx c Spotted heavy m	f cement or other plugs way set. ud through drill ement through drud through drud through drill	pipe 5 ill pipe 2 pipe 2	710 - to-2800 ! -	2800 • 2575 • 1900 •	•	
Spotted heavy m Spotted heavy m Spotted heavy m Spotted 10 sx c Spotted 10 sx c Spotted heavy m Spotted 20 sx c	f cement or other plugs way set. ud through drill ement through dr	pipe 5 ill pipe 2 ill pipe 2 ill pipe 1 pipe 1	710'-to-2800'-to-2575'-to-2875'-to-600'-to-600'-to-	2800 2800 2800 2800 2800 2800 2800 2800	•	
Spotted heavy m Spotted heavy m Spotted 70 sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted 20 sx c Spotted heavy m	f cement or other plugs way set. ud through drill ement through drill ement through drill ement through drill ud through drill ud through drill	pipe 5 ill pipe 6 pipe 6 ill pipe 7 ill pipe 1 pipe 1 ill pipe 1	710'-to- 2800'-to- 2575'-to- 900'-to- 600'-to- 540'-to-	2800 2800 2800 2800 2800 2800 2800 2800	•	
Spotted heavy m Spotted heavy m Spotted 70 sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted 20 sx c Spotted heavy m	f cement or other plugs way set. ud through drill ement through drud through drill ud through drill	pipe 5 ill pipe 6 pipe 6 ill pipe 7 ill pipe 1 pipe 1 ill pipe 1	710'-to- 2800'-to- 2575'-to- 900'-to- 600'-to- 540'-to-	2800 1 2875 1 1900 1 1875 1 600 1 20 1	•	
Spotted heavy m Spotted heavy m Spotted 70 sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted 20 sx c Spotted heavy m	f cement or other plugs way set. ud through drill ement through drud through drill ud through drill	pipe 5 ill pipe 6 pipe 6 ill pipe 7 ill pipe 1 pipe 1 ill pipe 1	710'-to- 2800'-to- 2575'-to- 900'-to- 600'-to- 540'-to-	2800 1 2875 1 1900 1 1875 1 600 1 20 1	•	
Spotted heavy m Spotted heavy m Spotted 70 sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted 20 sx c Spotted heavy m	f cement or other plugs way set. ud through drill ement through drud through drill ud through drill	pipe 5 ill pipe 6 pipe 6 ill pipe 7 ill pipe 1 pipe 1 ill pipe 1	710'-to- 2800'-to- 2575'-to- 900'-to- 600'-to- 540'-to-	2800 2800 2575 1900 1875 600 540 20 Surface	th placed, from	
Spotted heavy m Spotted heavy m Spotted 70 sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted 20 sx c Spotted heavy m	f cement or other plugs way set. ud through drill ement through drud through drill ud through drill	pipe 5 ill pipe 6 pipe 6 ill pipe 7 ill pipe 1 pipe 1 ill pipe 1	710'-to- 2800'-to- 2575'-to- 900'-to- 600'-to- 540'-to-	2800 2800 2575 1900 1875 600 540 20 Surface	•	feet
Spotted heavy m Spotted heavy m Spotted 70 sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted 20 sx c Spotted heavy m	f cement or other plugs way set. ud through drill ement through drud through drill ud through drill	pipe 5 ill pipe 6 pipe 6 ill pipe 7 ill pipe 1 pipe 1 ill pipe 1	710'-to- 2800'-to- 2575'-to- 900'-to- 600'-to- 540'-to-	2800 2800 2575 1900 1875 600 540 20 Surface	th placed, from	
Spotted heavy m Spotted heavy m Spotted 70 sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted 20 sx c Spotted heavy m	f cement or other plugs way set. ud through drill ement through drud through drill ud through drill	pipe 5 ill pipe 6 pipe 6 ill pipe 7 ill pipe 1 pipe 1 ill pipe 1	710'-to- 2800'-to- 2575'-to- 900'-to- 600'-to- 540'-to-	2800 2800 2575 1900 1875 600 540 20 Surface	th placed, from	feet ion commission 0.1962
Spotted heavy m Spotted heavy m Spotted 70 sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted 20 sx c Spotted heavy m	f cement or other plugs way set. ud through drill ement drill eme	pipe 5 ill pipe 2 pipe 2 ill pipe 1 pipe 1 pipe 1 ill pipe ill pipe ill pipe	2800!-to-2800!-to-2800!-to-3875!-to-600!-to-20!-to-20!-to-	2800 2800 2575 1900 1875 600 540 20 Surface	INTE CONTURATE	ION COMMISSION - 0.1962
Spotted heavy m Spotted heavy m Spotted 70 sx c Spotted heavy m Spotted 10 sx c Spotted heavy m Spotted heavy m Spotted heavy m Spotted heavy m Spotted 10 sx c Spotted heavy m Spotted 10 sx c	f cement or other plugs way set. ud through drill ement through d	pipe ill pipe aldescription is nece	2800!-to-2800!-to-2800!-to-3875!-to-600!-to-20!-to-20!-to-	2800 2800 2575 1900 1875 600 540 20 Surface	th placed, from	ION COMMISSION - 0.1962
Spotted heavy m Spotted heavy m Spotted 70 sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted lo sx c Spotted heavy m Spotted 20 sx c Spotted heavy m	f cement or other plugs way set. ud through drill ement drill eme	pipe ill pipe	2800!-to-2800!-to-2800!-to-3875!-to-600!-to-20!-to-20!-to-	2800 2800 2575 1900 1875 600 540 20 Surface	INTE CONTURATE	ION COMMISSION - 0.1962



FORMATION RECORD

Guy chails do sha a and an Casa ang a sa		. Gu festear		resituable. (.)	ZOLO M	entrol (GE)
pomotion	Pop 1	Dollon	Pondenok		lop	Bottom
				-	,	
Shale, sand &						
gravel	0					
Sand & gravel	410					
Clay, shale & sand	590	1350				
Shale, lime &						
shells	1350					
Shale & red bed	1640					
Cement	1847					
Sand	1882		,			
Shale & shells	2100	2450				
Lime, shells &						
shale	2450					
Shale & lime	2545					•
Lime	2865					
Lime w/chalk	3567		1			
Lime	4095	4940				
Lime w/shale &						
chalk	4940	4990			į	
Lime	4990					
Lime & shale	5245	5353				
Shale & lime	5353	5505				
Lime	5505	5580				
Lime & shale	5580	5590			i	
Lime	5590	5710				
T.D.	5710	1	_	1 a		
			. 3 🕅	L'ESION		
			an be sold a	Mille		
			Co grandis ve	ران		
			BEE GOODEN	1300	$^{\prime}O_{L_{f}}$	
			15 00 1.	1110	310	
		e(RECORPORATION OF	UN VES	3	
			Avo	Un Kau		
			RE CORPORATION CONSERVA	ito.		
į.			COL. MIC	1		ı
				ļ		