

KCC OIL/GAS REGULATORY OFFICES

Date: 02/02/16

District: 02

Case #: _____

- | | |
|---|--|
| <input type="checkbox"/> New Situation | <input checked="" type="checkbox"/> Lease Inspection |
| <input checked="" type="checkbox"/> Response to Request | <input type="checkbox"/> Complaint |
| <input checked="" type="checkbox"/> Follow-Up | <input checked="" type="checkbox"/> Field Report |

Operator License No: 32887

API Well Number: 15-191-19060-00-00

Op Name: Endeavor Energy Resources, LP

Spot: _____ Sec _____ Twp 35 S Rng 2 E W

Address 1: 110 N Marienfeld, Ste. 200

Feet from N S Line of Section

Address 2: _____

Feet from E W Line of Section

City: Midland

GPS: Lat: _____ Long: _____ Date: _____

State: TX Zip Code: 79701 -

Lease Name: Anderson Woods/Lawson Dean Well #: 8

Operator Phone #: (918) 467-3111

County: Sedgwick

Reason for Investigation:

Operator ordered by Wichita Legal Staff.

Problem:

Well(s) on Operators well inventory were listed as plugged and abandoned, yet no historical documentation to support this status can be found.

Persons Contacted:

Gus Meyers-Field Supervisor
Bruce Locke-Contracted Landman

Findings:

On January 27th 2016, I Dan Fox-Compliance Officer met with Endeavor Energy Resources, LP. field personnel at the Anderson Woods #8, API#15-191-19060-00-00. We conducted three different inspection digs, and based on our best professional estimates of three different GPS locations, and attempts to find top of well below the surface with a metal detector. We could find nothing. Endeavor provided a backhoe and dug out about a 30' X 40' and 6' deep hole(s) to find the well(s), with no success, we could not find any sign and any well(s) or any oil and gas plugging operation(s) in the area of last known location. Also attempted to expose the Lawson Dean B #1 API# 15-191-19062-00-00, and the Lawson Dean B #2 API#15-191-19061-00-00, all in the same manner and results were the same at all locations no signs of any oil and gas well(s)

Action/Recommendations:

Follow Up Required Yes No

Date: _____

No further action needed by Endeavor Energy Resources, LP to find these well(s). I recommend the KCC consider the matter of the above stated well(s) insufficiently plugged closed, and all reasonable attempts have been made to access the status of these well(s). I recommend the KCC data base show wells as plugged and abandoned with no plugging documentation, field attempts were made to find the well(s) with no success.

Verification Sources:

Photos Taken: Yes

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> RBDMS | <input checked="" type="checkbox"/> KGS | <input checked="" type="checkbox"/> TA Program |
| <input type="checkbox"/> T-I Database | <input checked="" type="checkbox"/> District Files | <input type="checkbox"/> Courthouse |
| <input type="checkbox"/> Other: <u>Google earth photos, GPS locations. Metal detector.</u> | | |

By: Daniel K. Fox-Compliance Officer

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

Form: _____