KCC OIL/GAS REGULATORY OFFICES

Inspection	Date	11/28/2016	Dist	rict: 3	lz	Incident Number: 5589				
			☑ New Situa	ition	Lease	Inspec	tion			
			[] Response	to Reques	Comp	laint				
			[] Follow-up		লৈ Field F	Report				
Operator Li	cense	No: 32851	API:	15-0	01-02688-00	0-00	Q3 (NE Q	2: SE	Q1: SW
•			eum Operating	g, L SEC	3 TWP	24	RGE	18	RGE	DIR E
		AMINO DEL	OESTE					FSL:		1100
•	akersfie	eld ip Code: 93	300	Lease:	Cross			FEL: No.:	8 P	3070
Phone cont		(661) 832		Lease.	CIUSS	Cou	nty:		o r	
Reason for		, ,								
Well #8P is p 09017.	oast du	e for a Mech	anical Integrity	y Test. Ope	erator can't k	ocale w	ell. W	ell is d	n Dock	cet #E-
Problem:										
	ent at th	ne location g	iven in RBDM	S.						
Persons co	ntacter	4.								
Randy Stanle			55-9884							
(10110) 010111	-), p	(P4.)								
Findings:										
where well #8 and Longitude	P was and a No we location	suppose to to didded them to all was present and he hall here the well	was suppose	converted that. We went and. Mr. Stand that thimself. to be locate	e given foots to the locati inley stated i We used a d. The oper	ages fro on whe lhal he metal d rator du	om RE re wel never letecto g arou	BDMS in the second seco	into Lat vas sur nbers a located ose four	itude opose a well l four
Actions / Rec	ommei	ndation	Follow-uj	Required	(L)	<u>Deadli</u>	ne Da	ite:		
will refer my t well be remove since no well c	ed from	Docket #E-								
							•			
					pı	noto's T	Taban			0
7 RBDMS	I] K	35 []	TA DBF	Report	repared By		n M. [•	J
					_			<u> </u>		
T1 DBF	ا∏ نحت	strict Files	Courthou	se Pos	ition:	E.C.	<u>K.S.</u>			