STATE OF KANSAS STATE CORPORATION COMMISSION



## WELL PLUGGING RECORD

ive All Information Completely		λ.		COTRO DE		
lake Required Affidavit  [ail   Deliver Report to:		WE	SLL PLU	IGGING RE	CORD	
aservation Division c Corporation Commission No. Broadway	K <b>i</b> •w	•		1.	300	
vichita, Kansas		E/CNW%SW%" o				$\underline{\qquad} (E) \underline{\qquad} (W)$
NORTH	Location as N Lease Owner_				any	
	Lease Name _					
ļ ļ i		Box	287 - G	t. Bend. I	Kansas	
- <del>-</del>	—— Character of V	Vell (completed a	ıs Oil. Gas o	Dry Hole)	Dry Hole	
i   i	Date well com	pleted <u>F</u>	ebruary	<u>13.</u>		19_ <b>62</b> _
	Application for	plugging filed		Februar	ry 14	19_62_
	Application for	plugging approve	ed	Februs	ary 16.	19 62
	Plugging comm	nenced	<del></del>	repri	lary 21	19 62
	Plugging comp	leted		repro	D 2	
<u> </u>	Reason for aba	ndonment of well	or producing	g formation	рку поте	
1 ! !	If a producing	well is abandons	d data of la	at maduation	<b>*</b> = = = =	=====9
						e plugging was com-
Locate well correctly on above Section Plat	menced?		me Conserv	ALLOH OIVISION OF	TIS AGENCE DETOIT	e program was com-
Name of Conservation Agent who s			red_Hamp	el		
Producing formation		Depth to top	Botton	·	Total Depth of W	VellFeet
Show depth and thickness of all wa					-	
or ore on warmen need	NDT).C				0	ASING RECORD
OIL, GAS OR WATER RECO	M1/3	<del></del>		1		ASING RECORD
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	PULLED OUT
Heebner	Dry	4146		8 5/811	4081	None
Toronto	tt	4168		4½ <sup>th</sup>	5054	2800*
Brown Lime	17	4326				
LKC	17	4341			<del></del>	<del></del>
Base LKC		4706 4732				<u> </u>
Marmaton Cherokee	11	4732				
<u>Mississippian</u>	11	4970		-		· <del> · · · · · · · · · · · · · · · · ·</del>
in introducing it into the hole. Iffeet for each pluSet_cast_i	cement or other plugs wg set.  ron brige plug a	vere used, state the	le character o	of same and depth	h placed, from	feet to
set east i:  Dumped 5 s:  at 2787*	cement or other plugs wg set.  ron brige plug ax. cement to 44.  Mudded hole to	at 4530° P. 50° Shot	lugged b casing a rock bri	ack from 45 t 44082 - 4 dge to 3402	530 to 4500 245 - 408 4 Dumped 20	O with rock. 3 Pipe loos 0 sx. cement
Set cast i  Dumped 5 st at 2787*.	cement or other plugs wg set.  ron brige plug ax. cement to 44	ere used, state the state that 4530 P. Shot of State and set rock	lugged b casing a rock bri	ack from 45 t 44082 - 4 dge to 3402	530* to 450 245* - 408 2 Dumped 2	O with rock. 3 Pipe loos 0 sx. cement
Set cast i  Dumped 5 st at 2787*.	cement or other plugs wg set.  ron brige plug ax, cement to 44  Mudded hole to Mudded to 40° ax	ere used, state the state that 4530 P. Shot of State and set rock	lugged b casing a rock bri	ack from 45 t 44082 - 4 dge to 3402 to 302. Du	530* to 450 245* - 408 2 Dumped 2	O with rock. 3 Pipe loos 0 sx. cement
Set cast i  Dumped 5 st at 2787*.	cement or other plugs wg set.  ron brige plug ax, cement to 44  Mudded hole to Mudded to 40° ax	ere used, state the state that 4530 P. Shot of State and set rock	lugged b casing a rock bri	ack from 45 t 44082 - 4 dge to 3402 to 302. Du	530* to 450 245* - 408 2 Dumped 2	O with rock. 3 Pipe loos 0 sx. cement
Set cast i  Dumped 5 st at 2787*.	cement or other plugs wg set.  ron brige plug ax, cement to 44  Mudded hole to Mudded to 40° ax	ere used, state the state that 4530 P. Shot of State and set rock	lugged b casing a rock bri	ack from 45 t 44082 - 4 dge to 3402 to 302. Du	530* to 450 245* - 408 2 Dumped 2	O with rock. 3 Pipe loos 0 sx. cement
Set cast i  Dumped 5 st at 2787*.	cement or other plugs wg set.  ron brige plug ax, cement to 44  Mudded hole to Mudded to 40° ax	ere used, state the state that 4530 P. Shot of State and set rock	lugged b casing a rock bri	ack from 45 t 44082 - 4 dge to 3402 to 302. Du	530* to 450 245* - 408 2 Dumped 2	O with rock. 3 Pipe loos 0 sx. cement
Set cast i  Dumped 5 st at 2787*.	cement or other plugs wg set.  ron brige plug ax, cement to 44  Mudded hole to Mudded to 40° ax	ere used, state the state that 4530 P. Shot of State and set rock	lugged b casing a rock bri	ack from 45 t 44082 - 4 dge to 3402 to 302. Du	530* to 450 245* - 408 2 Dumped 2	O with rock. 3 Pipe loos 0 sx. cement
Set cast i  Dumped 5 st at 2787*.	cement or other plugs wg set.  ron brige plug ax, cement to 44  Mudded hole to Mudded to 40° ax	ere used, state the state that 4530 P. Shot of State and set rock	lugged b casing a rock bri	ack from 45 t 44082 - 4 dge to 3402 to 302. Du	530* to 450 245* - 408 2 Dumped 2	O with rock. 3 Pipe loos 0 sx. cement
Set cast i  Dumped 5 st at 2787*.	cement or other plugs wg set.  ron brige plug ax, cement to 44  Mudded hole to Mudded to 40° ax	ere used, state the state that 4530 P. Shot of State and set rock	lugged b casing a rock bri	ack from 45 t 4408? - 4 dge to 340? to 30?. Du	b placed, from  530 to 450  245 - 408  Dumped 20  Imped 10 sx	O' with rock. 3'. Pipe loos 0 sx. cement . cement in
Set cast i  Dumped 5 st at 2787*.	cement or other plugs wg set.  ron brige plug ax, cement to 44  Mudded hole to Mudded to 40° ax	ere used, state the state that 4530 P. Shot of State and set rock	lugged b casing a rock bri	ack from 45 t 4408? - 4 dge to 340? to 30?. Du	b placed, from  530 to 450  245 - 408  Dumped 20  Imped 10 sx	O' with rock. 3'. Pipe loos 0 sx. cement . cement in
Set cast i  Dumped 5 st at 2787*.	cement or other plugs wg set.  ron brige plug ax, cement to 44  Mudded hole to Mudded to 40° ax	ere used, state the state that 4530 P. Shot of State and set rock	lugged b casing a rock bri	ack from 45 t 4408? - 4 dge to 340? to 30?. Du	530* to 450 245* - 408 2 Dumped 2	O' with rock. 3'. Pipe loos 0 sx. cement . cement in
Set cast i  Dumped 5 st at 2787*.	cement or other plugs wg set.  ron brige plug ax, cement to 44  Mudded hole to Mudded to 40° ax	ere used, state the state that 4530 P. Shot of State and set rock	lugged b casing a rock bri	ack from 45 t 4408? - 4 dge to 340? to 30?. Du	b placed, from  530 to 450  245 - 408  Dumped 20  Imped 10 sx	O' with rock. 3'. Pipe loos 0 sx. cement . cement in
Set cast i  Dumped 5 st at 2787*.	cement or other plugs wg set.  ron brige plug ax, cement to 44  Mudded hole to Mudded to 40° ax	ere used, state the state that 4530 P. Shot of State and set rock	lugged b casing a rock bri	ack from 45 t 4408? - 4 dge to 340? to 30?. Du	b placed, from  530 to 450  245 - 408  Dumped 20  Imped 10 sx	of with rock.  3: Pipe loos  0 sx. cement  cement in
Set cast i  Dumped 5 st at 2787*.	cement or other plugs we get.  ron brige plug ax. cement to 44 Mudded hole to Mudded to 40 ar base of cellar.	at 4530° P. 50° Shot 350° Set ad set rock	lugged b casing a rock bri bridge	ack from 45 t 4408 - 4 dge to 340 to 301. Du	b placed, from  530 to 4500  245 - 408  Dumped 20  Imped 10 sx	O' with rock. 3'. Pipe loos 0 sx. cement . cement in
Set cast i  Dumped 5 st at 2787*.	cement or other plugs we get.  ron brige plug ax. cement to 44 Mudded hole to Mudded to 40 ar base of cellar.	at 4530° P. 50° Shot 350° Set ad set rock	lugged b casing a rock bri bridge	ack from 45 t 4408 - 4 dge to 340 to 301. Du	b placed, from  530 to 4500  245 - 408  Dumped 20  Imped 10 sx	O' with rock. 3'. Pipe loos 0 sx. cement . cement in
Set cast i:  Dumped 5 s:     at 2787 b     to 280 c     filling to	cement or other plugs we get.  ron brige plug ax. cement to 44 Mudded hole to Mudded to 40 ar base of cellar.	at 4530° P. 50° Shot 350° Set ad set rock	lugged b casing a rock bri bridge	ack from 45 t 4408 - 4 dge to 340 to 301. Du	b placed, from  530 to 4500  245 - 408  Dumped 20  Imped 10 sx	of with rock.  3: Pipe loos  0 sx. cement  cement in
Set cast i:  Dumped 5 s:     at 2787 b     to 280 c     filling to	cement or other plugs we get.  ron brige plug ax. cement to 44 Mudded hole to Mudded to 40 ar base of cellar.	at 4530° P. 50° Shot 350° Set ad set rock  Ald set rock  Great	lugged b casing a rock bri bridge	ack from 45 t 4408 - 4 dge to 340 to 301. Du	b placed, from  530 to 4500  245 - 408  Dumped 20  Imped 10 sx	of with rock.  3: Pipe loos  0 sx. cement  cement in
Set cast i:  Dumped 5 s:     at 2787 b     to 280 c     filling to	cement or other plugs we get.  ron brige plug ax. cement to 44 Mudded hole to Mudded to 40 ar base of cellar.	at 4530° P. 50° Shot 350° Set ad set rock  Market Ca Great  UNTY OF	lugged b casing a rock bri bridge sary, use BACT sing Pul Bend, Ka	ack from 45 t 44082 - 4 dge to 3402 to 302. Du	b placed, from  530 to 4500  245 - 408  Dumped 10 sx  ECONOMICATION  CONSTRUCTOR  TEB 2	feet to 03 with rock. 31. Pipe loos 0 sx. cement 10 cement in 1962
Set cast i:  Dumped 5 s:     at 2787 b     to 280 c     filling to	cement or other plugs we get.  ron brige plug ax. cement to 44 Mudded hole to Mudded to 40 ar base of cellar (If addition)  (If addition)	at 4530° P. 50° Shot 350° Set ad set rock  Might Ca Great	lugged b casing a rock bri bridge ssary, use BACC sing Pul Bend, Ka	ack from 45 t 44082 - 4 dge to 3403 to 302. Du  Gof this sheet) ling Compar nsas.	placed, from  530 to 4500  245 - 408  Dumped 20  Imped 10 sx  ECONOMICATION  SS.  SS.	feet to the state of the above-describe
Set east i:  Dumped 5 s:  at 2787.  to 280.  filling to  Name of Plugging Contractor  Address  STATE OF KANSAS	cement or other plugs we get.  ron brige plug ax. cement to 44.  Mudded hole to Mudded to 40 are base of cellar.  (If addition	at 4530° P. 50° Shot 350° Set ad set rock  Ald set rock  WNTY OF  nowledge of the	lugged b casing a rock bri bridge ssary, use BACE sing Pul Bend, Ka BARTON employee of facts, statem	ack from 45 t 44082 - 4 dge to 3403 to 302. Du  of this sheet) ling Compar nsas.  owner) or (owners, and matter	placed, from  530 to 4500  245 - 408  Dumped 20  Imped 10 sx  ECONOMICATION  SS.  SS.	feet to the state of the above-describe
Set east i:  Set east i:  Dumped 5 s:  at 2787. J  to 280. J  filling to  Name of Plugging Contractor  Address  STATE OF KANSAS  well, being first duly sworn on oa	cement or other plugs we get.  ron brige plug ax. cement to 44.  Mudded hole to Mudded to 40 are base of cellar.  (If addition	at 4530° P. 50° Shot 350° Set ad set rock Knight Ca Great UNTY OF  (nowledge of the	lugged b casing a rock bri bridge ssary, use BACE sing Pul Bend, Ka BARTON employee of facts, statem	ack from 45 t 44082 - 4 dge to 3403 to 302. Du  of this sheet) ling Compar nsas.  owner) or (owners, and matter	placed, from  530 to 4500  245 - 408  Dumped 20  Imped 10 sx  ECONOMICATION  SS.  SS.	feet to the state of the above-describe
Set east i:  Set east i:  Dumped 5 s:  at 2787. J  to 280. J  filling to  Name of Plugging Contractor  Address  STATE OF KANSAS  well, being first duly sworn on oa	cement or other plugs we get.  ron brige plug ax. cement to 44.  Mudded hole to Mudded to 40 are base of cellar.  (If addition	at 4530° P. 50° Shot 350° Set ad set rock  Ald set rock  WNTY OF  nowledge of the	lugged becasing a rock bridge bridge bridge BARTON Employee of facts, statem help me God	ack from 45 t 44082 - 4 dge to 3402 to 302. Du  of this sheet) ling Compar nsas.  owner) or (owners, and matter	placed, from  530 to 4500  245 - 408  Dumped 20  Imped 10 sx  FEB 3 (1)  CONSTRUCTION  Service (1)  The serv	feet to 3 with rock.  3 Pipe loos  O sx. cement  cement in  1962  1962  The above-describe ed and the log of the
Set east i:  Set east i:  Dumped 5 s:  at 2787. J  to 280. J  filling to  Name of Plugging Contractor  Address  STATE OF KANSAS  well, being first duly sworn on oa	cement or other plugs we get.  ron brige plug ax. cement to 44.  Mudded hole to Mudded to 40 are base of cellar.  (If addition	at 4530° P. 50° Shot 350° Set ad set rock Knight Ca Great UNTY OF  (nowledge of the	lugged becasing a rock bridge bridge bridge BARTON Employee of facts, statem help me God	ack from 45 t 44082 - 4 dge to 3402 to 302. Du  for this sheet) ling Compar nsas.  owner) or (owners, and matter	placed, from  530* to 4500  245* - 408  Dumped 20  Imped 10 sx  ECONOMICATION  FEB 2.4  Service (Contained)  Bend, Kan	feet to 3 with rock.  3 Pipe loos  O sx. cement  cement in  1962  1962  The above-describe ed and the log of the
Set cast i:    Dumped 5 s:   at 2787;     to 280;     filling to     Set cast i:   Dumped 5 s:   at 2787;     to 280;     filling to     Set cast i:   Dumped 5 s:   at 2787;     to 280;     filling to     Set cast i:   Sumped 5 s:   at 2787;     to 280;     Set cast i:   Sumped 5 s:   at 2787;     to 280;     Set cast i:   Sumped 5 s:   at 2787;     to 280;     Set cast i:   Sumped 5 s:   at 2787;     to 280;     set cast i:   Set cast i:   Sumped 5 s:   at 2787;     to 280;     set cast i:   Sumped 5 s:   at 2787;     set cast i:   Sumped 5 s:   set cast i:   set cast i:	cement or other plugs we get.  ron brige plug ax. cement to 44 Mudded hole to Mudded to 40 and base of cellar.  (If additional the same are true as that the same are true as set.	at 4530° P. 50° Shot 350° Set ad set rock  Market Ca Great  UNTY OF  Inowledge of the and correct. So is (Signature)	lugged b casing a rock bri bridge  ssary, use BACT sing Pul Bend, Ka  BARTON employee of facts, statem help me God	ack from 45 t 44082 - 4 dge to 3402 to 302. Du  for this sheet) ling Compar nsas.  owner) or (owners, and matter	placed, from  530 to 4500  245 - 408  Dumped 20  Imped 10 sx  FEB 3 (  CONSTRUCTION  Service (  Bend, Kan  Address)	with rock.  3. Pipe loos  0 sx. cement  cement in  1962  1962  f the above-described and the log of the
Set east i:  Set east i:  Dumped 5 s:  at 2787. J  to 280. J  filling to  Name of Plugging Contractor  Address  STATE OF KANSAS  well, being first duly sworn on oa	cement or other plugs we get.  ron brige plug ax. cement to 44 Mudded hole to Mudded to 40 and base of cellar.  (If additional the same are true as that the same are true as set.	at 4530° P. 50° Shot 350° Set ad set rock  al description is neces Knight Ca Great  UNTY OF  nowledge of the and correct. So i	lugged becasing a rock bridge bridge bridge BARTON Employee of facts, statem help me God	ack from 45 t 44082 - 4 dge to 3402 to 302. Du  for this sheet) ling Compar nsas.  owner) or (owners, and matter  x 287 - Gt.	placed, from  530* to 4500  245* - 408  Dumped 20  Imped 10 sx  ECONOMICATION  FEB 2.4  ONISTRUM  BERG, Kan  Address  15	feet to  O' with rock.  3'. Pipe loos  O sx. cement  cement in  O' with rock.  1962  O' with rock.  1962  O' with rock.  1962  O' with rock.  O' with rock.
Set cast i:  Set cast i:  Dumped 5 s:  at 2787 . ]  to 280 . ]  filling to  Name of Plugging Contractor  Address  STATE OF KANSAS  well, being first duly sworn on oar above-described well as filed and	cement or other plugs we get.  ron brige plug ax. cement to 44 Mudded hole to Mudded to 40 and base of cellar.  (If additional the same are true as that the same are true as set.	at 4530° P. 50° Shot 350° Set ad set rock  Market Ca Great  UNTY OF  Inowledge of the and correct. So is (Signature)	lugged becasing a rock bridge bridge bridge BARTON Employee of facts, statem help me God	ack from 45 t 44082 - 4 dge to 3402 to 302. Du  for this sheet) ling Compar nsas.  owner) or (owners, and matter  x 287 - Gt.	placed, from  530 to 4500  245 - 408  Dumped 20  Imped 10 sx  FEB 3 (  CONSTRUCTION  Service (  Bend, Kan  Address)	with rock.  3. Pipe loos  0 sx. cement  cement in  1962  1962  f the above-described and the log of the

## EXPLORATION RECORD

Lease \_\_\_\_ Parkin

Well

1

		<del></del>	<u> </u>
Formation Name	Тор	Base	Remarks
Sand and Clay Shale and Sand Shale and Shells Shale Shale and Shells Red Bed, Shale and Shells Anhydrite Shale and Lime Shale and Lime Shale and Lime Lime and Shale Lime Lime and Shale Lime Lime and Shale Shale and Lime Lime and Shale Shale and Lime Lime and Shale		40 100 345 409 1000 1116 1147 1200 1460 1835 2310 2580 2680 2810 3045 3210 4350 4210 4350 4755 4855 4970 5055	STATE CORPORATION COMMISSION FEB 9 7 1562 CONSERVATION DIVISION Wichita, Kansas