

165' E & 15' N of NE corner of 9th/Kirwin, Salina

Application Number:

submitted Water Well Disinfected? Yes No ☒

From ft. to ft. From ft. to ft.

FROM	TO	LITHOLOGIC LOG	FROM	TO	PLUGGING INTERVALS
0	0.5	Asphalt,			
0.5	16	Clay, silty, moist, no odor, Dark Brown			
16	20	Clay, becoming v. silty, moist, plastic, Brown t			
20	24	Sand (vf-m), moist, no odor, Lt. Brown			
24	28	Sand (vf), v. silty, moist, no odor, Brown			
28	33	Sand (vf-m), mod. old gas odor, Brown			
33	35.5	Sand (vf-m), mod. old gas odor, Gray			
35.5	36	Silt, sl. sandy (vf), strong old gas odor, Gray			
36	40	Sand (vf-c) w/f gravel, saturated, Gray			
40	45	Sand (vf-c) w/f-m gravel, saturated, Grayish B			
					SSMW4R , Tag # 00376356 , Flushmount
					Project Name: Southside Service/Sinclair - Monitoring
					GeoCore # 329 , KDHE # U5 085 00862

Karlissas Water Well Contractor's License No. 527 This Water Well Record was completed on (Friday, 11/11/2011) under the business name of GeoCore, Inc. by (signature) [Signature]