



SLOAN MEIER HANCOCK

ENGINEERS SURVEYORS

July 20, 2007

Donovan Miller
GeoCore, Inc.
PO Box 386
Salina, KS 67424-0386

Dear Donovan:

The following is the information requested on a Monitoring Well Site, Farmer's Coop, Lakin, Kearny County, Kansas.

Point	North Coord	East Coord	Distance from SE Cor. Sec. 27		Elev. Top of Rim or PK Nail	Elev. Top of PVC Pipe	Latitude North	Longitude West
			North	West				
SE Cor. S27-T24S-R36W	5000	5000						
MW 12	9251.85	3205.88	4251.85	1794.12	3003.98	3003.45	37.94156	101.25525
MW 13	9334.82	3121.64	4334.82	1878.36	3004.48	3003.96	37.94175	101.25553
MW 14	9417.87	3202.35	4417.87	1797.65	3004.80	3004.31	37.94172	101.25556
Site B.M.	9302.53	3105.10	4302.53	1894.90	B.M. Elev. = 3004.04			

Description: Square "□" cut on northeast corner of light pole base at northwest corner of property.

MW12 is in the SW/4, SE/4, NW/4, SW/4 S27-T24S-R36W
MW13 and MW14 are in the NW/4, SE/4, NW/4, SW/4 S27-T24S-R36W

If you have any questions, please do not hesitate in giving us a call.

Sincerely,

Tim Sloan

Tim Sloan,
Sloan Meier Hancock Engineers Surveyors, P.A.

