



**COMPLETION
& PRODUCTION
SERVICES CO.**

DUAL RECEIVER CEMENT BOND LOG

<<< Fold Here >>>

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.

Comments




THANK YOU FOR USING NABORS SERVICES
HAYS, KANSAS (785) 628-6395
DIRECTIONS
DUBUQUE CHURCH 1 W. - 1 S. - 1/2 W. - S. INTO




Database File: 10773grnb.db
Dataset Pathname: pass3.2
Presentation Format: cbl02
Dataset Creation: Wed Mar 20 08:38:20 2013 by Calc Std Casedhole 08121
Charted by: Depth in Feet scaled 1:240


Charted by: Depth in Feet scaled 1:2.15		
0	Gamma Ray (GAPI)	150
200	5' Travel Time (usec)	1000

0	AMP3 (mV)	100
9	CCL	-1
0	Amplified Amplitude (mV)	20

200	5FT VDL	1000
-----	---------	------










2800

2850

2900

2950







3000


3050

3100

3150



3200





3250

3300



200

5FT VDL

1000