



Borehole Compensated Sonic Log

<<< Fold Here >>>

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.


Comments



Thank you for using Pioneer Energy Services
www.pioneerres.com
785 625 3858



Quinter Ks.,
7 North to 130 Road, 1 West, 2 North, East Into.



Database File: c:\warrior\data\culbreath_coburn #6-8\culbreath_coburn_6-8hd.db
Dataset Pathname: DIL\culstk
Presentation Format: sonic
Dataset Creation: Fri Jun 13 06:33:00 2014
Charted by: Denth in Feet scaled 1:240



0	Gamma Ray	150	Sonic Int	140	Delta Time (usec/ft)	40
150	Gamma Ray	300	5	0	SPOR	-10
6	Caliper (GAPI)	16		15000	LTEN (lb)	0
						LSPD



































































0	Gamma Ray	150
150	Gamma Ray	300
6	Caliper (GAPI)	16



Sonic Int	140	Delta Time (usec/ft)	40
5	0	SPOR	-10
	15000	LTEN (lb)	0

LSPD