Stephen C. Robben

Box 426 Victoria, Kansas 67671

Phone 913-735-9405

10-19-15W

DaMar Resources, Inc.
Seeber # 1
150' S E/2-NE-NW
10/19S/15W
Barton Co., Kansas

Completion Report

8/29/85 Moved in Express Well Service. Correlation log and cement Bond log was run. P.B.T.D. 3609'. Swabbed hole dry. Perforated from 3573-80' (4/ft. SSB's). Shut well in overnight.

8/30/85 500' of fluid in hole (5' oil and 495' water).

Swab down - 12.3 BBL
1 hr. - 1.1 BBL Scum of oil
1 hr. - .8 BBL Scum of oil

Perforated from 3564-70' (4 ft. SSB's). Swab tested.

1 hr. - 1.0 BBL Scum of oil
1 hr. - .7 BBL Scum of oil

Treated zones with 300 gallons of Mud Acid (15%). Maximum pressure 1100#. Treated at ½ BPM 400#. ISIP 300#. 15 minutes 200#. Bled back 2 barrel. 95 barrel load.

Swab down - 91.7 BBL
1 hr. - 2.9 BBL Scum of oil

FEB 03 1986
State Geological Survey
WICHITA BRANCH

9/2/85 1400' of fluid in hole (50' oil and 1350' water). Did not swab down. Shut down after checking fill up.

9/3/85 1400' of fluid in hole, no oil.

Swab down - 38.4 BBL
1 hr. - 2.5 BBL Scum of oil
1 hr. - 1.7 BBL Scum of oil
1 hr. - 1.7 BBL Scum of oil

Moved off rig.

RECEIVED
STATE CORPORATION COMMISSION
DEC 3 1985
CONSERVATION DIVISION
Wichita, Kansas