

WOOLSEY OPERATING COMPANY, LLC
125 North Market, Suite 1000, Wichita, Kansas 67202
Phone: 316-267-4379 Fax 316-267-4383

KEESECKER 1

Survey: 600' FNL, 2310' FWL
Approx. S2 NE NE NW Sec 33-T34S-R11W
Barber County, Kansas

API: 15-007-23560-00-00
Elev: 1404' GL 1414' KB
Field: Stranathan NE

SUMMARY OF CEMENT IN HOLE

07/14/10 Set 5 jts 10 3/4" x 32.725# surface casing at 225'
w/ 240 sx Class A, 2% gel, 3% cc (by Allied). Plug down at 3:15 am on 07/14. Cmt did circ.

07/16/10 Set 22 jts 8 5/8" x 24#/ft intermediate surface casing at 913'
w/ 100 sx 60/40 pozmix, 2% gel, 3% cc. Plug down at 11:45 am on 07/15 (by Allied)

07/17/10 Plug deviated hole at 2065'
w/ 325 sx Common cement. 2% cc (by Basic)

07/20/10 Second plugging of deviated hole
Cement w/ 325 sx common, 2% gel. Plug down at 2 am on 7/20 (by Basic)

07/21/10 Plug and abandon
w/ 170 sx 60/40 pozmix, 4% gel: 50 sx at 930', 50 sx at 230', 20 sx at 60', 30 sx in RH, 20 sx in MH
(by Allied). 100 sx was one-inched between 10 3/4" and 8 5/8" casing. Plug down at 2:15 pm on
07/21. Steve Pfeifer, KCC agent, witnessed plugging operations.