KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION

1170423

Form CDP-5
May 2011
**Form must be Typed**

# EXPLORATION & PRODUCTION WASTE TRANSFER

Operator Name: Culbreath Oil & Gas Company, Inc.
License Number: 34344

Operator Address: 1532 S PEORIA AVE TULSA OK 74120 6202

Contact Person: Billy Schmidt
Phone Number: ( 918 ) 749 - 3508

Permit Number *(API No. if applicable)*: 15-065-23939-00-00
Lease Name: KUHN

Well Number: 1-32

Source of Waste:

- ☐ Emergency Pit
- ☐ Settling Pit
- ☐ Workover Pit
- ☑ Drilling Pit
- ☐ Burn Pit
- ☐ Haul-off Pit
- ☐ Steel Pit
- ☐ Spill / Escape
- ☐ Dike

Source Location (QQQQ): _____ - NE - NE - NE

Sec. 32 Twp. 9 R. 25 ☐ East ☑ West

330 Feet from ☑ North / ☐ South Line of Section

330 Feet from ☑ East / ☐ West Line of Section

GPS Location: Lat: _____ *(e.g. xx.xxxxx)* , Long: _____ *(e.g. -xxx.xxxxx)*

Datum: ☐ NAD27 ☐ NAD83 ☐ WGS84

County: Graham

No Waste to be Hauled: ☑ *(If checked, provide an explanation as to why no waste was hauled in the Comments area.)*

Type of waste to be disposed: ☐ Fluid ☐ Soil ☐ Mud / Cuttings ☐ Other: _____

Amount of waste: _____ No. of loads _____ Barrels _____ Tons _____ YDS

Destination of waste: ☐ Reserve Pit ☐ Haul Off Pit ☐ Disposal Well ☐ Lease Road ☐ Dike / Berm ☐ Other: _____

If waste is transferred to another reserve pit, is the lease active? ☐ Yes ☐ No

Location of Waste Disposal:

Destination Out of State: ☐ *(If checked, provide the location of where the waste was hauled in the Comments area.)*

Date of Waste Transfer: _____

Operator Name: _____ License No.: _____

Lease Name: _____ Sec. _____ Twp. _____ R. _____ ☐ East ☐ West

Docket No./API No.: _____ County: _____

Comments:

solids were allowed to settle, fluid was allowed to evaporate, solids were allowed to air dry then the drilling pits and reserve pit were pushed back in with a dozer. No drilling waste left the site.

Submitted Electronically

**Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202**