1367142

KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION

Form CDP-5
May 2011
Form must be Typed

EXPLORATION & PRODUCTION WASTE TRANSFER

Operator Name: Griffin, Charles N.
License Number: 33936
Operator Address: PO BOX 347 PRATT KS 67124 0347
Contact Person: Charles N Griffin
Phone Number: (972) 342 - 4648
Permit Number *(API No. if applicable)*: 15-007-23388-00-01
Lease Name: SHERRY
Well Number: 1-9 OWWO

Source of Waste:

- ☐ Emergency Pit
- ☐ Settling Pit
- ☐ Workover Pit
- ☑ Drilling Pit
- ☐ Burn Pit
- ☐ Haul-off Pit
- ☐ Steel Pit
- ☐ Spill / Escape
- ☐ Dike

Source Location (QQQQ): NE - NE - SW - NW
Sec. 9 Twp. 33 R. 12 ☐ East ☑ West
1619 Feet from ☑ North / ☐ South Line of Section
1198 Feet from ☐ East / ☑ West Line of Section
GPS Location: Lat: _____ *(e.g. xx.xxxxx)*, Long: _____ *(e.g. -xxx.xxxxx)*
Datum: ☐ NAD27 ☐ NAD83 ☐ WGS84
County: Barber

No Waste to be Hauled: ☑ *(If checked, provide an explanation as to why no waste was hauled in the Comments area.)*

Type of waste to be disposed: ☐ Fluid ☐ Soil ☐ Mud / Cuttings ☐ Other: _____

Amount of waste: _____ No. of loads _____ Barrels _____ Tons _____ YDS

Destination of waste: ☐ Reserve Pit ☐ Haul Off Pit ☐ Disposal Well ☐ Lease Road ☐ Dike / Berm ☐ Other: _____

If waste is transferred to another reserve pit, is the lease active? ☐ Yes ☐ No

Location of Waste Disposal:

Destination Out of State: ☐ *(If checked, provide the location of where the waste was hauled in the Comments area.)*

Date of Waste Transfer: _____

Operator Name: _____ License No.: _____

Lease Name: _____ Sec. _____ Twp. _____ R. _____ ☐ East ☐ West

Docket No./API No.: _____ County: _____

Comments:

Waste evaporated

Submitted Electronically