KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION

Form CDP-5
May 2011
Form must be Typed

EXPLORATION & PRODUCTION WASTE TRANSFER

Operator Name: O'Brien Energy Resources Corp.
License Number: 32211

Operator Address: 18 CONGRESS ST, STE 207 PORTSMOUTH NH 03801 4091

Contact Person: Joseph Forma
Phone Number: (603) 427 - 2099

Permit Number *(API No. if applicable)*: 15-119-21402-00-00
Lease Name: HUSH

Source of Waste:

- ☐ Emergency Pit
- ☐ Settling Pit
- ☐ Workover Pit
- ☐ Drilling Pit
- ☐ Burn Pit
- ☑ Haul-off Pit
- ☐ Steel Pit
- ☐ Spill / Escape
- ☐ Dike

Well Number: 3-16

Source Location (QQQQ): _____ - _____ - _____ - _____

Sec. 16 Twp. 33 R. 30 ☐ East ☑ West

330 Feet from ☑ North / ☐ South Line of Section

330 Feet from ☑ East / ☐ West Line of Section

GPS Location: Lat: _____ *(e.g. xx.xxxxx)*, Long: _____ *(e.g. -xxx.xxxxx)*

Datum: ☐ NAD27 ☐ NAD83 ☐ WGS84

County: Meade

No Waste to be Hauled: ☑ *(If checked, provide an explanation as to why no waste was hauled in the Comments area.)*

Type of waste to be disposed: ☐ Fluid ☐ Soil ☐ Mud / Cuttings ☐ Other: _____

Amount of waste: _____ No. of loads _____ Barrels _____ Tons _____ YDS

Destination of waste: ☐ Reserve Pit ☐ Haul Off Pit ☐ Disposal Well ☐ Lease Road ☐ Dike / Berm ☐ Other: _____

If waste is transferred to another reserve pit, is the lease active? ☐ Yes ☐ No

Location of Waste Disposal:

Destination Out of State: ☐ *(If checked, provide the location of where the waste was hauled in the Comments area.)*

Date of Waste Transfer: _____

Operator Name: _____ License No.: _____

Lease Name: _____ Sec. _____ Twp. _____ R. _____ ☐ East ☐ West

Docket No./API No.: _____ County: _____

Comments:

No dewatering method was required due to natural evaporation.

Submitted Electronically