KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION

Form CDP-5
May 2011
Form must be Typed

EXPLORATION & PRODUCTION WASTE TRANSFER

Operator Name: Jones, Stephen C.
License Number: 33453
Operator Address: 2332 W NEW ORLEANS BROKEN ARROW OK 74011
Contact Person: Steve Jones
Phone Number: (918) 286 - 1499
Permit Number *(API No. if applicable)*: 15-031-22118-00-00
Lease Name: OSBORN
Well Number: 1

Source of Waste:

- ☐ Emergency Pit
- ☐ Settling Pit
- ☐ Workover Pit
- ☑ Drilling Pit
- ☐ Burn Pit
- ☐ Haul-off Pit
- ☐ Steel Pit
- ☐ Spill / Escape
- ☐ Dike

Source Location (QQQQ): SE - NW - SE - SE
Sec. 29 Twp. 22 R. 14 ☑ East ☐ West
680 Feet from ☐ North / ☑ South Line of Section
710 Feet from ☑ East / ☐ West Line of Section
GPS Location: Lat: _____ *(e.g. xx.xxxxx)*, Long: _____ *(e.g. -xxx.xxxxx)*
Datum: ☐ NAD27 ☐ NAD83 ☐ WGS84
County: Coffey

No Waste to be Hauled: ☐ *(If checked, provide an explanation as to why no waste was hauled in the Comments area.)*

Type of waste to be disposed: ☑ Fluid ☐ Soil ☐ Mud / Cuttings ☐ Other: _____

Amount of waste: 0 No. of loads 0 Barrels 0 Tons 0 YDS

Destination of waste: ☐ Reserve Pit ☐ Haul Off Pit ☐ Disposal Well ☐ Lease Road ☐ Dike / Berm ☑ Other: Evaporation

If waste is transferred to another reserve pit, is the lease active? ☐ Yes ☐ No

Location of Waste Disposal:

Destination Out of State: ☐ *(If checked, provide the location of where the waste was hauled in the Comments area.)*

Date of Waste Transfer: 01/20/2006

Operator Name: Jones, Stephen C.
License No.: 33453
Lease Name: _____
Sec. 29 Twp. 22 R. 14 ☑ East ☐ West
Docket No./API No.: _____
County: Coffey

Comments:

Submitted Electronically