KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION

Form CDP-5
May 2011
Form must be Typed

EXPLORATION & PRODUCTION WASTE TRANSFER

Operator Name: Spess Oil Company, a General Partnership
License Number: 30288

Operator Address: 200 S BROADWAY CLEVELAND OK 74020 4617

Contact Person: JEFFREY SPESS
Phone Number: (918) 358 - 5831

Permit Number *(API No. if applicable)*: 15-055-22468-00-00
Lease Name: L L JONES

Source of Waste:

- [ ] Emergency Pit
- [ ] Settling Pit
- [ ] Workover Pit
- [x] Drilling Pit
- [ ] Burn Pit
- [ ] Haul-off Pit
- [ ] Steel Pit
- [ ] Spill / Escape
- [ ] Dike

Well Number: 5R

Source Location (QQQQ): E2 - SW - SE - SE

Sec. 30 Twp. 25 R. 33 [ ] East [x] West

330 Feet from [ ] North / [x] South Line of Section

975 Feet from [x] East / [ ] West Line of Section

GPS Location: Lat: _____ (e.g. xx.xxxxx), Long: _____ (e.g. -xxx.xxxxx)

Datum: [ ] NAD27 [ ] NAD83 [ ] WGS84

County: Finney

No Waste to be Hauled: [x] *(If checked, provide an explanation as to why no waste was hauled in the Comments area.)*

Type of waste to be disposed: [ ] Fluid [ ] Soil [ ] Mud / Cuttings [ ] Other: _____

Amount of waste: _____ No. of loads _____ Barrels _____ Tons _____ YDS

Destination of waste: [ ] Reserve Pit [ ] Haul Off Pit [ ] Disposal Well [ ] Lease Road [ ] Dike / Berm [ ] Other: _____

If waste is transferred to another reserve pit, is the lease active? [ ] Yes [ ] No

Location of Waste Disposal:

Destination Out of State: [ ] *(If checked, provide the location of where the waste was hauled in the Comments area.)*

Date of Waste Transfer: _____

Operator Name: _____ License No.: _____

Lease Name: _____ Sec. _____ Twp. _____ R. _____ [ ] East [ ] West

Docket No./API No.: _____ County: _____

Comments:

EVAPORATED, NONE TO BE HAULED OFF.

Submitted Electronically