KOLAR Document ID: 1582402

KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION

Form CDP-5
May 2011
Form must be Typed

EXPLORATION & PRODUCTION WASTE TRANSFER

Operator Name: Steffen Resource Development, LLC
License Number: 35666

Operator Address: 3500 N MAYFIELD RD HUTCHINSON KS 67502 9461

Contact Person: Mark Steffen
Phone Number: (620) 802 - 1188

Permit Number *(API No. if applicable)*: 15-095-22340-00-00
Lease Name: COLLEN

Source of Waste:

Well Number: 2-21

- ☐ Emergency Pit
- ☐ Settling Pit
- ☐ Workover Pit
- ☑ Drilling Pit
- ☐ Burn Pit
- ☐ Haul-off Pit
- ☐ Steel Pit
- ☐ Spill / Escape
- ☐ Dike

Source Location (QQQQ): NE - SW - SE - NW

Sec. 18 Twp. 30 R. 7 ☐ East ☑ West

3245 Feet from ☐ North / ☑ South Line of Section

1900 Feet from ☐ East / ☑ West Line of Section

GPS Location: Lat: _____ *(e.g. xx.xxxxx)* , Long: _____ *(e.g. -xxx.xxxxx)*

Datum: ☐ NAD27 ☐ NAD83 ☐ WGS84

County: Kingman

No Waste to be Hauled: ☑ *(If checked, provide an explanation as to why no waste was hauled in the Comments area.)*

Type of waste to be disposed: ☐ Fluid ☐ Soil ☐ Mud / Cuttings ☐ Other: _____

Amount of waste: _____ No. of loads _____ Barrels _____ Tons _____ YDS

Destination of waste: ☐ Reserve Pit ☐ Haul Off Pit ☐ Disposal Well ☐ Lease Road ☐ Dike / Berm ☐ Other: _____

If waste is transferred to another reserve pit, is the lease active? ☐ Yes ☐ No

Location of Waste Disposal:

Destination Out of State: ☐ *(If checked, provide the location of where the waste was hauled in the Comments area.)*

Date of Waste Transfer: _____

Operator Name: _____ License No.: _____

Lease Name: _____ Sec. _____ Twp. _____ R. _____ ☐ East ☐ West

Docket No./API No.: _____ County: _____

Comments:

Minimal fluid in reserve pit when Collen #2-21 aborted secondary to twisting off collars in hole that proved irretrievable. Rig slid 50 feet north. Resrve pit lengthened 30-50 feet to accomodate new rig position. This enlargement further made fluid levels minimal to unavailable for pumping. Collen #3-21 immediately spud and reserve pit back in use. Now existing fluids are all associated with the Collen #3-21.

Submitted Electronically