KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION

Form CDP-5
May 2011
Form must be Typed

EXPLORATION & PRODUCTION WASTE TRANSFER

Operator Name: Timberline Oil & Gas Corporation
License Number: 9232

Operator Address: 4000 PENROSE PLACE RAPID CITY SD 57702 6837

Contact Person: Brant C. Grote
Phone Number: (605) 341 - 3400

Permit Number *(API No. if applicable)*: 15-151-21657-00-00
Lease Name: BECKER

Source of Waste:

- ☐ Emergency Pit
- ☐ Settling Pit
- ☑ Workover Pit
- ☐ Drilling Pit
- ☐ Burn Pit
- ☐ Haul-off Pit
- ☐ Steel Pit
- ☐ Spill / Escape
- ☐ Dike

Well Number: 4

Source Location (QQQQ): NW - SE - NW - NE

Sec. 33 Twp. 26 R. 13 ☐ East ☑ West

4589 Feet from ☐ North / ☑ South Line of Section

1948 Feet from ☑ East / ☐ West Line of Section

GPS Location: Lat: _____ (e.g. xx.xxxxx), Long: _____ (e.g. -xxx.xxxxx)

Datum: ☐ NAD27 ☐ NAD83 ☐ WGS84

County: Pratt

No Waste to be Hauled: ☑ *(If checked, provide an explanation as to why no waste was hauled in the Comments area.)*

Type of waste to be disposed: ☐ Fluid ☐ Soil ☐ Mud / Cuttings ☐ Other: _____

Amount of waste: _____ No. of loads _____ Barrels _____ Tons _____ YDS

Destination of waste: ☐ Reserve Pit ☐ Haul Off Pit ☐ Disposal Well ☐ Lease Road ☐ Dike / Berm ☐ Other: _____

If waste is transferred to another reserve pit, is the lease active? ☐ Yes ☐ No

Location of Waste Disposal:

Destination Out of State: ☐ *(If checked, provide the location of where the waste was hauled in the Comments area.)*

Date of Waste Transfer: _____

Operator Name: _____ License No.: _____

Lease Name: _____ Sec. _____ Twp. _____ R. _____ ☐ East ☐ West

Docket No./API No.: _____ County: _____

Comments:

No fluids to be removed.

Submitted Electronically