KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION

Form CDP-5
May 2011
Form must be Typed

EXPLORATION & PRODUCTION WASTE TRANSFER

Operator Name: Sneath, Gene dba Lucky Iron
License Number: 30911
Operator Address: 2060 17 RD PLAINVILLE KS 67663 9022
Contact Person: Gene Sneath
Phone Number: (785) 737 - 6179
Permit Number *(API No. if applicable)*: 15-163-22354-00-00
Lease Name: BENOIT
Well Number: 4

Source of Waste:

- [ ] Emergency Pit
- [ ] Settling Pit
- [x] Workover Pit
- [ ] Drilling Pit
- [ ] Burn Pit
- [ ] Haul-off Pit
- [ ] Steel Pit
- [ ] Spill / Escape
- [ ] Dike

Source Location (QQQQ): _____ - NE - SW - NE
Sec. 5 Twp. 7 R. 20 [ ] East [x] West
1650 Feet from [x] North / [ ] South Line of Section
1650 Feet from [x] East / [ ] West Line of Section
GPS Location: Lat: _____ *(e.g. xx.xxxxx)*, Long: _____ *(e.g. -xxx.xxxxx)*
Datum: [ ] NAD27 [ ] NAD83 [ ] WGS84
County: Rooks

No Waste to be Hauled: [ ] *(If checked, provide an explanation as to why no waste was hauled in the Comments area.)*

Type of waste to be disposed: [x] Fluid [ ] Soil [ ] Mud / Cuttings [ ] Other: _____

Amount of waste: 1 No. of loads 60 Barrels _____ Tons _____ YDS

Destination of waste: [ ] Reserve Pit [ ] Haul Off Pit [ ] Disposal Well [x] Lease Road [ ] Dike / Berm [ ] Other: _____

If waste is transferred to another reserve pit, is the lease active? [ ] Yes [ ] No

Location of Waste Disposal:

Destination Out of State: [ ] *(If checked, provide the location of where the waste was hauled in the Comments area.)*

Date of Waste Transfer: 03/03/2023

Operator Name: Sneath, Gene dba Lucky Iron
License No.: 30911
Lease Name: _____
Sec. 5 Twp. 7 R. 20 [ ] East [x] West
Docket No./API No.: _____
County: Rooks

Comments:

Submitted Electronically