KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION

Form CDP-5
May 2011
Form must be Typed

EXPLORATION & PRODUCTION WASTE TRANSFER

Operator Name: Pickrell Drilling Company Inc
License Number: 5123
Operator Address: 929 W DOUGLAS AVE WICHITA KS 67213 4705
Contact Person: Cord Denton
Phone Number: (316) 262 - 8427
Permit Number *(API No. if applicable)*: 15-093-21838-00-00
Lease Name: KLEEMAN
Well Number: 4-36

Source of Waste:

- ☐ Emergency Pit
- ☐ Settling Pit
- ☑ Workover Pit
- ☐ Drilling Pit
- ☐ Burn Pit
- ☐ Haul-off Pit
- ☐ Steel Pit
- ☐ Spill / Escape
- ☐ Dike

Source Location (QQQQ): NE - NW - NE - SW
Sec. 36 Twp. 22 R. 36 ☐ East ☑ West
2419 Feet from ☐ North / ☑ South Line of Section
1763 Feet from ☐ East / ☑ West Line of Section
GPS Location: Lat: _____ *(e.g. xx.xxxxx)*, Long: _____ *(e.g. -xxx.xxxxx)*
Datum: ☐ NAD27 ☐ NAD83 ☐ WGS84
County: Kearny

No Waste to be Hauled: ☑ *(If checked, provide an explanation as to why no waste was hauled in the Comments area.)*

Type of waste to be disposed: ☐ Fluid ☐ Soil ☐ Mud / Cuttings ☐ Other: _____

Amount of waste: _____ No. of loads _____ Barrels _____ Tons _____ YDS

Destination of waste: ☐ Reserve Pit ☐ Haul Off Pit ☐ Disposal Well ☐ Lease Road ☐ Dike / Berm ☐ Other: _____

If waste is transferred to another reserve pit, is the lease active? ☐ Yes ☐ No

Location of Waste Disposal:

Destination Out of State: ☐ *(If checked, provide the location of where the waste was hauled in the Comments area.)*

Date of Waste Transfer: _____

Operator Name: _____ License No.: _____

Lease Name: _____ Sec. _____ Twp. _____ R. _____ ☐ East ☐ West

Docket No./API No.: _____ County: _____

Comments:

No free fluid after plugging operation.

Submitted Electronically