KOLAR Document ID: 1856700

KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION

Form U-7
August 2019

CASING MECHANICAL INTEGRITY TEST

Disposal: ☐ Enhanced Recovery: ☑ KCC District No.: 3

Operator License No.: 33215 Name: Taylor, Robert W. dba Taylor Oil Co.

Address 1: PO BOX 894

Address 2:

City: EL DORADO State: KS Zip: 67042 + 0894

Contact Person: Robert Taylor Phone: (316) 322-0466

API No.: 15-073-23233-00-01 Permit No.: E25344.1

_ - NW - SW - NE Sec. 17 Twp. 28 S. R. 11 ☑ East ☐ West

3445 Feet from ☐ North / ☑ South Line of Section

2113 Feet from ☑ East / ☐ West Line of Section

Lease: ADAMS Well No.: 13

County: Greenwood

Well Construction Details: ☐ New well ☐ Existing well with changes to construction ☑ Existing well with no changes to construcion

Maximum Authorized Injection Pressure: 300 psi Maximum Injection Rate: 300 bbl/d

	Conductor	*Surface*	*Intermediate*	*Production*	*Liner*	*Tubing*
Size:	N/A	7	N/A	4.5	NA	2.375
Set at:		43		1195		1110
Sacks of Cement:		12		155		Type: Duraline
Cement Top:		0		0		
Cement Bottom:		43		1195		

Packer Type: AD-1 Set at: 1110

☐ DV Tool ☐ Port Collar Depth of: ___ feet with ___ sacks of cement TD (and plug back): 1250 (1195) feet depth

Zone of Injection Formation: LANSING-KANSAS CITY Top Feet: 1117 Bottom Feet: 1122 Perf. or Open Hole: Perf

Is there a Chemical Sealant or a Mechanical Casing patch in the annular space? ☐ Yes ☑ No

If Dual Completion - Injection is: ☐ Above Production ☐ Below Production

FIELD DATA

GPS Location: Datum: ☐ NAD27 ☑ NAD83 ☐ WGS84 Lat: 37.61559 Long: -96.22321 Date Acquired: 08/17/2020

MIT Type: Tubing and Packer (or Initial Pressure) Test MIT Reason: 90-DAY RETEST - FAILURE

Time in Minute(s):	10	20	30			
Pressures: Set up 1	300	300	300			
Set up 2						
Set up 3						

Tested: ☐ Casing ☑ or Casing - Tubing Annulus System Pressure during test: ___ Bbls. to load annulus: ___

Test Date: 08/19/2025 Using: Taylor Oil Company's Equipment

The zone tested for this well is between 0 feet and 1110 feet.

The test results were verified by operator's representative:

Name: Robert Taylor Title: Owner Phone: (316) 322-0466

KCC Office Use Only

The results were:

☑ Satisfactory

☐ Not Satisfactory

Next MIT: 08/18/2030

State Agent: Thad Triboulet Title: E.C.R.S. Witness: ☑ Yes ☐ No

Remarks:

Annulus full of fluid.
ACO-1 located (Eastern Kansas). All information came from ACO-1 and does not match permit (Pg.1). Correction needed. KCC corrected the permit and mailed a copy to the operator.