

Notice: Fill out COMPLETELY
and return to Conservation Division at
the address below within
60 days from plugging date.

KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION

WELL PLUGGING RECORD

K.A.R. 82-3-117

Form CP-4

March 2009

Type or Print on this Form

Form must be Signed

All blanks must be Filled

OPERATOR: License #: 34357
Name: Atlas Operating LLC
Address 1: 1900 ST JAMES PLACE SUITE 800
Address 2: _____
City: HOUSTON State: TX Zip: 77056 + 4133
Contact Person: Zafar Ullah
Phone: (281) 893-9400
Type of Well: (Check one) ☒ Oil Well ☐ Gas Well ☐ OG ☐ D&A ☐ Cathodic
☐ Water Supply Well ☐ Other: _____ ☐ SWD Permit #: _____
☐ ENHR Permit #: _____ ☐ Gas Storage Permit #: _____
Is ACO-1 filed? ☒ Yes ☐ No If not, is well log attached? ☐ Yes ☐ No
Producing Formation(s): List All (If needed attach another sheet)
Mississippi Depth to Top: 4346 Bottom: 4356 T.D. 4500
_____ Depth to Top: _____ Bottom: _____ T.D. _____
_____ Depth to Top: _____ Bottom: _____ T.D. _____

API No. 15 - 15-095-00900-00-00
Spot Description: _____
_____SW NW SW Sec. 26 Twp. 30 S. R. 8 ☐ East ☒ West
1650 Feet from ☐ North / ☒ South Line of Section
4950 Feet from ☒ East / ☐ West Line of Section
Footages Calculated from Nearest Outside Section Corner:
☐ NE ☐ NW ☒ SE ☐ SW
County: Kingman
Lease Name: BOYLE C (WSU 30 1) Well #: 3
Date Well Completed: _____
The plugging proposal was approved on: 04/15/2026 (Date)
by: _____ (KCC District Agent's Name)
Plugging Commenced: 07/09/2026
Plugging Completed: 07/14/2026

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water Records		Casing Record (Surface, Conductor & Production)			
Formation	Content	Casing	Size	Setting Depth	Pulled Out
mississippi	oil,gas	Surface	8.625	310	
		Production	5.5	4499	

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set.

07/09/26 Move in rig up Quality well service unit. Pull out of hole with rods .Pulling out with tubing.
07/10/26 Finish pulling out tubing. Set cjb @ 4290. dump bail 2 sks cmt on top of plug.. Dig cellar and pit.
07/13/26 Perforate at 1300'. Go in with tbq to 1300'. Pump 50 sks cmt at 1300. woc.did not tag. Perforate at 850 and 360'.
Go in with tbq to 1300. Pump 50 sks cmt at 1300'..
07/14/26 Tag cmt at 840'. Pump 35 sks cmt at 800'..Pull tbq to 360' and pump 145 sks cmt to surface.Empty pit. Top off with 25 sks cmt.
Backfill cellar and pit. Move off Quality.

Plugging Contractor License #: 31925 Name: Quality Well Service, Inc.
Address 1: PO BOX 468 Address 2: _____
City: PRATT State: KS Zip: 67124 + 0468
Phone: (620) 727-6964
Name of Party Responsible for Plugging Fees: Atlas Operating LLC
State of Texas County, Harris, ss.

(Print Name)

☐ Employee of Operator or ☐ Operator on above-described well,

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

Submitted Electronically