

Form 51-5M-3-35-Mid-West

NORTH

WEST

EAST

SOUTH

Rig Up

Drilling Remarks

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ cu. ft. _____

Dry Hole _____

Abandoned _____

Well No. 1-10 March Farm 10

NORTH

Ft. from W. Line

WEST

EAST

SOUTH

REPORT

Date / /

3/11	SD 200
------	--------

3/13 --

3/20 10"-180 Drlg. 840

3/27 Drlg. 2460'

4/2 T. Do1o. 2905' 7"- 2902' WOC.

4/10 RUST.

4/16 Drlg. 2950'

4/23 Simpson 2926' T.D. 3051'-1200' oil.

4/30--

5/7 1000 acid.

5/14--1 bbl oil per hour.

5/21	No test.
------	----------

5/28--

6/4 Shot 20 qts.

6/11	No test.
------	----------

7/1/36-Simpson 2926'.

T.D. 3051.

1000 gallons. acid.

Shot 20 qts. Show 40 qts.

3000 gallons of acid.

Pump 20 bbls of oil.

COMPLETED

Map No. 1 Sec. 11 Twp. 32 R. 2 EWell No. 1- WartickHelmerick + Payne Company

Contractor

FIRST REPORTS

SECTION PLAT

Ft. from N. Line

75 Ft. from S. Line1875 Ft. from E. Line

Ft. from W. Line

Location

Rig up

Drilling and Remarks:

Ad 200'

RECORD

Cased in., ft.

Sand

Gas

Oil

Total Depth

PRODUCTION

1st 24 hrs. Nat.

1st 24 hrs. after shot

Gas Cu. Ft.

Dry Hole

Abandoned

Date

ORVAL MANNSCHRECK

3-11-36 192

Scout

Map No. 1 Sec. 11 Twp. 32 R. 25Well No. 1 CharlieHelmreich & Payne Company

Contractor

SECTION PLAT

		0	

Ft. from N. Line

75 Ft. from S. Line1875 Ft. from E. Line

Ft. from W. Line

COMPLETED

Location _____

Rig up _____

Drilling and Remarks:

Simpson 2926.1000 acidBar 20 gts" 40 "3000 acidPump 20 & 40.

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth 3051

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

JUL 1 1936

19

S. J. LEWIS

Scout