STAFFORD.
County
FRANK N. SCHARTZ No. 2.
Farm
STANOLIND OIL & GAS CO.
Company
Sec. 6 5 4 3 2 1 / 7 8 9 10 11 12 / 18 17 16 15 14 X / 19 20 21 22 23 24 / 30 29 28 27 26 25 / 31 32 33 34 35 36
Twp.
SW.c NE
Elev. ---- T.D 3701' P.B. 3699'
Date Drilled 6-7-38.
Correlation by ----------
PROD. POT. 607 B/D 3% wtr.
Section 13
Township 22 S
Range 13 W

CLAY

GRAVEL + SHELLS

CORE #1. 3672 - 3676'
S.C. REC.
TAN to GREY LIME 40% SH. 3677
CORE #2. 1/3 REC.
LIME SPT BROWN to GREY SLIGHT POR. FAIR SAT. 3678-3680'
CORE #3. 0/3 REC. 3681'
FAIR SATS OF GREEN SHALE
CORE #4. 0/3' REC. 3686'
WHITE POOR SAT. LIME
CORE #5 0/2' REC. 3687'
GREY LIME NO POR.
CORE #6. 1 1/2 REC. 3688-91'
WHITE HRD LIME NO POR.
CORE #7. 1 1/2 REC.
GREY LIME NO POR.
CORE #8. 2/2' REC. 3693-95'
LIME GOOD SAT. IN LAST FOOT.
CORE #9. 0/2 REC. 3695-97'
CORE #10. 3 1/4' REC. 3697-3701'
LIME SLIGHT SAT.
T.D. 3701' P.B. 3699'

CORE #2. 2 1/2/7' REC.
REC. 2 1/2. DOLO. TAN FINE CRYST. W/THIN GREEN SHALE BRKS. PYRITE & CHERTY STKS. FAIR POR & SAT. 3672'

TOP SILICEOUS 3687'
CABLE TOOLS.
S.C. CORE #1. 2/2/7' REC.
TAN to GREY LIME 40% SH. 3677
CORE #2. 1/3 REC.
LIME SPT BROWN to GREY SLIGHT POR. FAIR SAT. 3678-3680'
CORE #3. 0/3 REC.
DOLO. WSTRKS OF GREEN SHALE
FAIR SAT. 3681'
CORE #4. 0/3' REC. 3686'
WHITE POOR SAT. LIME
CORE #5 0/2' REC. 3687'
GREY LIME NO POR.
CORE #6. 1 1/2 REC. 3688-91'
WHITE HRD LIME NO POR.
CORE #7. 1 1/2 REC.
GREY LIME NO POR.
CORE #8. 2/2' REC. 3693-95'
LIME GOOD SAT. IN LAST FOOT.
CORE #9. 0/2 REC. 3695-97'
CORE #10. 3 1/4' REC. 3697-3701'
LIME SLIGHT SAT.
T.D. 3701' P.B. 3699'

TOP LANSING 3355'

CORE #1. 8/13' REC.
LIME STONE TAN OOLITIC. GOOD POR. GOOD SPOTTED SAT. SH OIL & GAS. 3480'
LIME W/THIN SHALE PARTINGS.

CORE #2. 2 1/2/7' REC.
REC. 2 1/2. DOLO. TAN FINE CRYST. W/THIN GREEN SHALE BRKS. PYRITE & CHERTY STKS. FAIR POR & SAT. 3672'

TOP SILICEOUS 3687'
CABLE TOOLS.

CONGL.
CHERT.

SHALE SALT & SHELLS

ANHYD.

SHALE RED & GREY

ANHYD.

& PYRITE

SDY SHALE & LIME

SDY LIME & SHALE

& PYRITE

Y & SHELLS.